



Manufacturing Analytics

Production Performance Dashboard

Monitor production, delivery and quality performance across your manufacturing operations



Overview
Executive KPIs



Product
Product Analysis



Delivery
Delivery Performance



Quality
Quality Metrics



Work Order
Production Orders



Risk & Prediction



Year Slicer

- ☐ 2022
- ☐ 2023
- ☐ 2024

Total Produced

4M

On-Time %

68.6%

Late Orders

23K

Scrap Rate

0.2%


Work Orders

73K

Production Attainment

99.8%


Delivery Performance



Top 20 Products by Delivery Performance

ProductName	Late	On-time	Orders	Late %
Touring-3000 Yellow, 62	29	28	57	50.9%
Touring-3000 Yellow, 58	30	20	50	60.0%
Touring-3000 Yellow, 54	38	18	56	67.9%
Touring-3000 Yellow, 50	35	28	63	55.6%
Touring-3000 Yellow, 44	35	27	62	56.5%
Touring-3000 Blue, 62	45	22	67	67.2%
Touring-3000 Blue, 58	39	26	65	60.0%
Touring-3000 Blue, 54	35	28	63	55.6%
Touring-3000 Blue, 50	36	17	53	67.9%
Touring-3000 Blue, 44	38	22	60	63.3%
Total	455	312	767	59.3%

Highest Scrap Rate Products





Product Slicer

All

Work Orders

73K

On-Time %

68.6%

Scrap Rate





0.2%

Avg Delay

8.44


Late Orders

23K







Weekly Same-Week Delivery Rate



Late Rate by Station




Station Health Map



Station Performance

LocationName	Operations	Resource Hours	Late %	Start Delay	Duration Variance
Paint	816	1,632.00	0.63	3.89	1.64
Debur and Polish	1490	1,490.00	0.63	3.87	1.69
Specialized Paint	674	1,348.00	0.62	3.84	1.76
Final Assembly	18554	74,216.00	0.60	4.17	1.46
Frame Welding	5923	20,730.50	0.59	4.21	1.44
Frame Forming	9567	39,224.70	0.58	4.28	1.37
Subassembly	30107	90,321.00	0.57	4.36	1.31



Total Ordered

4.5M

Total Scrapped

10.7K

Scrap %

0.2%

Scrapped W/O

729

Above Threshold

478

Threshold %


65.6%

Top 10 Scrap

28.5%


Scrap Growth YoY

85.3%




Largest Scrap Events


Product Name	Order Qty	Scrapped Qty	Scrap %	Scrap Reason
BB Ball Bearing	22440	673	3.0%	Trim length too long
Seat Stays	11632	314	2.7%	Wheel misaligned
Seat Stays	11012	297	2.7%	Gouge in metal
Seat Stays	10172	274	2.7%	Primer process failed
Fork End	9014	270	3.0%	Thermoform temperature too low
Fork End	8984	269	3.0%	Paint process failed
Fork End	8696	260	3.0%	Paint process failed
Chain Stays	12062	241	2.0%	Drill pattern incorrect
Fork End	7996	239	3.0%	Trim length too short
Blade	5816	203	3.5%	Brake assembly not as ordered
Chain Stays	10110	202	2.0%	Drill size too small
Blade	5644	197	3.5%	Drill pattern incorrect
Seat Stays	6708	181	2.7%	Primer process failed
Total			2.8%	




Top Ordered Products



Production Share by Product Group



Work Orders by Product Group



Monthly Production Difference





ModelAUC

0.81

Recall (Late)

86.60%

Precision (Late)

53.40%


High Risk Orders

8K

Avg Risk Score

34.6%

Actual vs Predicted Late % by Risk Band



High Risk Work Orders

Product Name	W/O ID	Late Risk Score	Sum of IsLate	RiskBand
HL Mountain Seat Assembly	39	0.98	1	High
HL Mountain Seat Assembly	2545	0.98	1	High
HL Mountain Seat Assembly	9092	0.98	1	High
HL Mountain Seat Assembly	10278	0.98	1	High
HL Mountain Seat Assembly	11676	0.98	1	High
HL Mountain Seat Assembly	14536	0.98	1	High
HL Road Front Wheel	9135	0.98	1	High
HL Road Seat Assembly	9095	0.98	1	High
HL Mountain Seat Assembly	7713	0.98	1	High
HL Mountain Seat Assembly	3703	0.98	1	High
HL Mountain Front Wheel	73	0.98	1	High
HL Mountain Rear Wheel	77	0.98	1	High
Front Derailleur	82	0.98	1	High
HL Bottom Bracket	87	0.98	1	High
HL Fork	103	0.98	1	High
HL Headset	68	0.98	1	High
HL Mountain Handlebars	69	0.98	1	High
LL Bottom Bracket	85	0.98	1	High
LL Fork	101	0.98	1	High
LL Road Front Wheel	74	0.98	1	High
Total		116.76	119	

Adjustable Race

Late Orders	On-time Orders	Total Produced
22790	49801	4497070

