

Maintenance Report - Hydraulic System

1. Aircraft Information

Aircraft type: A320. Flight hours: 12500. Registration: F-TEST.

2. Reported Issue

Crew reported abnormal noise from hydraulic system during descent.

3. Inspection Findings

Hydraulic pump showed signs of wear and minor leakage. No structural damage detected.

4. Corrective Action

Hydraulic pump replaced. System tested successfully. No further anomalies detected.

5. Recommendations

Monitor hydraulic pressure trends. Schedule preventive replacement after 2000 hours.