

HSS Inspection Report


Date : 25 Sep 2025
Page : 1 of 9

Report Number: SIS2524903 Inspection Date/Time: 25 Sep 2025 09:00
Workplace: PPT1,PPT2,PPT3
Inspectors: CHNG MING HAO, SR OPS EXEC, YOD, PSA
LEE SIAK QUEE, AVP (YARD OPS), YOD, PSA
LARRY WONG HENG KEONG, ASST MGR, YOD, PSA
JOULBERT CHNG, ASST MGR, YOD, PSA
25 Sep 2025 11:00

BUILDING AND OFFICE - PPTB1 LVL 1 (Control Centre) - BRIEFING

Inspected on: 25 Sep 2025 09:30

Description / Immediate Action	Follow Up / Remarks
<p>A safety inspection was conducted on the control center AES(RCOC/ARCOC) staff at PPTB1 lvl 1.</p> <p>The objective of this safety inspection is to ensure that AES(RCOC/ARCOC) comply to all AES safety rules and measures implemented. It was also aimed to observe the behavior of individual AES(RCOC/ARCOC).</p> <p>Team engaged with the AES(RCOC/ARCOC)s and briefed them on the following:</p> <ul style="list-style-type: none"> 1) Always check for job information from the data pc when a job is link-up to console. 2) Always check on prime mover number and its chassis position using camera provided before trigger spreader or container to "Move to lane". 3) Always focus on the screen when handling a job and not to be distracted by any other activities. 4) Do not use any handheld devices or engage in other activities while handling a job. 	<p>SOP complied.</p>



Caption : SAFETY INSPECTION DONE ON ABCOC

Caption : SAFETY INSPECTION DONE ON RCOC

HSS Inspection Report

BUILDING AND OFFICE - PPTB1 ANNEX BUILDING (CARPARK) - GENERAL

Inspected on: 25 Sep 2025 09:30

CheckList

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection along PPTB1 (Near Carpark).	
Team observed displayed banner were faded and worn.	CNHRSA to follow up.
Team had informed CNHRSA to follow up with it.	



Caption : FADED BANNERS



Caption : FADED BANNERS

Follow Up

Person	Action Required
LAURA CHEW	Faded banner along PPT1 ANNEX BUILDING (Carpark)


OTHERS - PPTB1 LVL 1 - FIRE SAFETY

Inspected on: 25 Sep 2025 09:30


CheckList

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection along PPTB1 (Near Carpark). Team performed a safety check on ERT response. ERT team had responded it quickly and was also notified of the drill. Team also did a check with the fire extinguisher serviceability and was up to date.	NIL

HSS Inspection Report



Caption : FIRE EXTINGUISHER UP TO DATE



Caption : ERT HOTLINE

HSS Inspection Report



Caption : SAFETY CHECK ON ERT RESPONSE

YARD - JUNCTION NEAR U67 AND T06 - PAINTING

Inspected on: 25 Sep 2025 09:50

CheckList

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection along PPT3 (U26) and PPT2 (T06) junctions.	
Team observed the road markings were smeared with oil stains and black marks.	TID to follow up
This will affect the CES visibility while performing cross gantry of RTG along the location stated.	
Team had informed TID to follow up with it.	

HSS Inspection Report



Caption : SMEARED MARKING ALONG T06 JUNCTION

Caption : SMEARED MARKING ALONG U26 JUNCTION

Follow Up


Person	Action Required
MOHAMED SHIRAZ S/O MOHAMED RAFI	Smeared markings along U26 and T06

YARD - JUNCTION BETWEEN L08 AND M08 - QUALITY INSPECTION

Inspected on: 25 Sep 2025 10:10

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection along PPT2 LM street. Team observed the signages for (No Entry) were either missing or not in placed. Team also observed faded signages were seen along the busbar of the EA-RTG blocks. Team had informed TID to follow up with it.	TID to follow up.


HSS Inspection Report



Caption : Signages along LM street standardization



Caption : Replacement for signages



Caption : Missing Signages along LM street (L Block bigger)

Follow Up

Person	Action Required
MOHAMED SHIRAZ S/O MOHAMED RAFI	Missing signages and faded signages along LM street.

HSS Inspection Report

YARD - Q12 Slot 54 - GENERAL

Inspected on: 25 Sep 2025 10:30

CheckList

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection at Q12 hyster block.	
Team observed a tire was misplaced at Q12 slot 54.	SRDO to follow up
Team informed SRDO to clear it as it could be seen as a hazard.	



Caption : TIRE LYING ALONG Q12

YARD - Q12 - HYSTER OPS

Inspected on: 25 Sep 2025 10:30

CheckList

<input checked="" type="checkbox"/>	SWP COMPLIANCE
-------------------------------------	----------------

HSS Inspection Report

Description / Immediate Action	Follow Up / Remarks
<p>Team conducted On-Site inspection at hyster block Q12.</p> <p>-Team observed FM034 operator adhered to SOP while in standby position with 20ft spreader close and hoist up to 3 high.</p> <p>-Team also engaged the FMO to share on the recent accident case as well as raise awareness with the safety timeout.</p> <p>-Team commended the FM034 operator for complying to SOPs and to continue practicing good safety habits at all times.</p> <p>-Team also reminded the FM034 operator to report any hazard immediately to his superiors and /or control centre.</p>	SOP complied



Caption : FM034 STANDBY SWP



Caption : FM034 FMO ENGAGEMENT

BERTH / WHARF - QC528 AND QC529 - SWP COMPLIANCE - PROPER LABELLING AND IMCO COMPLIANCE

Inspected on: 25 Sep 2025 10:30

HSS Inspection Report

Description / Immediate Action	Follow Up / Remarks
Team conducted On-Site inspection at hyster block Q12.	
Team observed that QC 528 and QC528 safety signages were faded and poor visibility.	P123QC to follow up.
Team informed P123QC to follow up.	



Caption : QC528 FADED SIGNAGES



Caption : QC529 FADED SIGNAGES

Follow Up

Person	Action Required
CHEONG KOK MENG	To replace faded signages for QC528 and QC529.