# **HSS Inspection Report**

Date : 20 Sep 2025

Page: 1 of 3

Report Number: SIS2524440 Inspection Date/Time: 20 Sep 2025 09:13

20 Sep 2025 16:08

Workplace: PPT1,PPT2,PPT3

Inspectors: CALVIN HO, SR OPS EXEC, YOD, PSA

AUSTIN CHUE, SR OPS EXEC, YOD, PSA

## YARD - PM/HAULIER/IGH OPS

Inspected on: 20 Sep 2025 09:14

#### CheckList

×	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
×	SWP COMPLIANCE - DRIVING INTO OPERATIONAL AREA WITHOUT PERMISSION

Description / Immediate Action	Follow Up / Remarks
XE7749S was observed to have encroach into the yard slot of the block (D13).	NISR issued.



Caption: XE7749S was observed to have encroach into the yard slot of the block.

Caption: XE7749S was observed to have encroach into the yard slot of the block.

### **Personnel**

Person	Company	NISR / SBR
SANDHU PARGAT SINGH	SPIRAL MARINE PTE LTD	NISR Ref No: S2025005279

## YARD - PM/HAULIER/IGH OPS

Inspected on: 20 Sep 2025 09:24

# CheckList

. /	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE
<b>V</b>	WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING

Description / Immediate Action	Follow Up / Remarks
• •	• •

# **HSS Inspection Report**

CCTV inspection was conducted at K11.
-It was observed that PPM036 driver adhered to waiting SOP. The driver stopped 1 x 40ft container length away from the mounting slot while waiting for the FM to complete its task.

-PPM036 driver was commended for complying to SOP and to continue practicing good safety habits at all times.

-PPM036 driver was reminded to report any hazard immediately to his superiors or control center.

SBR awarded.



Caption: PPM036 keeping the safe distance while in queue for the container to be mounted

#### **Personnel**

Person	Company	NISR / SBR
MOHAMAD HARITH BIN HASSANUDIN	CALL LADE ENTERPRISES PTE LTD	/ SBR Ref No: SBR2025092010077

# **YARD - HYSTER OPS**

Inspected on: 20 Sep 2025 14:36

#### CheckList

SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
CCTV Inspection was conducted at X09PFM023 operator was observed to have adhered with the SOP when reversing within the slot. The operator stopped before the white line before proceeding farther onto the bypass lanePFM023 operator was commended for complying to SOPs and to continue practicing good safety habits at all timesPFM023 operator was reminded to report any hazard immediately to his superiors or control center.	SBR awarded.

# **HSS Inspection Report**



Caption : PFM023 came to a complete stop while reversing, checked for traffic

#### Personnel

Person	Company	NISR / SBR
ABDUL RAHIM BIN MOHAMAD JAINI	S M S MARINE PTE LTD	/ SBR Ref No: SBR2025092010078

#### **YARD - HYSTER OPS**

Inspected on: 20 Sep 2025 16:07

#### CheckList

SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
CCTV Inspection was conducted at U31PFM061 operator was observed to have adhered to SOP when gantry to smaller slot for PM offloading. It had its spreader retracted to 20ft and hoisted to 3 highPFM061 operator was commended for complying to SOP and to continue practicing good safety habits at all timesPFM061 operator was reminded to report any hazard immediately to his superiors or control center.	SBR awarded.



Caption : PFM061 on gantry complying with the safety SOP aspects.  $\label{eq:complex} % \begin{subarray}{ll} \end{subarray} % \begin{subarray}{l$ 

# Personnel

Person	Company	NISR / SBR
EDWIN ALFIAN BIN ABDUL YAZID	GKE SERVICES PTE LTD	/ SBR Ref No: SBR2025092010079