Date : 14 Sep 2025 Page : 1 of 5

Report Number: Inspection Date/Time: 13 Sep 2025 23:38 SIS2523781

14 Sep 2025 06:21

Workplace: PPT2,PPT3

AUSTIN CHUE, SR OPS EXEC, YOD, PSA Inspectors:

MUHAMMAD JAMALULLAIL BIN MAHADI, SR OPS EXEC, YOD, PSA


## **YARD - HYSTER OPS**

Inspected on: 13 Sep 2025 23:38

#### CheckList

SWP COMPLIANCE
I SWE COMELIANCE

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at hyster block T09.	
Team observed FM023 operator adhered to SOP when gantrying to another block with 20ft spreader close.	
Team observed FM023 operator also come to a complete stop at unbroken white line before crossing.	SOP complied / SBR awarded.
Team commended the FM023 operator for complying to SOPs and to continue practicing good safety habits at all times.	
Team also reminded the FM023 operator to report any hazard immediately to his superiors and /or control centre.	



Caption: FM 023 gantry ops

## Personnel

Person	Company	NISR / SBR
SUDIRMAN BIN MHD YUSOFF	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509149860


# YARD - HYSTER OPS

Inspected on: 13 Sep 2025 23:42

# CheckList

✓ SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at hyster block S10.	
Team observed that FM051 operator was on stationary position with spreader closed to 20-footer and hoist to 3 high.	
Team commended FM051 operator for complying to SOP and to continue practicing good safety habits at all times.	SOP complied / SBR awarded.
Team also reminded the FM051 operator to report any hazard immediately to his superiors and /or control centre.	



Caption: FM 051 on standby

# Personnel

Person	Company	NISR / SBR
SEI WEI GUANG		/ SBR Ref No: SBR202509149861


# YARD - HYSTER OPS

Inspected on: 13 Sep 2025 23:57

# CheckList

✓ SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at hyster block U31.	
Team observed FM061 operator adhered to SOP by following 3-step mounting rule for all mounting PMs.	
Team commended the FM061 operator for complying to SOPs and to continue practicing good safety habits at all times.	SOP complied / SBR awarded.
Team also reminded the FM061 operator to report any hazard immediately to his superiors and /or control centre.	



Caption: FM 061 mounting ops

#### **Personnel**

Person	Company	NISR / SBR
TOH JING LIANG		/ SBR Ref No: SBR202509149862


# YARD - PM/HAULIER/IGH OPS

Inspected on: 14 Sep 2025 00:03

## CheckList

SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at Hyster blk K10.	
Team observed PPM598 was doing mounting job at K10.	
Team observed PPM598 was parking 40ft slot away from front PM chassis while waiting for his turn for mounting.	SOP complied / SBR awarded.
Team commended the PM598 driver for complying to SOPs and to continue practicing them.	
Team also encouraged the PM598 driver to report any hazard immediately to his superiors and /or control centre.	



Caption: PPM 598 40ft safety distance from front PM

## Personnel

Person	Company	NISR / SBR
RAJENDRAN ANANDARAJ	CALL LADE ENTERPRISES PTE LTD	/ SBR Ref No: SBR202509149863

# YARD - PM/HAULIER/IGH OPS


Inspected on: 14 Sep 2025 05:39

## CheckList

×

SWP COMPLIANCE - STOP AT STOP LINE

Description / Immediate Action	Follow Up / Remarks
It was observed that XD 4424D failed to stop at stop line before exiting RTG block T02 after offloading.	SOP not complied / NISR issued separately.



Caption: XD 4424D

## Personnel

Person	Company	NISR / SBR
LI YUE	UBTS PTE LTD	NISR Ref No: S2025005144