Date: 18 Sep 2025 Page: 1 of 4

Report Number: SIS2524203 Inspection Date/Time: 18 Sep 2025 00:36

18 Sep 2025 05:00

Workplace: PPT3,PPT2,PPT1

Inspectors: MUHAMMAD JAMALULLAIL BIN MAHADI, SR OPS EXEC, YOD, PSA

AUSTIN CHUE, SR OPS EXEC, YOD, PSA


### **YARD - S10 - HYSTER OPS**

Inspected on: 18 Sep 2025 00:36

#### CheckList

✓ FM gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at FM yard S10 to check on FM compliance to SWP.	
- At FM yard S10, team observed FM031 operator adhered to SOP when gantrying from smaller to bigger slot with 20 footer spreader close and raised to 3 high.	SWP Complied/SBR issued.
-Team commended FM031 operator for complying to SWP and also reminded the FM operators to report any hazard immediately to his superiors and/or control centre.	



Caption: FM 031 gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

### Personnel

Person	Company	NISR / SBR
SUDIRMAN BIN MHD YUSOFF	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509189998

### **YARD - X31 - HYSTER OPS**

Inspected on: 18 Sep 2025 01:40

CheckList

**\** 

FM Stopped before the white line and checked traffic clearance before reversing out from the yard slot

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at FM yard X31 to check on FM compliance to SWP.	
- At FM yard X31, FM012 was observed to have came to a complete stop before the white line and check for traffic before further moving out from the yard slot.	SWP Complied/SBR issued.
-Team commended FM 012 for complying to SWP and also reminded the FM operators to report any hazard immediately to his superiors and/or control centre.	



Caption: FM 012 stopped white line before reversing

### Personnel

Person	Company	NISR / SBR
MOHAMED HAFIZULHAKIM BIN DOLMAT		/ SBR Ref No: SBR202509189999

# YARD - K11 & X31 - PM/HAULIER/IGH OPS

Inspected on: 18 Sep 2025 02:45

### CheckList

<b>✓</b>	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
<b>✓</b>	SWP COMPLIANCE - OBEY TRAFFIC RULES (STOPPED BEFORE WHITE STOP LINE BEFORE PROCEEDING TO NEXT LOCATION)

Description / Immediate Action	Follow Up / Remarks
· ·	• •

Team did a CCTV inspection at FM yard blocks to check on PPMs compliance to SWP.

- -Firstly, It was observed that PPM 777 stopped before the STOPLINE at the end of K10/K11 before proceeding to his next location.
- Next, It was observed that PPM 551 was observed to be maintaining 2X20 footer safety distance from the front PM while awaiting his turn to mount at FM yard X31.
- -Both PPM driver 777 & 551 was commended for complying to SOPs and for continuing to always practice safe driving habits.
- -Both PPM driver 777 & 551 was reminded to report any hazards immediately to control center.

SWP Complied/ SBR issued.



Caption: PM 777 stopped at the STOP LINE at the end of K10/K11, checked for clear traffic before moving off.

Caption: PPM 551 MAINTAIN 1X 40FT SAFETY DISTANCE at X31

#### Personnel

Person	Company	NISR / SBR
MANOHARAN MUTHUKUMARAN		/ SBR Ref No: SBR2025091810000
HUANG DONGLIANG		/ SBR Ref No: SBR2025091810001


### YARD - Street in between L & M - YC GANTRY

Inspected on: 18 Sep 2025 03:30

### CheckList

✓ SWP COMPLIANCE - LINEAR AND CROSS GANTRY

Description / Immediate Action	Follow Up / Remarks
Team then conducted inspection at RTG yard blocks to ensure that RTG operators ensure traffic clearance and no obstruction at the gantry path before proceed out from the RTGs block.	SWP Complied/SBR issued.



Caption : RTG 628 ensure traffic clearance during gantry operation

### **Personnel**

Person	Company	NISR / SBR
S SELVARAJAN		/ SBR Ref No: SBR2025091810002

# YARD - A13 RMG BLOCK - GENERAL

Inspected on: 18 Sep 2025 04:10

# CheckList

X

PPE COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
At about 0413hrs, the haulier driver of XF 569K was observed	
coming down from his haulier cabin to lock the chassis twistlocks without wearing	SWP not complied. NISR S2025005229 issued.
proper PPE (high visibility vest).	



Caption: Haulier XF569K no high visibility vest