

HSS Inspection Report

Date : 03 Sep 2025
Page : 1 of 4

Report Number: SIS2522707 Inspection Date/Time: 03 Sep 2025 11:00
 03 Sep 2025 12:00
Workplace: PPT1,PPT2,PPT3
Inspectors: MERVIN HO, SR OPS EXEC, YOD, PSA
 AUSTIN CHUE, SR OPS EXEC, YOD, PSA

YARD - D/T - PM/HAULIER/IGH OPS

Inspected on: 03 Sep 2025 11:00

CheckList

| | |
|-------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING |
|-------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|

| Description / Immediate Action | Follow Up / Remarks |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| With increasing number of incidents where PM/IGH/Hauliers failed to comply with the SOP, the team observed drivers failed to keep safety from front PM. | NISR issued |



YARD - W/U - YC GANTRY

Inspected on: 03 Sep 2025 11:15

CheckList

| | |
|-------------------------------------|------------------------------------------|
| <input checked="" type="checkbox"/> | SWP COMPLIANCE - LINEAR AND CROSS GANTRY |
|-------------------------------------|------------------------------------------|

| Description / Immediate Action | Follow Up / Remarks |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| Team then conducted inspection at RTG yard blocks to ensure that RTG operators ensure traffic clearance and no obstruction at the gantry path before proceed out from the RTGs block. | SBR awarded |

HSS Inspection Report



Caption : RTG556 ensure traffic clearance during gantry operation



Caption : RTG245 ensure traffic clearance during gantry operation

Personnel

| Person | Company | NISR / SBR |
|----------------------|---------|-------------------------------|
| NUR ASHROY BIN HAMDI | | / SBR Ref No: SBR202509039440 |
| ROBIN TONG | | / SBR Ref No: SBR202509039441 |

YARD - T/U - HYSTER OPS

Inspected on: 03 Sep 2025 11:30

CheckList

| | |
|-------------------------------------|--------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | SWP - PERFORMED 3 STEP HOIST DURING MOUNTING/OFFLOADING OPERATION. |
|-------------------------------------|--------------------------------------------------------------------|

| Description / Immediate Action | Follow Up / Remarks |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| The team then observed FM065 and FM056 to be performing offloading/mounting operations at T09/U31. FMOs were observed to have performed 3 step hoisting of the spreader while offloading/mounting. After offloading/mounting the container from the PM chassis, FMOs were observed to have reversed to a safe distance before giving the instruction to 'PMGO'. They commended on their compliance to the SWP and reminded not to perform any self recovery on their FM and to inform control or the SR team should they encounter any issues. They acknowledged the reminders and assured the team that they will continue to do so. issues. They acknowledged the reminders and assured the team that they will continue to do so. | SBR awarded |

HSS Inspection Report



Caption : FM65 performing offloading operations at
U31

Caption : FM56 performing mounting operations at
T09

Personnel

| Person | Company | NISR / SBR |
|----------------|---------|-------------------------------|
| WONG KUAN HAW | | / SBR Ref No: SBR202509039442 |
| SAM YOONG SENG | | / SBR Ref No: SBR202509039443 |

YARD - J13 - HYSTER OPS

Inspected on: 03 Sep 2025 11:45

CheckList

| | |
|-------------------------------------|--------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | SWP - PERFORMED 3 STEP HOIST DURING MOUNTING/OFFLOADING OPERATION. |
|-------------------------------------|--------------------------------------------------------------------|

| Description / Immediate Action | Follow Up / Remarks |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| <p>Lastly, The team then turned their attention to J13 where RS operations was ongoing. The team observed that RSO803 had followed ensure that his surroundings were clear while performing the shuffling and complied with the 3 step hoisting procedure of the spreader while lifting the container. In addition, RSO803 retracted the boom all the way and lower the container to the ground in compliance with the SWP. RSO803 was also reminded to monitor his Linear Load Moment Indicator and stop work immediately if the indicator is in the yellow region. RSO803 acknowledged the reminders and ensured he will continue to work safe for both himself and safety of others.</p> | SBR awarded |

HSS Inspection Report



Caption : RS803 performing offloading at J13

Personnel

| Person | Company | NISR / SBR |
|----------------|---------|-------------------------------|
| CHEW KONG SANG | | / SBR Ref No: SBR202509039444 |
