

Arm® Cortex®-M55
32-bit Microcontroller

NuMicro® Family
M55M1 Series BSP
Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller and microprocessor based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.01.005 (Released 2026-07-24)

- Add SBOM.
- CMSIS upgrades to 6.3.0 and adds CMSIS-Compiler 2.2.0.
- Startup
 - Reset_Handler_Prelit fixes incorrect timeout check.
- Standard driver
 - FMC: FMC_WriteMultiple supports resume for timeout recovery.
 - I2S: I2S_ORDER_AT_LSB and I2S_ORDER_AT_MSB fix wrong definition.
 - LTPWM: LTPWM_ENABLE_OUTPUT fixes disable functionality.
- CMSIS driver
 - USB: Support HSUSB DMA transfer.
- Library
 - UsbHostLib supports UAC 2.0.
- ThirdParty
 - FatFs: Upgrade to R0.16.
- Sample code
 - All sample code projects add no-unaligned-access compiler flag.
 - DMIC_I2S_Play and DMIC_WAVRecorder: Add 10 ms DMIC turn-on time.
 - EPWM: EPWM_EnableFaultBrake removes support of multiple brake sources.
 - FMC_XOM, XOMLib, and XOMLibDemo: Refactor for dual bank.
 - HSUSB mass-storage sample codes: Use memory buffer to replace fixed address.
 - HSUSB_MassStorage_ScatterGather: Align buffer for Cache/DMA coherence.
 - HSUSB_RNDIS: Improve performance of bulk transfer with DMA.
 - HSUSBH_USBH_AudioClass, HSUSBH_USBH_UAC_HID, and HSUSBH_USBH_UAC_Loopback: Support UAC 2.0.
 - I2S_Codec_PDMA: Support 24-bit data width.
 - ISP_DFU: Remove dfu-util.
 - Jpeg_Display: Refine memory usage to display larger pictures.
 - LwIP_MQTT: Fix issues of semaphore double-take and local stack buffer.
 - SDH_FATFS: Improve SD card hot-plug response time.
- Tool
 - HIDTransferTest
 - Move from USB sample codes.
 - Add Control transfer.
 - mcuboot: Upgrade to v2.4.0 with imgtool.

Revision 3.01.004 (Released 2026-03-26)

- Peripheral register
 - fmc_reg.h: Define FMC_ISPSTS_INTFLAG_Pos based on secure state.
- Standard driver
 - EADC: EADC_Open removes EADC_Calibration call.
 - EPWM: EPWM_EnableFaultBrake supports multiple brake sources.
 - I3C: Update for new I3C sample codes.
 - PMC: PMC_SetPowerDownMode adds NPD3 power-down mode limitation.
 - QSPI: QSPI_GET_TX_FIFO_COUNT adds.
 - RNG: Remove SysTick dependency.
 - SPIM: Improve stability of quad I/O transfer mode and 4-byte address mode.
- CMSIS driver

- Flash: Support PDMA and non-blocking mode operations.
- Library
 - UsbHostLib
 - Support still image capture.
 - Reduce memory usage and fix device disconnect flow.
 - xmodem: Fix 128-byte unalignment send issue.
- Sample code
 - CANFD_CAN_TxRx, CANFD_CAN_TxRxINT, CANFD_CANFD_TxRx, CANFD_CANFD_TxRxINT: Add bus-off recovery handling.
 - CANFD_TxRxINT: Fix wrong bitmask in CANFD00_IRQHandler.
 - EADC samples: Fit max 90 MHz EADC clock frequency.
 - HSUSBH_USBH_UVC: Support video still image capture.
 - I3C_Controller: Replace samples of I3C_Master_IBI, I3C_MasterRW, I3C_MasterRW_PDMA and I3C_SecondaryMaster.
 - I3C_Target: Replace samples of I3C_Slave_HotJoin, I3C_Slave_IBI, I3C_Slave_Wakeup, I3C_SlaveRW, I3C_SlaveRW_PDMA and I3C_SecondaryMaster.
 - ISP samples
 - Fix flash select setting in flash download of Keil project.
 - Fix the issue of “Reset and Run” command not booted from APROM.
 - Jpeg_Display: Add.
 - LwIP_MQTT: Renew flespi token.
 - NuvotonAudioGUI_Firmware: Add.
 - QSPI_DualMode_Flash, QSPI_QualMode_Flash, SPI_Flash: Improve performance.
 - RNG_EntropyPoll, RNG_Random: Remove SysTick dependency.
 - SPIM samples: Update trim procedure to reduce times to erase or program Flash.

Revision 3.01.003 (Released 2025-10-29)

- Peripheral register
 - eadc_reg.h: Remove some redundant bit-field macros.
- Standard driver
 - retarget.c: Improve compatibility with CMSIS RTE.
 - CLK: Remove CLK_APLLCTL_APLLSRC_HXT_DIV2.
 - LPPDMA: Redefine LPPDMA_INT_TRANS_DONE and LPPDMA_INT_EMPTY to support multi-bit mask.
 - PDMA
 - PDMA_INT_TRANS_DONE, PDMA_INT_EMPTY, PDMA_INT_TIMEOUT, PDMA_DisableInt, PDMA_EnableInt: Support multi-bit mask.
 - PDMA_INT_ALIGN: Add.
 - SPIM: Remove voltage raise for HyperBus device and octal SPI flash.
- CMSIS driver
 - RTE_Device.h: Improve compatibility with CMSIS packs.
 - I2C: Master adds I3C IP support.
 - USB: Add HSUSB IP support.
 - VIO: Add NuMaker board support.
- Library

- UsbHostLib: Improve robustness of memory management and EHCI interrupt handling.
- Sample code
 - DMIC_I2S_Play, I2S_Codec_PDMA, I2S_MP3Player, I2S_WAVEPlaye: Fix cache line alignment issues of I2S PDMA buffers.
 - EADC_AverageCMP: Add.
 - MP3_Recorder: Add USB storage device support.
 - VS Code projects upgrade to use GCC 14.3.1.

Revision 3.01.002 (Released 2025-8-8)

- Peripheral register
 - canfd_reg.h
 - CANFD_RXF0A_F0AI_Msk: Replace CANFD_RXF0A_F0A_Msk.
 - CANFD_RXF0A_F0AI_Pos: Replace CANFD_RXF0A_F0A_Pos.
 - hsusbd_reg.h: Fix definitions of HSUSBD_EPBUFSTART_SADDR_Msk and HSUSBD_EPBUFSTART_SADDR_Pos.
- Startup
 - SysTick vector on flash uses Default_Handler.
- Standard driver
 - CANFD: Remove unsupported UTSU function.
 - HSUSBD: Add HSUSBD_DISABLE_HS_HANDSHAKE and HSUSBD_ENABLE_HS_HANDSHAKE.
 - SPI: Add SPI_DISABLE_3WIRE_MODE and SPI_ENABLE_3WIRE_MODE.
 - SPIM
 - Raise voltage to 1.2V for HyperBus device and octal SPI flash.
 - Support Infineon octal SPI flash.
 - SYS
 - SYS_GPC_MFP0_PC2MFP_UTCPD0_CCDB2: Replace SYS_GPC_MFP0_PC2MFP_UTCPD0_CCDB1.
 - SYS_GPC_MFP0_PC3MFP_UTCPD0_CCDB1: Replace SYS_GPC_MFP0_PC3MFP_UTCPD0_CCDB2.
 - SYS_ResetModule: Add SPIM clock setting handling.
- CMSIS driver
 - CAN, ETH_MAC, Flash, GPIO, I2C, MCI, SAI, SPI, USART, USB, USBH: Add.
- Library
 - CryptoAccelerator: Improve cache coherence.
 - JpegAcceleratorLib: Improve performance.
 - UsbHostLib: Add UVC support.
- Sample code
 - AWF_GSensor_Wakeup: Use I/O buffer to replace fixed address.
 - DMIC_VAD_Wakeup: Increase VAD power threshold.
 - HSUSBD_Audio20_Codec and HSUSBD_Audio20_Headset: Fix no sound issue.
 - HSUSBD_HID_Mouse: Improve LPM stability.
 - HSUSBD_RNDIS: Add.
 - HSUSBD_Video_CAM: Fix UVC image noise issue and race condition of UVC functions.

- HSUSBH_USBH_UVC, HSUSBH_USBH_VCOM_MassStorage and ImageClassification: Add.
- I3C samples: I3C pins enable Schmitt trigger.
- ISP_DFU_20 and ISP_HID_20: Fix USB high-speed issue.
- ISP_I2C and ISP_SPI: Fix potential command failure.
- KeywordSpotting: Add UAC support.
- KS_AESKey: Improve cache coherence.
- ObjectDetection_FreeRTOS, VisualWakeWords: Fix I/O buffer alignment and race condition of UVC functions.
- RTC_TimeAndTick: Remove because almost the same as RTC_Time_Display.
- SecureApplication samples: VS Code projects require Python 3.12 at least for post-build.
- SPIM_HYPER_ExeInHRAM: Fix I/O buffer alignment and GCC project execution failure.
- SPIM_HYPER_RW_MemMap: Fix I/O buffer alignment.
- USB_D samples: Improve stability and performance.
- VS Code projects update for Nuvoton NuMicro Cortex-M Pack.

Revision 3.01.001 (Released 2025-2-14)

- Initial release for M55M1.

Revision 3.00.001 (Released 2024-1-31)

- Initial release for M55M1ES.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*