

ARM® Cortex®-M0 32-bit Microcontroller

NuMicro[®] Family NUC126 Series BSP Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com



Revision 3.00.007 (Released 2023-09-11)

- 1. Modified ADC_PWMTrigger sample code print message for IAR Tiny printf formatter.
- 2. Modified USCI UART TxRx Function and FMC IAP sample code.
- 3. Revised startup NUC126.S and retarget.c to fix Hard Fault can't run code.
- 4. Modified VendorName of Nu DFU.inf.
- 5. Added SYS_PowerDown_MinCurrent sample code.
- 6. Updated SPI_Loopback sample code.
- 7. Updated Windows driver of USBD_Printer_And_HID_Transfer sample code.
- 8. Modified SYS UnLockReg() time-out handler.
- 9. Fixed TX hardware FIFO size to 16 and call UART FIFO size from uart.h in USBD VCOM sample code.
- 10. Removed printf for PowerDown in USBD sample code.

Revision 3.00.006 (Released 2022-08-17)

- 1. Revised printing error message for I2C sample code.
- 2. Fixed return in main() cause hardfault issue.
- 3. Revised infinite loop timeout handler.
- 4. Fixed USBD MassStorage CDROM crash on Linux.
- 5. Added I2C hang up and recover mechanism for I2C Master and Slave sample code.
- 6. Opened CESTOPEN in trim function of USBD sample code.
- 7. Updated auto trim to use SW boundary function of USBD sample code.
- 8. Enabled schmitt trigger of I2C sample code.
- 9. Fixed UART TX FIFO control issue in USBD VCOM sample code.

Revision 3.00.005 (Released 2021-01-21)

- 1. Fixed USCI SPI driver issue in Library/StdDriver/src/usci spi.c
- 2. Modified to pass USB-IF CV-Chapter 9 & Class test of all USBD Sample code.
- 3. Fixed USPI SET SS HIGH macro in Library/StdDriver/inc/usci spi.h
- 4. Corrected adc definitions for conversion sampling time selection in Library/StdDriver/inc/adc.h
- 5. Added Apache-2.0 license declaration in driver source.
- 6. Added README.md file.
- 7. Added SPI TRIGGER TX RX PDMA and SPI DISABLE TX RX PDMA API.

Revision 3.00.004 (Released 2019-10-25)

- 1. To support GNU GCC.
- 2. Add emWin supporting.
- 3. Improve USB driver reliability.
- 4. Add ISP firmware sample code.

Revision 3.00.003 (Released 2018-01-26)

- 1. Added CLK_SysTickLongDelay() function for long delay.
- 2. Improved baud rate calculation accuracy of UUART driver.
- 3. Improved robust of USB sample code.

Revision 3.00.002 (Released 2017-05-05)

- 1. Update multi-function pin name definitions.
- 2. Add single byte and multi byte write/read APIs for I2C.



Revision 3.00.001 (Released 2016-10-17)

1. Initial Release



Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

Please note that all data and specifications are subject to change without notice.

All the trademarks of products and companies mentioned in this datasheet belong to their respective owners