

Oxford Flying Club Flight Operations Incident Report (FOIR)		
To: OFC Safety Officer	From:	Date: May 2, 2020
Note: Refer to Club website	Note: Name is optional but helpfu	ul.
Type of Event - check all appropriate responses		
X Altitude Deviation	☐ Runway/taxiway excursi	ion
☐ Navigational Deviation	☐ Runway Incursion	☐ Severe Wake Turbulence
☐ Communication Error	☐ Severe Turbulence	☐ Collision Hazard
☐ Severe Icing	☐ Aborted Takeoff	Other
2. Weather Conditions - check all appropriate responses		
□ IMC	☐ Thunderstorm	☐ Icing
X VMC	X Turbulence	X Crosswind
☐ Precipitation	X Wind shear	□ Other
3. Time/Date - check or fill out all appropriate responses		
Month5 Day2	Year <u>2020</u>	□ 0400-0759 local time
X 0800-1559 local time	□ 1600-1959 local time	□ 2000-2359 local time
4. Mode of Flight	•	
□ Ramp	□ Climb	□ Descent
□ Taxi	□ Cruise	X Approach (Practice)
□ Takeoff	☐ Holding	☐ Landing
5. Action Taken - check all a	propriate responses	
☐ Performed Emergency Pro	c. Declared Emergency	☐ In-Flight Engine Shutdown
☐ Followed Checklist	☐ Requested Crash/Rescue	□ Divert From Dest. Airport
☐ Requested Medical Assist.		
6. Safety Officer, or his/her designee, Initial Assessment		
Probability: 3 Severity: 1		
Resulting Risk Code: 1 Note: Risk Assessment Code of 5 requires immediate notification of Club President.		
7. Comments or Suggestions (Use additional sheets as necessary)		
While on a practice approach to ILS 36 OXC I descended to 2500' MSL, the chart altitude for the segment.		
It was quite turbulent and 150' of altitude was lost breaching the upper limit of airspace for KJSD by 150'.		
Correction to exit the D airspace was made immediately. Nasa form was submitted. (Not attached)		
KJSD = Sikorsky Aircraft Private field.		
8. Safety Officer, or his/her designee, Investigation summary:		
Safety Officer, or his/her desig		Date: July 4, 2020
Tracking # (assigned by Safety Officer): FOIR-2020-001		
Summary: The pilot and CFI responded properly. It is recommended that after CUTMA intersection pilots remain at 3,000' until glideslope intercept. Then fly the glideslope down to KOXC which will		
keep the aircraft clear of KJSD airspace.		
Roop the unoral or Roop anopase.		
9. Notes		
a) If a NASA form was filed (Strongly Recommended if practical), please attach a copy to this report.		
b) For confidentiality, this form may be delivered to any Safety Committee representative.		
Thank you for your interest in your Safety Program.		

DCR-2019-001 OFC1002 Revision: Initial Date: March 14, 2019