

Oxford Flying Club					
To: OFC Safety Officer From:					Date:
10. Of 6 Safety Officer	Name surmised but withheld				Date.
	Aug 18, 2019 est.				
Note: Refer to Club website	Note: Name is optional but helpful.				,
Type of Event - check all appropriate responses					
☐ Altitude Deviation	☐ Runway/taxiway excursion			☐ Foreign Object Damage	
☐ Navigational Deviation	☐ Runway Incursion			Severe V	Wake Turbulence
☐ Communication Error	☐ Severe Turbulence			Collision Hazard	
☐ Severe Icing	☐ Aborted Takeoff		X	K Flat Spot on Tire	
2. Weather Conditions - check all appropriate responses					
□ IMC	□ Thunderstorm			Icing	
□ VMC	☐ Turbulence			Crosswind	
□ Precipitation	□ Windshear			□ Other	
3. Time/Date - check or fill out all appropriate responses					
Month 08 Day 18	Year 2019			0400-07	59 local time
□ 1200-1559 local time	☐ 1600-1959 local time			2000-23	59 local time
4. Mode of Flight					
□ Ramp	□ Climb			Descent	
□ Taxi	□ Cruise			Approach	
□ Takeoff	☐ Holding		X	Landin	g
5. Action Taken - check all appropriate responses					
☐ Performed Emergency Proc.	☐ Declared Emergency			In-Fligh	t Engine Shutdown
☐ Followed Checklist	☐ Requested Crash/Rescue			Divert From Dest. Airport	
☐ Requested Medical Assist. X Return to Ramp. No report made!					
6. Safety Officer, or his/her designee, Initial Assessment					
Probability: 4	Severity: 2	Severity: 2 Note: Risk Assessment Code of 5 requires			
action needed under the existing circumstances. immediate notification of Club President. 7. Comments or Suggestions (Use additional sheets as necessary)					
7. Comments of Suggestions (Ose additional sheets as necessary)					
Without a report from the pilot it is difficult to determine what was the root cause. Generally, this kind of					
tire damage (see attached) is usually caused by landing with the brake applied or over-braking after touchdown.					
8. Safety Officer, or his/her designee, Investigation summary:					
Safety Officer, or his/her designee, Name: Alan Amato Date: 10/30/2019					
Tracking # (assigned by Safety Officer): FOIR-2019-001					
Summary: The Safety Officer's designee would like to assume that the pilot did not know that he/she					
did this damage. If this is the case, it may be appropriate for members to consider a post-flight inspection of the aircraft. Knowingly leaving the aircraft with a flat spot on the tire may					
provide a hazard, or at least inconvenience, to the next pilot.					
9. Notes					
a) If a NASA form was filed (Strongly Recommended if practical), please attach a copy to this report.					
b) For confidentiality, this form may be delivered to any Safety Committee representative.					
Thank you for your interest in your Safety Program.					

DCR-2019-001 OFC1002 Revision: Initial Date: March 14, 2019

