

Meeting Minutes

19 September 2023, 6:30 PM – Hangar NW B10

Attendees

Directors (6): Vaughn Mauren*, Joseph McCormick, Leo Mollica, DJ Nicholson, Scott Price, Francis Pullaro

Members (17): Ryan Archer, Daniel Berk, Philip Caporusso, Jack Dennis, Daniel Gannon, Brian Hanecak, Amy Kaniewski, Justin Leach, Cody McManama, Jillian Porter, Bruce Richardson, Brian Smith, Christopher Sutherland, Vincent Tanuis, Wayne Tremallo, Sheldon Wermes, Joshua Whiteley

Members via Zoom (3): Eric Atkins, Edward Chromczak**, Burt Stevens**

Directors and Members are Regular Members unless otherwise noted as *Associate, **Emeritus Associate, or ***Medical Associate.

Note: This meeting was Zoomed also, as arranged by Francis Pullaro.

General Business

The Meeting was called to order at 6:40 p.m. by President Francis Pullaro. As this is an odd month, this was considered a Member Meeting. The meeting was held in Hangar NW B10 and via Zoom. A Quorum of Directors (1/2 of Directors) *was* present. A Quorum of Members (1/3 of Regular Members) *was* present. (6 of 8 Directors, and 23 of 69 Regular Members, were present.)

Guests

The Club welcomed the following guests:

Tim Thorland

New Members

The Club welcomed the following new members:

• David Smith (Regular Member)

Meeting Minutes

July 18 Meeting Minutes (Monthly Meeting) and August 28 Meeting Minutes (Special Board Meeting) posted on the Club's website were approved.

New Certificates & Ratings

The Club proudly recognized these members who recently earned new certificates or ratings (alphabetically):

- Peter Callahan, Private Pilot Certificate (September 14)
- Jack Dennis, Air Transport Pilot (ATP) Certificate & Gulfstream GIV Type Rating (August 29)
- Vaughn Mauren, Pilatus PC-12 Type Rating (September 15)
- Jillian Porter, Private Pilot Certificate (September 3)

October 16, 2023

Monthly Reports

Refer to Club officers' monthly reports for Activities*, Finance, Long-Range Planning (LRP)*, Maintenance, Membership and Safety (attached).

* Written report was not submitted this month.

President Francis Pullaro called for any questions on the monthly reports. Discussion followed.

Activities

Membership Officer DJ Nicholson announced the RAF (<u>Recreational Aviation Foundation</u>) annual event at Waterbury Airport (N41) at Mt. Tobe on October 6-7. See flyer (<u>attached</u>).

Maintenance

General - President Francis Pullaro said the Maintenance Officer position remains vacant.

Coordination - Francis spoke about using the Flight Schedule Pro (FSP) maintenance function to improve communications with shops and between members through work orders, to ensure logbook entry compliance before returning aircraft to service, and to verify spending authorizations.

N98819 - Members discussed ongoing trim issues with N98819. Pilots should refer to the white board in the hangar for guidance on setting the trim wheel for takeoff.

Financial Stability

President Francis Pullaro spoke about preserving the Club's long-term financial stability. He asked the Finance Committee to review aircraft rates to account for maintenance cost trends using recent data-points with engine overhauls, oil changes, and repairs, and the need for a "slush fund" to cover large unbudgeted aircraft repairs.

Avionics Upgrades

Refer to "OFC Overhaul & Avionics Upgrades - Draft Budget" (attached).

President Francis Pullaro opened discussion on funding the engine overhaul for N735GC and the avionics upgrades for Club aircraft.

Finance Committee Member Sheldon Wermes reviewed the Finance Committee's recommendations as presented in the Draft Budget.

Following discussion, Francis requested a Motion to adopt the Committee's recommendations.

Vice President Vaughn Mauren made, and Regular Member Wayne Tremallo seconded, the following Motion.

Motion: Resolved, the Club adopts the recommendations of the Finance Committee as presented to fund the "Avionics Upgrade Plan, Years 2023-2025, Version 5, July 18, 2023."

Francis called for voting and the Motion was adopted by a show of hands.

Accounts Receivable

President Francis Pullaro provided an update on the status of the Club's accounts receivable.

October 16, 2023

Since implementing new payment policies several months ago, receivables decreased from about \$20,000 to about \$10,000, but are starting to creep back up again. Receivables are now about \$12,000, of which about \$4,000 is more than 30 days past due.

Standard Operation Manual

Refer to redline markup of the Club's Standard Operation Manual (attached).

In view of the Club's continuing accounts receivable challenges, Francis introduced a proposal to amend the Club's Standard Operation Manual to strengthen suspension and termination provisions for past due balances and requested a Motion to adopt the proposal.

Nominating Committee Member Bruce Richardson made, and Regular Member Jillian Porter seconded, the following Motion.

<u>Motion:</u> Resolved, the Club adopts the changes to the Standard Operation Manual as presented in the redline markup Version 3, September 19, 2023.

Following discussion, Francis called for voting and the Motion was adopted by a show of hands.

Automatic Electronic Payments

President Francis Pullaro asked for volunteers to serve on a committee to develop a recommendation on whether to require automatic electronic payments to satisfy Club members' dues and aircraft hourly charges.

Additional Business

No additional business was discussed.

The Meeting was adjourned at 7:36 p.m.

Meeting Minutes submitted by Scott Price, Secretary

#

October 16, 2023 3

Oxford Flying Club

August 2023

Financial Information

Assets				
Checking/Fuel Bank Accounts			\$10,990	
Savings (Prop/Engine Reserve)			\$185,010	
* Prop & Engine Reserve			\$70,177	
* Liability Insurance Fund			\$68,086	
* LRP Upgrade Fund			\$56,159	
Accounts Receivable			\$25,373	
Fixed Assets	Piper Archer N8261H	\$105,533		
	Cessna 172P - N98819	\$167,098		
	Piper Archer II - N4334X	\$147,248		
	Cessna C182Q - N735GC	\$186,580		
Aircraft - (values based on AOPA Vref figures as of 2		\$606,458		
			Total Assets:	\$827,830
Liabilities				
Accounts Payable (Includes Outstanding Quarterly I	nsurance Payments)		\$32,151	
Loan Payable · N735GC	Monthly payments, including interest: \$1,509.38. EndA	fter 9/1/2023 Payment	\$6	
Prop and Engine Reserve (all planes - cumulative)		,	\$67,546	

EquityTotal Liabilities:\$99,703TOTAL LIABILITIES & EQUITY\$728,127\$827,830

Aircraft Data Current Month

Equipment	Hours Flown	Flight Total	/ Hour	Fuel	/ Hour	Mx Expense	/ Hour	Hanger	Reserve	Upgrade Funds
N8261H	50.16	\$6,947	\$138.49	\$3,031	\$60.42	\$682	\$13.59	\$90	\$1,379	\$62
N4334X	30.70	\$4,605	\$150.00	\$1,990	\$64.83	\$1,627	\$53.00	\$90	\$844	\$15
N98819	31.10	\$4,199	\$135.00	\$2,092	\$67.27	\$567	\$18.23	\$90	\$855	\$36
N735GC	0.00	\$0	\$0.00	\$231	\$0.00	\$1,673	\$0.00	\$650	\$0	\$0
N228TR	11.60	\$2,842	\$245.00	\$845	\$72.85	\$711	\$61.33	\$0	\$0	
Totals	111.96	\$18,592	\$166.06	\$8,189	\$73.14	\$5,261	\$46.99	\$920	\$3,079	\$112

Inflows/Outflows	Current Month	Totals
Membership - Initiation Fees	\$1,500.00	
Membership Dues - Regular	\$11,137.96	
Membership Dues - Associate	\$1,000.00	
Total Flight Time Billing	\$20,092.30	
Interest Income	\$1.53	
Sporty's Rebate (quarterly)	\$0.00	
Finance Charges/Late Fees/Banktime To Club	\$0.00	
Billed Monthly Total:		\$33,731.79
Flight Hours (Unbilled Maintenance & Marketing)	\$24.70	
Transfer to P&E Reserve	\$3,078.90	
Insurance Fund Transfer (Goal \$57,187 by 3/15/2024)	\$5,136.42	
Transfer of aircraft upgrade funds	\$112.46	
5GC Loan Payments (current month as above)	\$1,509.68	
Fuel & Oil Expense	\$8,188.99	
Club Officer & Maint. Credits (5 aircraft)	\$1,755.00	
Other Misc. Expenses (FSP, Web Site, Events, Advertising, Landing Fees & Other)	\$158.80	
Licensing and Registration Fees for Aircraft (CBP Decals)	\$0.00	
Accounting Services & QuickBooks	\$705.90	
Aircraft Liability Insurance/D&O Insurance Payment	\$0.00	
General Maintenance Expense - (Includes 8TR tie-down space)	\$964.78	
Leaseback Aircraft Waterfall (Minus Management Fee Above)	\$902.16	
Total Aircraft Expense (above Ann/Av/Fee/Mx and Tiedown & Hanger)	\$6,180.51	
Expenses Total (Minus Initiation Fees To LRP Account):	<u> </u>	\$28,718.30
Monthly Cash Flow Total		\$5,013.49

Fund Balance	es (Variance)												Dues %		Month Only	_	All Funds
Dues:	Accounting												5.05%	\$	28.30	\$	(965.94)
	Avionics Sul	oscriptions											1.81%	\$	230.34	\$	1,002.32
	D&O Insura	nce											0.41%	\$	51.74	\$	90.11
	Hangar / Tie	Down											8.27%	\$	42.56	\$	(3,157.52)
	Insurance												39.86%	\$	5,077.22	\$	8,007.97
	Loan												11.72%	\$	(17.69)	\$	19,033.14
	Officer Cred												15.19%	\$	179.42	\$	61.55
	Taxes & Reg	istrations											0.25%	\$	31.62	\$	(264.88)
	Web Site / F	SP											0.59%	\$	15.12	\$	216.85
	General Ma	intenance											7.76%	\$	(2,272.78)	\$	(1,424.98)
	Marketing E	xpenses											0%	\$	-	\$	-
	Landing Fee	s											0.65%	\$	(13.66)	\$	375.89
	Quickbooks												7.76%	\$	(4.30)	\$	124.24
	Not Specifie	d											0.00%	\$	8,904.12	\$	45,014.62
	Upgrades - I	RP Fund												\$	1,501.53	\$	47,749.85
Aircraft															Last Month		Current Bal
N4334X																	- Carrent Dai
	Fuel													\$	126.14	Ś	3,193.00
	MX													\$	(298.02)	-	(15,516.16)
	P&E													\$	844.25	-	16,337.20
	Upgrades													\$	315.31	•	3,590.06
N735GC	Орбицись													۲	013.51	Ψ.	3,330.00
, 5500	Fuel													\$	(230.56)	Ś	(4,851.38)
	MX													\$	(1,260.00)	-	(18,225.23)
	P&E													\$	(321.75)		(3,573.75)
	Upgrades													\$	(1,812.31)		3,149.33
N8261H	Орбичес													۲	(1)011101)	٧	3,213.00
14020111	Fuel													\$	9.86	Ġ	4,872.34
	MX													\$	1,598.07	•	3,757.28
	P&E													\$	(276.96)		(15,070.23)
	Upgrades													\$	261.97	-	5,925.74
N98819	. •													-		-	
	Fuel													\$	(186.36)	\$	691.97
	MX													\$	753.10	\$	(10,915.17)
	P&E													\$	426.25	\$	33,295.13
	Upgrades													\$	117.24	\$	6,405.59
Fuel Account	Balance (Acr	oss All Aircra	ft)														\$3,905.93
Leaseback Re	port																
N228TR	Hours	Income	Fue	el Surchar	r Fuel	MX		Maint I			gar/Tie		urance		otal	Payo	
Apr-22		\$ 3,690.00		205.00	\$ 1,379.83	\$	311.46		175.64		340.00		552.04	_	726.03	\$	726.03
May-22		\$ 1,534.00	-	79.00	\$ 852.13	\$	311.46		72.75		340.00	\$		\$	(334.09)	\$	325.02
Jun-22	25.60	\$ 5,120.00	\$	256.00	\$ 1,539.59	\$	26.46	\$	243.20	\$	340.00	\$	689.38	\$	2,025.37	\$	2,025.37
Jul-22		\$ 6,520.00		326.00	\$ 3,341.76	\$	311.47	\$	326.00		340.00		877.92		1,648.85	\$	1,681.45
Aug-22	8.50	\$ 1,700.00	\$	85.00	\$ 904.61	\$	849.74	\$	85.00	\$	340.00	\$	228.91	\$	(623.26)	\$	(623.26)
Sep-22	0.00		\$	-	\$ -	\$	-	\$	-	\$	340.00	\$	-	\$	(340.00)	\$	(950.71)
Oct-22			\$	-	\$ -	\$	-	\$	-	\$	340.00	\$	-	\$	(340.00)	\$	(1,290.71)
Nov-22			\$	-	\$ -	\$	-	\$	-	\$	-	\$	-	\$	-	\$	(1,290.71)
Dec-22			\$	-	\$ -	\$	-	\$	-	\$	-	\$	-	\$	-	\$	(1,290.71)
Jan-23		\$ 1,300.00		-	\$ 572.41	\$	-	\$	-	\$	-	\$		\$	552.55	\$	(738.16)
Feb-23		\$ 2,205.00		-	\$ 759.85	\$	-	\$	-	\$	-	\$	242.37		1,202.78	-	464.62
Mar-23		\$ 2,033.50		-	\$ 943.09		-	\$	-	\$	-	\$	•	\$	(2,619.68)		(2,155.06)
Apr-23	7.10	\$ 1,739.50		-	\$ 497.64	\$	-	\$	-	\$	-	\$	234.58	\$	1,007.28		(1,147.79)
		4 46 00	4	_	\$ 2,025.36	\$	-	\$	-	\$	-	\$	1,017.63	\$	4,503.01	\$	3,355.22
May-23		\$ 7,546.00		-													
-		\$ 7,546.00 \$ 2,058.00		-	\$ 2,023.30		-	\$	-	\$	-	\$	277.54		882.13	\$	882.13
May-23	8.40		\$			\$	-	\$	-	\$ \$	-	\$ \$	297.36	\$	882.13 762.61		882.13 1,644.74
May-23 Jun-23	8 8.40 8 9.00	\$ 2,058.00	\$ \$	-	\$ 898.33	\$ \$	- - 711.48	\$				\$ \$		\$	762.61 902.16	\$	

Maintenance Report OFC Club Meeting September 19, 2023

Missing adapters for Garmin database updates- have you seen them?

8261H

- 61H had the oil changed and the lower spark plugs cleaned. Removal of the 4 lower plugs revealed heavy carbon fouling
- 61H had a safety incident with no claimed aircraft damage nor anyone hurt. The PIC reported that at KTTN at night while taxiing he got off the taxiway (tower was closed) and there were areas of construction. The grass was soft and PIC got the services of the airport to get back to the runway.

735GC

• A factory re-manufactured engine has been ordered for 735GC. Expected arrival is 9 to 11 weeks.

228TR

- 228TR is still grounded due to alternator light not resolved. ALT 1 lights comes on with no underlying alternator failure.
- Autopilot marked inop until VIP appointment on Oct 3rd due to sudden pitch down commands in ALT mode and wing rocking in HDG/NAV mode.

4334X

- 34X was grounded due to nosewheel shimmy. A required close tolerance bolt is not in stock and will be ordered today. The airplane will also be inspected for any further damage.
- During constant rate turns, the GI-275 heading indicator fails when getting close to the selected heading, then resumes operating normally.
- A deposit will be sent this week for the 34X avionics upgrades. OFC has requested the first available date for the work while avoiding 61H's scheduled maintenance in October. 98819 will be used to pick up the pilot flying 34X to shop so that the KX155 in 819 can be repaired same day. While the 34X upgrades are made, the shop will investigate the GI275 heading issue.

Dear Club members,

We had some new members join this month as reflected below.

	Jan 2023	Feb 2023	Mar 2023	April 2023	May 2023 **	June 2023	July 2023	August 2023	Sep 2023
Member type									
Regular	65	61	64	66	65	68	69	70	70
Associate	40	41	41	40	41	36	36	39	41
Med Associate	6	6	6	6	6	6	6	6	6
Associate Emeritus	4	4	4	4	4	4	4	4	4
Non-Member	1	1	2	2	3	3	3	3	3
Other	0	0	0	0	0	0	0	0	0
TOTAL	116	113	117	118	119	119	118	122	124

- Numbers for Regular and Associate have been fluctuating up and down in between reports as we reconcile between members switching roles and losing members for various reasons.
- We had one new member join since the last meeting, David Smith. When you see him at the hanger or on the ramp please welcome him.
- We have two potential members in the queue.
- Happy Flying and don't forget to keep your online profile updated! PLEASE!



OFC SAFETY COMMITTE | September 2023 UPDATE

- 1. Confidential Safety Report updates:
 - CFR 2023-001. Completed. Flight w/o Mx sign-off.
 - CFR 2023-002. Completed. Unmanned sighting from pilot.
 - CFR 2023-003. In Progress. Off Runway during taxi.
- 2. Safety Committee meeting Updates:
 - No meeting was held in Sept. yet we will continue having committee meetings ad-doc for special items/discussion.
- 3. Safety Meeting/Events updates.
 - By sept 15th Based on the status of OFC profile update.
 - 3 of 72 regular members (4%) are fully current. Lower than previous month.
 - 50 of 72 regular members (72%) needs CFI to fly. † Higher than previous month.
 - 22 of 72 regular members (30%) needs to attend or input safety meeting/event to remain current.
 ↓ Lower than previous month.
 - Please update your profile once you complete a flight or attend/complete a safety meeting.



EVENT SCHEDULE

Raffle Tickets \$1.00 EACH 25 FOR \$20

FRIDAY OCT, 6TH

Arrival Day! Event attendees are free to arrive anytime!

4-6pm - Group fly out to Candelight Farms (11N), and triumph (CT24)

6pm - Spot / Stol competition practice landings upon return to N41

7pm - Dinner and Campfire

8pm - Aviation-themed movie, and campfire

SATURDAY OCT. 7TH

7am - Breakfast is served! Pancakes, Sausage, bacon and breakfast dishes. (\$15.00 donation requested)

8-10am - Group fly out to Salmon River (9B8), Goodspeed (42B)

10-11am - Spot / Stol competition practice landings upon return to N41

11-12pm - Lunch is served! Provided by Barnstormers Burgers Food truck

12:30-2pm - 50/50 Pumpkin drop. \$10per pumpkin 50/50 cash prize awarded

2:30-4pm - Friendly Spot / Stol landing "competition" Sponsor donated swag awarded to top three

4pm - Raffle drawing and prizes awarded (present to win)

6pm - Dinner is served! Provided by Barnstormers Burgers Food truck

8pm - Aviation-themed movie, campfire, hanger flying stories and outright lies

Pumpkin drop pumkins \$10



Meal Donation
Requested per Meal
\$15

OFC Overhaul & Avionics Upgrades- Draft Budget

_	<u>Total</u>			Cash Flows		
Expenses	_	Sept. 23	Dec. 23	Mar. 24	Jun. 24	Apr. 25
5GC P&E and install	(\$65,000.00)	(\$65,000.00)				
34x Avionics Upgrade	(\$27,381.25)	(\$27,381.25)				
61H Avionics Upgrade	(\$65,943.25)			(\$65,943.25)		
819 Avionics Upgrade	(\$58,510.00)					(\$58,510.00)
Insurance 2 pmts. 2023	(\$29,392.00)	(\$14,696.00)	(\$14,696.00)			
Expense Total	(\$246,226.50)	(\$107,077.25)	(\$14,696.00)	(\$65,943.25)	\$0.00	(\$58,510.00)
Revenues						
Insurance Balance 9/1/20	\$68,085.69	\$68,085.69				
5GC P&E Account	\$21,509.45	\$21,509.45				
Current LRP Balance	\$56,065.82	\$56,065.82				
1 New Member Aug	\$1,500.00	\$1,500.00				
5GC Loan Pmt Continues	\$22,248.00	\$1,500.00	\$4,524.00	\$4,524.00	\$2,700.00	\$9,000.00
3 Member Loans	\$30,000.00			\$30,000.00		
5 Member Loans	\$50,000.00					\$50,000.00
Revenue total	\$249,408.96	\$148,660.96	\$4,524.00	\$34,524.00	\$2,700.00	\$59,000.00
Net	\$3,182.46	\$41,583.71	\$31,411.71	(\$7.54)	\$2,692.46	\$3,182.46

I. Oxford Flying Club Policy & Procedures

Section 1.01 This manual shall not represent restrictions in contradiction to or less restrictive than the club bylaws. (See Section III.)

Section 1.02 This Standard Operations Manual shall be reviewed and maintained by the OFC Safety Officer and, as adopted in October of 2021, will replace the former Training & Operations Manual referenced within the OFC Bylaws of 2017.

Section 1.03 Wherever this manual applies policy, the policy shall be required as described and enforced by the OFC Board of Directors (BOD).

<u>Section 1.04</u> Section III of this manual shall apply to all OFC policy.

II. Procedure Guidelines

<u>Section 2.01</u> Wherever this manual applies a procedure, the procedure shall be required as described and enforced by the BOD.

<u>Section 2.02</u> Section III of this manual shall apply to all OFC procedure.

III. Most Restrictive Clause

<u>Section 3.01</u> The most restrictive of any regulation or operational restriction by an appropriate governing agency, aircraft manufacturer, or OFC policy or bylaw shall apply wherever and whenever applicable.

Section 3.02 The BOD has authority to change any policy or procedure through electronic bulletins which shall be the rule until this manual is updated, but Section 3.01 is always applicable.

Section 3.03 Any deviation to a manufacturer specification or club policy and procedure must be approved by the BOD after a System Analysis Exercise is provided by the Safety Committee.

IV. Club Members

Section 4.01 No member may operate outside of their membership rules and restrictions without prior approval specific to each occasion. Except for medical reasons, a Regular member may not become an Associate member if he or she has been an Associate member within the previous twelve months. Membership category changes will be effective at the start of the next billing month. A new member must pay the initiation fee before the member has privileges to create flight reservations and act as PIC in club aircraft.

Section 4.02 Regular – reserved (reference bylaws)

Section 4.03 Club Instructors

- (a) The BOD shall maintain a published list of club instructors and may add or remove from the list as necessary.
 - (i) Any person acting as a CFI in club aircraft shall meet requirements in *Sections 5.03 and 6.03* and will require BOD approval prior to any instruction.
 - (ii) Anytime a club member is acting as a CFI, they are not utilizing club membership, but serving as a designated club instructor with BOD approval.

Section 4.04 Student Pilots – reserved (reference bylaws)

Section 4.05

Associate — Associate members, including club instructor associate members, may only fly club aircraft with a club approved instructor for the purpose of flight training or to obtain a club aircraft checkout. The associate member's reservation must identify the club instructor.

Associate members who are also club instructors may fly club aircraft in a pilot-in-command

capacity as long as they do so in the furtherance of club business and with the prior approval of the BOD.

Section 4.06 Club Member Guests – reserved

V. Club Aircraft Checkouts

Section 5.01 All checkouts which expire after a defined number of months shall all expire at the end of the calendar month of the expiring month.

Section 5.02 All checkouts or flight checks required by OFC shall be defined by the Chief Instructor and Safety Officer and shall be defined by the FAA standards listed in Airman Certification Standards (ACS) or Practical Test Standards (PTS).

Section 5.03 Required Club Checkouts

- (a) Initial Club Checkout (ICC)
 - (i) All members shall complete an ICC to be PIC in club aircraft and have access to the booking and scheduling of each make and model.
 - (ii) An ICC is specific to each make and model and shall only be required once except if a member has more than 12 months between (periods of -flight as PIC.-
 - (iii) A member must have at least 200 hours of fixed-wing time to act as PIC N228TR.
 - (iv) All members with less than 25 hours of PIC time in a Cirrus SR20 or SR22 time must complete the Cirrus VFR transition training program with a CFI approved by the club for Cirrus training before acting as PIC in N228TR. Any club member with more than 25 hours in an SR22 but no hours in an SR20, may become qualified in N228TR upon completion of a flight review in N228TR with a CFI approved by the club for Cirrus training.
- (b) Instrument Competency Evaluation (ICE)
 - (i) All members must receive an ICE prior to being PIC of OFC aircraft during an IFR flight or flight plan.
 - (ii) A member whose Instrument Checkride is in a club aircraft shall receive credit for an ICE.
 - (iii) An ICE shall only be valid for 12 months.
- (c) Flight Instructor Club Evaluation (FICE)
 - (i) Each Club Instructor shall complete an FICE prior to conducting any flights in club aircraft which are considered to be "flight instruction" under any FAR.
 - (ii) An FICE does not expire provided the member does not have more than 12 months between periods of flight instruction.
- (d) Proficiency Check (PC)
 - (i) A PC is required when a lapse in proficiency has occurred as listed in Section VI.

VI. Club Proficiency Requirements

Section 6.01 Aircraft Checkout

- (a) Each member shall complete an Initial Club Checkout (ICC) or Proficiency Check (PC) whenever this policy dictates to utilize Flight Scheduler Pro (FSP).
- (b) Each member will be required to complete an ICC for each type of aircraft by a club CFI.
- (c) Student pilots will be required to have a CFI signoff in his/her logbook before any solo flights. If a member completes a private pilot check ride in a club aircraft with club CFI instruction, that will count as an ICC in that aircraft type.
- <u>Section 6.02</u> An Instrument Competency Evaluation (ICE) shall be completed every 12 calendar months to act as PIC in IFR flight conditions in club aircraft.
- Section 6.03 Annual Proficiency Check (PC)

- (a) Members who wish to fly club aircraft as PIC must complete an annual proficiency check. The PC will mirror ACS standards and be posted yearly by the BOD.
 - (i) A yearly PC will not have to be performed if the pilot has met any of the following requirements:
 - 1) Members who've flown a minimum of 24 hours in the preceding 12 months (club or non-club aircraft). **See Section 6.04 below**
 - 2) Obtained a new license or rating. The new annual PC date will be 12 months from the date of the check ride.
 - 3) Club CFIs who provide a minimum of 16 hours of dual instruction in the preceding 12 months and provide evidence of the time to the BOD.
 - 4) An exemption given by the BOD.

Section 6.04 Club Currency

- (a) ICC currency shall be defined as follows:
 - (i) A minimum of one flight within 90 days in each aircraft make and model except that currency in the Skylane qualifies for currency in the Skyhawk; and
 - (ii) A minimum of 2 hours PIC in club aircraft within a 90-day period with a minimum of 3 takeoffs and landings.
- (b) If a member falls out of club or ICC currency, they must perform a PC. **See Section 6.03 above** This PC will count as an annual PC allowing the 12-month annual PC clock to be reset.
- Section 6.05 Members have the responsibility for maintaining their currency profile on the Club website.

 At any time, a member may be asked to present evidence of compliance to the BOD to retain flying privileges in OFC aircraft. Lack of such documentation may result in booking privilege suspension or membership termination.
- (a) Members who fly non-club aircraft or who fly dual flights (e.g., safety pilot IFR) will have to submit their time to the vice-president so the hours can be inputted into FSP.

VII. Safety Meetings Attendance

Section 7.01 Every member is required to participate in a two (2) safety meetings each year in order to maintain access to aircraft booking and be considered proficient regardless of flight hours. Members have the responsibility for maintaining their safety profile on the Club website. At any time, a member may be asked to present evidence of compliance to the BOD to retain flying privileges in OFC aircraft. Lack of such documentation may result in booking privilege suspension or membership termination.

Section 7.02 A safety meeting shall be defined as

- (a) Any OFC sponsored safety meetings as approved by OFC Safety Officer
- (b) Any AOPA safety training approved by the OFC Safety Officer
- (c) Any FAAST sponsored IMC or WINGS events attended.

Section 7.03 Outside Flying & Exemptions

(a) Any outside flying or exemptions to the requirements listed in Section VI are considered on a case by case basis by the Chief Flight Instructor & Safety Officer for approval.

VIII. Aircraft Scheduling Policy

Section 8.01	The club shall maintain Flight Scheduler Pro for the scheduling of aircraft.

<u>Section 8.02</u> New members shall be added after payment of the initiation fee.

Section 8.03 A member must be meet Club Proficiency Requirements (Section VI) and Club Checkout Requirements (Section V) to book aircraft.

- Section 8.04 Associate Members may have one booking at any given time consisting of not greater than 24 hours. Regular members may have a maximum of 4 bookings at any given time consisting of not greater than:
- (a) 3 individual daily bookings not to exceed a combined total of 24 hours and cannot to extend into another calendar day.
 - (i) In order to qualify for a daily booking, you may not have any *** in your online booking. Note: a *** in the reservation will only appear if you exceed 24hrs.
- (b) 1 overnight booking (denoted by a *** in your online reservation).
 - (i) Only ONE overnight reservation is allowed per pilot at any given time.
 - (ii) An overnight booking is any entry that is over 24 hours and does not exceed 96 hours (an *** will be automatically added to your booking to indicate it is overnight).
 - (iii) Your 4th booking may be converted to a daily booking, waiving your option to have an overnight booking when used in this manner.
- (c) Every calendar year each member is allowed a one-time 5th booking called a "long booking" defined as any booking more than 96 hours and less than 288 hours (5- 12 days).
 - (i) Extensions beyond 12 days are allowable pending favorable membership approval. 7 Revised April 2018
 - 1) Cancellation of this booking forfeits the right to an additional long booking until the following calendar year or pending favorable membership approval.
 - (ii) Members will be blocked from manually entering this booking, however:
 - If you would like to schedule a "long booking", please send an email with the requested dates to the Master Scheduler (who is the Vice President of the club or his designee.) He will enter your booking dates into the system for you.
- Section 8.05 If you are not at the aircraft within 45 minutes of your scheduled start time, you are subject to forfeiture of your booking to the backup booking if one is scheduled.
- <u>Section 8.06</u> If a member wishes to use an aircraft outside of these booking rules, a request must be made to and approved by the BOD-.

IX. Aircraft Maintenance & Responsibilities

- Section 9.01 The BOD is ultimately responsible for maintaining the aircraft whereas no member shall perform or request maintenance on an OFC aircraft without approval from the BOD except that,
- (a) A maintenance captain is authorized to approve work orders for routine maintenance up to \$1000.
- (b) The maintenance officer is authorized to approve work orders up to \$2,500 for routine maintenance and keeping each club aircraft airworthy. Amounts greater than \$2,500 require the authorization of the maintenance officer, president, and treasurer.
- (c) Proposals to upgrade club aircraft avionics, interior, and paint shall be developed by the long-range planning committee and must be approved by a vote at a club meeting.
- Section 9.02 Any change to an aircraft per 14 CFR Part 43 maintenance, preventive maintenance, rebuilding, and alteration, shall require the guidance of the MX Team and completion of a work order.
- Section 9.03 A Maintenance Policy for Pilots shall be located in the OFC QRH for referenced located in each aircraft.
- Section 9.04 Any member may Ground an aircraft which would require an appropriate FAR Part 43 certified mechanic to inspect the discrepancy in question.

- <u>Section 9.05</u> The MX Team must ensure the proper records are maintained for aircraft airworthiness.
 - (a) Any squawk of a system or equipment which is inoperative will be considered grounding until the MX Team has appropriately managed the discrepancy and approved it for flight.
- (b) Only the MX Team may authorize the use of an aircraft after a discrepancy is found or squawk is made.
- (c) No club aircraft shall be returned to service without a logbook entry and confirmation by the plane captain and maintenance officer that all work requested in a work order was completed.
- (d) (Reserved for future use.)

Section 9.06 PIC Member Squawks

- (a) Any discrepancy found must be squawked in Flight Schedule Pro (FSP) and communicated with the MX Team prior to the aircraft's next flight.
- (b) Authorization of flight after an open squawk has been reported is the sole responsibility of the MX Team
- (c) The PIC has the ultimate responsibility to know of squawks and how they may create limitations on a flight operation via Flight Schedule Pro.

X. Rates, Payments & Statements

- Section 10.01 Statements are sent to all members via email during the first week of each month.
- <u>Section 10.02</u> Payment is due upon receipt and is past due if not paid_by the end of the month in which the statement is originally sent.
- <u>Section 10.03</u> Finance charges may be assessed to any past due amount.
- Section 10.04 Any member or Club CFI having a balance more than 630 days past due will have flight privileges and airport gate access suspended until the account is paid in full. (already adopted) Each member is responsible for dues charges incurred during the suspension period.
- Section 10.05 A member having a balance that is more than 90-75 days past due will be presented for termination from the club at the next club meeting. The terminated member may appeal the termination at the following-monthly club meeting following termination and will remain as a suspended member pending the appeal. (already adopted)
- Section 10.06 The following are the regular member hourly rates, per tach hour, for flying club aircraft:

N228TR, \$245

N735GC, \$175

N4334X, \$150

N8261H, \$140

N98819, \$135

Associate members will be charged the rate of 1.5 times the hourly rate of regular members.

XI. Operational Policy & Procedures

Section 11.01 Aircraft Flight & Ground Operation

- (a) All aircraft must be operated within their specific manufacturer specifications.
- (b) PIC Members are responsible for referencing engine manuals, aircraft manuals, and bulletins necessary to each make and model.
- <u>Section 11.02</u> The OFC QRH is required for operation and shall be used whenever necessary.
- (a) Revision recommendations to the QRH may be sent to the Safety Chair
- Section 11.03 No aircraft engine may be used above taxi power (~1200 rpm) unless on a painted taxi lane.
- (a) All engine run-ups above 1200 rpm must be made in appropriate airport locations avoiding hazards in front of and behind aircraft.
- (b) No prop blast or aircraft shall be directed towards buildings, vehicles, other aircraft, or equipment.

XII. Ramp, Hangar, & Storage Policy

- <u>Section 12.01</u> No personal items shall be stored on OFC property without BOD approval
- Section 12.02 No OFC equipment or tools shall be for personal use without BOD approval

Section 12.03 Ramp Storage

- (a) All aircraft must be properly tied down, locked, and covered anytime it will remain on the ground for more than 3 hours.
- (b) All appropriate cowl plugs and pitot covers must be utilized anytime it will remain on the ground for more than 3 hours.
- (c) Any equipment, i.e., ladders, pre-heaters, tie down straps, chocks, and vehicles, must be properly stored clear of all aircraft movement areas and never left loose on the ramp.

Section 12.04 Hangar Use & Storage

- (a) Any aircraft parked in the hangar shall be parked with chocks, doors closed, and completely shut down with properly placed away from ignition.
- (b) All equipment or furnishings shall be stored clear of aircraft movement in or out of the hangar at all times.
- (c) The hangar shall never be left unlocked open and unattended.

Section 12.05 Non- KOXC Parking and Storage

(a) All aircraft and equipment belonging to OFC shall be properly stored as mentioned in this section as applicable.

Section 12.06 All costs or conveniences are paid for and arranged by the PIC club member

XIII. Preflight & Postflight Policy

Section 13.01 Preflight Operations

- (a) All aircraft must be checked out in Flight Scheduler Pro prior to access of the aircraft.
 - (i) This ensures a pilot doesn't disrupt on-going maintenance or begin preflight of a grounded aircraft.
- (b) A PIC Member shall utilize the OFC QRH Preflight checklist once the FSP checkout has been completed.

Section 13.02 Postflight Operations

- (a) All flights shall be checked in with appropriate squawks, fuel, tool kit, cleanliness and storage policy prior to the PIC Member leaving the aircraft.
- (b) A PIC Member shall utilize the OFC QRH Postflight checklist prior to leaving the aircraft for storage. (See Section XII)

XIV. Use & PIC Policy

- Section 14.01 All OFC aircraft shall be operated by an authorized, current, and proficient regular member or instructor. Whereas any PIC in the aircraft shall be in good standing with all club requirements and following all FAR's to operate as PIC.
- <u>Section 14.02</u> Any use of the aircraft shall be within all insurance coverage, bylaws and manuals provided or mentioned within this document.
- Section 14.03 At no time shall a non-member act as, nor be required as a PIC in any application of the FAR's.
- (a) A club instructor may authorize a guest to manipulate the flight controls during a "Marketing Flight", but shall not log any of the flight time for the non-member nor shall he/she consider it dual given. This shall only be a demonstration flight where the instructor is the only PIC. No club instructor may provide a Marketing Flight without prior approval of the Membership Officer and President.

Section 14.04 No OFC aircraft shall be used in a commercial operation except for flight training with club instructors. All members are required to understand the privileges and limitations regulations preventing the operation from ever becoming a commercial operation.

XV. Seasonal Operations

<u>Section 15.01</u> Summer Operations

- (a) High winds, increased insects, reverted rubber, thunderstorms and hail represent challenges for aircraft parked outside. All members must assist with thorough inspections of aircraft and equipment belonging to OFC when suspected damage of any property could be sustained.
- (b) Aircraft cleanliness from insects, dirt, and debris is essential to the longevity of the aircraft and it must be maintained by each PIC Member after each flight.

Section 15.02 Winter Operations

- (a) Preheating is essential to properly operate the aircraft's engine during cold weather. It also reduces wear and tear allowing the operation to cost less and last longer.
 - (i) Anytime where 4 hours has lapsed where the temperature was < 32F or the engine hasn't been running, a preheat is required.
 - (ii) A Preheat Policy shall be located in the OFC QRH for reference located in each aircraft.
- (b) Winter brings challenging weather with snow, ice, slush and frost. The aircraft shall be kept clean of these types of precipitation when necessary. The weight of snow and ice can damage the aircraft. Removal must be careful not to damage paint, antennas, and flight controls.
 - (i) No one shall use removal techniques that could damage the aircraft or use of any de-icer agent that is not an approved solution at OFC.