

Oxford Flying Club							
Confidential Safety Report							
Name of Reporting Member	Aircraft # or Approximate Location:				Date Reported:		
Note: Optional and will be redacted.	Note: Optional and will be redacted.			- 1	11/11/202		
	735GC - Keene, NH						
1. Date of Event: 10/7/2021 Local Time (24hr approx okay)					7pm		
2. Type of Event - check all appropriate responses							
Aborted Takeoff	Foreign Obj	Foreign Object Damage		Collision Hazard			
Abnormal Landing	Weather	<u> </u>		Airport Hazard			
Hangar Safety	Maintenance Issue/Discrepancy			Other (Please add description)			
3. Weather Conditions - check all appropriate responses							
IMC or VMC	Thundersto	Thunderstorm		Icing			
Cold/Heat Related		Turbulence		Crosswind			
Precipitation		Windshear			Other (Please add description)		
4. Phase of Operation - check all appropriate responses							
Ramp/Hangar Area		Takeoff			Descent		
Preflight	L Climb	Climb		Approach			
Taxi-Out	Enroute			Landing			
5. Pilot Action - check all appropriate responses							
Declared Emergency		Trouble Shooting In Flight			Diverted From Planned Dest.		
Emergency Checklist		Trouble Shooting On Ground		Requested Medical Assist.			
Requested Crash/Rescue		NASA Report Filed		Aircraft Grounded			
	ntact Airport Manager Activated ERP			Other (Please add description)			
6. Comments or Suggestions: Is additional information attached: No							
Reporting Member Summary:							
Reporting Member Summary: GC flew normally with normal operating parameters from Otc to EEN. After dinner I. prepared plane for departure and noticed oil pressure was reading slightly above "O". Called Peter Dawson and after a couple checks decided to ground aircraft. Aircraft was							
EEN. After dinner prepared plane for deficient							
oil pressure was reading slightly above of Called Peter Dawson and							
after a couple checks decided to ground aircraft, the							
Fied down and secured according to OFC SOP'S + QRH.							
7. Name of Safety Officer or Designee: Peter Dawson Date Reviewed: 11/11/2021							
			Summary Attached: - No				
Resulting Risk Code: -3 Assigned Tracki			g # OFC-CSR 2021-011				
Committee Summary:							
This was the second time where the oil pressure regulator was stuck creating a constant low oil pressure. In both situations the mechanic							
involved removed, cleaned, and reinstalled the regulator correcting the problem. This has all been within the first 150 hours since the top overhaul was completed. The first time was during straight mineral oil and break in whereas the second time was post break-in with							
ashless oil present. It is our recommendation that if this happens again, the mx team replace the regulator for a new part and investigate the oil filter and							
contents completely.							
Note: Risk Assessment Code of 4 or more resets the OFC Safety Clock							
Note: Risk Assessment Code of 5 requires immediate notification of Club President.							
Note: Information identifying any member will be redacted for anonymity. Please provide as much as possible.							
Thank you for your interest in your Safety Program.							

Revision: Initial Date: February 23, 2021