

Oxford Flying Club		
	t Operations Incident	
To: OFC Safety Officer	From:	Date:
Note: Refer to Club website	Note: Name is optional but help	oful.
Type of Event - check all appropriate responses		
☐ Altitude Deviation	☐ Runway/taxiway excur	rsion Foreign Object Damage
☐ Navigational Deviation	☐ Runway Incursion	☐ Severe Wake Turbulence
☐ Communication Error	☐ Severe Turbulence	☐ Collision Hazard
☐ Severe Icing	☐ Aborted Takeoff	✓ Other
2. Weather Conditions - check all appropriate responses		
□ IMC	☐ Thunderstorm	
☑ VMC	☐ Turbulence	□ Crosswind
☐ Precipitation	□ Windshear	☐ Other
3. Time/Date - check or fill out all	1	- Other
Month H Day	Year 202	□ 0400-0759 local time
□ 1200-1559 local time	☐ 1600-1959 local time	□ 2000-2359 local time
4. Mode of Flight	1000-1737 local time	2000-2337 local time
Ramp	□ Climb	□ Descent
☐ Taxi	☐ Cruise	☐ Approach
☐ Takeoff	☐ Holding	✓ Landing
5. Action Taken - check all appro		<u>■ Landing</u>
☐ Performed Emergency Proc.	Declared Emergency	In Flight Engine Shutdown
☐ Followed Checklist		□ In-Flight Engine Shutdown ue □ Divert From Dest, Airport
	Requested Crash/Rescu	•
= reducerd reducer resists.		
6. Safety Officer, or his/her designee, Initial Assessment Probability: occasional Severity: Major		
y.		
Resulting Risk Code: This report is in combination with CSR 2021-004 Resulting in Risk #4 Note: Risk Assessment Code of 5 requires immediate notification of Club President.		
7. Comments or Suggestions (Use additional sheets as necessary)		
Blow a tire on rollout on a XC to INT. performed the landing I thought it was a pretty		
smooth touchdown. On rollout I noticed us veering left so I applied right rudger and asked		
not to fight me on the controls, but he said he masn't. I took over and got us off anto a taximay rive we were pretty close and shut down. A couple pilots were on the field working on their own plane and helped change		
were pretty close and shut down.	A couple pilots were on the f	ield working on their own done and helped change
I the inner tube for us with an old	space tire they had lying	around See attached.
8. Safety Officer, or his/her design	gnee, Investigation summa	ry:
Safety Officer, or his/her designee		Date 4/22/2021
Tracking # (assigned by Safety Officer) OFC-CSR 2021-003		
Summary: A discussion with the members of this scenario don't provide data as to why the tire blew upon		
landing so we shifted the conversation towards the OFC policy of MX and repairs. Both members are now aware that the plane captains and mx officer have to approve of any repairs prior to the		
next flight in an OFC aircraft. This report is in combination with CSR 2021-004 and has resent the clock		
9. Notes		
a) If a NASA form was filed (Strongly Recommended if practical), please attach a copy to this report.		
b) For confidentiality, this form may be delivered to any Safety Committee representative.		
Thank you for your interest in your Safety Program.		

DCR-2019-001 OFC1002 Revision: Initial Date: March 14, 2019