OXFORD FLYING CLUB

MEETING MINUTES

15 Apr 2014

Attendance: Regular: 12 Reg/Student: 2 Associate: 3 Quorum: Yes X No ____

Location: 121 Restaurant Oxford, CT

	Туре	Member	Present
1	Assoc	Aulet, Maximillian	
2	Reg	Baker, Matt	
3	Reg	Bell, Joe	
4	Assoc	Berwick, Ken	
5	Reg	Burmann, Bruce	
6	Assoc	Camejo, Christopher	
7	Reg	Carr, Tim	
8	Reg	Chromczak, Ed	Х
9	Assoc (Honorary)	Dasilva, Domingos	
10	Reg	Delp, Greg	
11	Assoc	Dobbs, Glen	
12	Assoc	Dobbs, Kristi	
13	Reg	Earl, Gavin	
14	Reg	Ebbert, Davis	
15	Reg	Fazio, Mike	
16	Reg	Feeney, Richard	
17	Reg	Feinman, Jason	
18	Assoc	Feinman, Phil	
19	Reg	Green, Geoffrey	
20	Reg	Hansen, Jens	
21	Reg	Heidrich, Don	

Туре	Member	Present
Reg	Hill, Ed	
Med/Assoc	Hill, Jeremy	
Reg	Kit, Volodymyr	
Assoc	Kramer, Tom	
Reg	Kuhsel, Bob	х
Reg	Laine, George	
Reg	Lafosse, Larry	
Assoc	Lyons, Hal	х
Assoc	Moir, Floyd	х
Reg	Monahan, Jay	х
Reg	Morici, John	х
Assoc	Morrow, Bill	
Reg	Mowerman, Illya	
Reg/Stu	Murphy, Mick	
Reg	Nalband, Gary	х
Reg	Noffke, Karl	х
Reg	Oloff, Scott	х
Reg	Palmatier, Bruce	
Reg	Poole, Christopher	
Reg	Poole, Raymond	
Reg	Proulx, Brian	х

Туре	Member	Present
Reg	Pugliese, Jay	
Reg/Stu	Reddy, Mahesh	х
Reg	Richardson, Bruce	
Reg/Stu	Riolo, Jonah	
Reg	Robinson, Andy	
Reg	Rosen, Stewart	
Reg	Rosendahl, Eric	
Assoc	Sabot, Jay	х
Assoc	Schindler, Len	
Reg	Schmecker, Ron	х
Reg/Stu	Shaker, Ed	
Reg	Stevens, Burt	х
Reg	Treanor, Jim	х
Reg	Tremallo, Wayne	
Reg	Trueman, Jeffrey	
Reg	Tyrrel, Chris	
Reg/Stu	Vitagliano, Erik	х
Reg	Wilson, Richard	х
Assoc	Zipkin, David	
<u> </u>		

- Burt S. called the meeting to order at 7:06 PM
- Prospective new member Peter St. Pierre, former member Jerry Posniak attended meeting
- March meeting minutes accepted unanimously

¹ Per By-Laws, quorum = one-third of regular plus non-mentored student members. In the event a quorum is not achieved, or is subsequently lost, the President will determine if a majority of the board is present. If so, then the meeting will become a Board Meeting.

Monthly Reports:

Membership Report: Presented by Ed C. on behalf of Don H.



Membership Report Oxford Flying Club

Don Heidrich, April 2014

Membership Changes since Last Meeting:

Resigned:

- Jens Hanson (returned to Denmark)

Status Change:

- Ron Schmecker Associate to Regular
- Jeff Trueman Student to Regular CONGRATS!

Joined:

_

Current Totals

Regular 40 Student 5 Mentored Student 0

Associate 14 (Includes Dom Dasilva)

Med Associate 1

Total 60

Other Notes:

New Prospects:

- Larry Timpson
- Peter St. Pierre
- Roland Greenwood

Prior Prospects:

- Peter Hill
- Scott Price Flies with Kyle, getting back into flying, attended Safety Day
- Norm Forrester Student, paused for a while, attended Safety Day

- Jeff DiStasio Flew with Barry Lerman, works for Cisco
- John Herman was member of HFD club, hasn't flown in 4 years
- Tom Krasowski owns a Cherokee, working on IFR with Ron, interested after that

Membership Report accepted unanimously.

Additional membership business:

Applications for reinstating former member Jerry Posniak as associate member and Larry Timpson as a new regular member were discussed during the meeting and a motion to approve both Jerry and Larry was presented, all meeting members unanimously approved the motion.

Treasurer's Report: Presented by Mahesh Reddy (see attached).

Mahesh R. wrote:

"The loss shown of \$32k is not a true loss. In fact, there is a YTD profit of about \$11,000. The difference is an expense of \$44,058 recorded as an engine expense. Rightfully this amount should be reversed to E&P Reserve and the value of the aircraft (61H) adjusted accordingly.

The other significant issues to report is the total cost of Engine and Prop overhaul (for 61H) is \$35,111 of which \$11,300 is outstanding and is yet to be paid.

Please feel free to call Mike Fazio or me if you have any questions."

Burt S. mentioned to make every effort to use up our \$329.00 credit we have with Oxford Flight Training.

Treasure's Report accepted unanimously.

MX Report: Presented by Brian Proulx (see attached).

Brian P. wrote:

"A busy month for the maintenance team!

4334X – Pre-buy was completed at Mutual Air in Brookhaven. The plane is in great shape. We found a small list of items that need to be addressed, nothing major. The aircraft logs have been reviewed thoroughly and I have an electronic logbook built for use going forward. You will also see that 4334X has been added to the MX page on the scheduler. Waiting for next steps from the BoD and Finance committee.

61H – Engine replaced, new prop, and annual all within 1 week – Wonderful!. Engine break-in going well, thank you for your patience while we go through these next few weeks. We are close to the end of Phase 2 and will be entering Phase 3. Please refer to the club scheduler News page for a link to the break-in document to see what Phase 3 will entail. The MX team will advise when this occurs. I flew approx. 4.3 hrs. in it over the past two weeks, and this is what is needed. If you have a long flight approaching please consider 61H for that trip. The sooner the break-in is complete, the sooner we can get back to normal ops! I also have an air scoop on order to replace the one that is now broken.

84F – Entering annual with Russell Emmons at MMK. Guestimate of \$2800 plus new tires. Engine oil analysis continues to impress, good numbers across the board.

62Y – 50hr oil change done over the weekend. Found a flat spot on the left main that is now causing some vibration. Will wait a few more weeks before considering replacement, as this is the time of year for notorious crosswind flying at OXC.

NOTE to 182-checked pilots: The dipstick was found unsecure when the cowl was removed for the oil change and oil seepage was found in the engine compartment as a result. Please make sure that the dipstick is not getting caught on the baffle material. The hook at the top of the dipstick comes in contact with the baffle and the O-ring will not seat well unless double checked for positive engagement. The dipstick also has evidence of being bent, please use caution.

819 – Needed to perform an oil change mid-week. Do not check engine oil after a flight. The oil readings will be low as the oil is still in the cylinders and valve area. Doing so and adding oil in a hot engine will lead to a potential overfill scenario. I have a Pitot cover on order to replace the one that went missing last week."

Maintenance Reports accepted unanimously.

<u>Long Range Planning Committee Summary, 4/15/2014</u>: Presented by Ed Chromczak (see attached).

All Category (A) upgrades, except for maintenance have been suspended until further notice, due to pending aircraft purchase/sale/upgrade/overhauls, etc.

- o Category (A): Basic upgrades that make the aircraft better and safer 1 year or less
- o Category (B): Recommended but requiring substantially more resources 1-2 years
- o Category (C): Items to add to wish-list; or a 3-4 year time horizon

The scheduling of the LRP projects have been coordinated with maintenance issues and are on track with the Committee's goals.

Suggested Aircraft Improvements:

 $\underline{62Y}$ (230 hrs/yr; airframe TT 4.8K hrs; engine since MOH 355 hrs; remaining 900 hrs) Install ADS-B in/out collision avoidance avionics [\$6K] (B) LED landing & taxi light upgrade [\$285ea. x 2 = \$570] (C) {repl. lamps should be LED} LRP (A+B+C) Summary: \$6.6K

61H (350 hrs/yr; airframe TT 4.0K hrs; engine since MOH 5 hrs; Upgrade Transponder to Extended Squitter-out collision avoidance [\$1.5K] (A) LRP (A+B+C) Summary: \$29.5K

<u>34X</u> (290 hrs/yr; airframe TT 3.5K hrs; engine since MOH 150 hrs) Engine OH'd 2013 Upgrade Transponder to Extended Squitter-out collision avoidance [\$1.5K] (A) Upgrade ELT to 406 mhz; \$2K (A) Corrosion proofing; \$700 (A)

819 (210 hrs/yr; airframe TT 7.0K hrs; engine since MOH 1700 hrs; remaining 300 hrs) Install co-pilot seat inertia reel [\$1K]; back-ordered via Cessna (B) Upgrade GPS - to 430WAAS [\$3.5K] (B) Install ADS-B in/out collision avoidance avionics [\$6K] (C) Exterior Paint - Consider 2 years from now. [\$18K] (C) LED landing light upgrade [\$285] (C) {replacement lamps should be LED} LRP (A+B+C) Summary: \$27.8K [consider extending paint job by touch-ups]

Three-four year summary of a/c improvements (A+B+C):

LRP upgrades only.]

The above, one per year or earlier, ADS-B installation schedules are considered due to avionics shop scheduling prior to the end of 2019 & available funding.

Safety: Presented by Jay Sabot

FAA Safety seminar at NVCC held on April 8th was a great success.

Jay has lined-up two guest speakers for our Safety Day event:

Jerry Posniak suggested combining our OFC Safety Day event by inviting the American Yankee ???? group to host a more diverse and interesting event. All club members expressed approval for the idea saying it can only make the event better. Jerry will be involved in making this happen if the club choses to accept this idea.

Unfinished Business:

• Pinch Hitter course, Summer 2014 - Mahesh Reddy

This involves 3 hrs. of ground school and 1 hr. in the plane. Mahesh has 3 CFIs lined-up and 14 interested in the program so far. Scott O. volunteered to teach the ground school portion. Mahesh plans on sending a reminder email in early May.

IMC program – John Morici – KMMK at 6pm April 22 (next Tuesday)

John highly suggested attending meeting in Meriden to see if this is something OFC will be interested in starting up.

Jones Beach Air Show & speaker for Spot Landing Event – Jay Sabot

Jay is still looking for more participants to go on this great event. This year the Blue Angels will be flying and they are amazing.

Finance Committee report – Rates

The finance committee plans on presenting their findings and a proposal on club rates at our May meeting so no numbers will be provided here. In lieu of that the topic was discussed informally and there appears to be a rate hike for both membership rates and aircraft hourly rates.

N4334X purchase price \$85k – pre-buy – borrowing \$55k

The club affirmed the purchase price of \$85K is a good value for OFC. All the records and inspections show this plane is in great shape and valued higher.

Brian shared his pre-buy concerns with the members present and requested the following be addressed in the near-term:

- Door loose on hinges The door is sloppy and appears to be the hinge pins. This same repair was made to 84F. While the parts are inexpensive, the door was not properly aligned. This made the door difficult to close. Additional labor hours were needed to make the appropriate adjustments. Estimate up to \$1000 to fix.
- Fuel tank vent wrong orientation and may result in a lower pressure within the tank.
 Estimate up to \$600 to fix.
- Oil pressure indication When engine initially starts the pressure reading is at the top of yellow/red line. Pressure comes down once warmed up but remains at the green/yellow line.

Suspect this is an indication issue and not an engine issue. According to Burt, VIP Maintenance Director Eric Santerre was consulted. Penn Yann indicated this was normal. Brian recommended additional troubleshooting should be performed. No estimate provided.

Mike F. wrote:

"... The purchase will be partially funded from the proceeds of the sale of 84F. Following a rather exhaustive review of our current cash position, it was determined that we should request the membership to loan the club treasury \$55,000. to be used for the purchase of the plane.

We are offering notes of \$5,000 each, to be repaid over a term of five years at an interest rate of 5% per annum. Preference would be given to members who do not have a current outstanding note (for 62Y's purchase). We would also like to limit notes to two notes (\$10,000) per member, if you would have interest in purchasing more than a single \$5,000 note.

As we do want to move this process forward as soon as possible, please contact Burt (<u>bstevens@snet.net</u>) or me if you have any questions. We would like to complete this process by 4/20."

Burt S. mentioned that members should only fly N4334X VFR until they get checked-out on the Aspen avionics package. Brian P. is working on creating a PowerPoint presentation summing up the operating instruction manual.

New Business:

Davis Ebbert has offered to develop a Facebook website for OFC.

Club members feel this could be a good idea to reach more potential members. Let's see what Davis offers.

The club adjourned at 8:17 PM.

Submitted by, Karl Noffke

Document History

Version	Date	Change Reference
1.0	22-Apr-2014	Original release

Oxford Flying Club

Current Financial Status

Balance Sheet

	04/15/14		
Assets			
Cash			\$52,612
Accounts Red	ceivable		\$19,627
- Core Depo:	sit for 61H		\$16,400
	N8261	Н \$82,000	
	N4384	F \$51,000	
	N9881	9 \$45,000	
***************************************	N7362		
Planes - (values	s based on AOPA Vref figures as of 1/1/2013)	· · · · · · · · · · · · · · · · · · ·	\$275,000
		Total Assets:	\$363,639
Liabilities			
Accounts Pay	/ablı(O/S Inv. of approx. \$11k approx 61H not includ	led)	-\$329
Bank Time			\$21,658
Loans	\$36,597		
Engine & Pro	p Reserve* (Not Reduced by 61H Engine)		\$123,457
	To	ntal Liabilities:	\$181,383
		Total Equity:	\$182,256
	Profit & Loss Sto	atement	
		April-14	YTD
Total Incom	me	\$7,157	\$48,281
Expenses		······································	
- 7		Monthly	YTD
N4384F	(When adj. JE is made to reduce	\$90	\$5,068
N8261H -	\$44K for 61H engine Expense, OFC	\$143	\$49,698
N98819	will show a YTD profit of \$11,000)	\$90	\$4,941
N7362Y		\$600	\$8,013
Officers Fly	ing Time	\$760	\$2,850
Fuel & Oil Ex		\$3,938	
Other Expen	ses	\$1,160	\$2,013

Total Expenses:

Net Income:

\$6,782

\$375

\$81,087

(\$32,807)

OFC Maintenance Report Active Issues - April 2014

Open Date	ID#	Issue	Resolution	Scheduled for	Status	Assigne
N4384F						
3/2/2014	993	Dry rot on main tires, Pilot side main has significant flatspot	Replacing at Annual	4/14/2014	Open	Russ
N7362Y						
11/17/2013	967	The non-essential top right side instrument light sometimes function when "tapping" on the top of the instrument panel.			Pending	Club
11/17/2013	966	The airspeed indicator is very difficult to view during night operations because it has a "ring" lighting device installed	Perhaps there may be a "brighter" way to illuminate the ASI. Bring along a "head-lamp" if flying at night.		Pending	Club
N8261H						
4/7/2014	1001	GPS becoming intermittent againneed to watch this	2 separate occasions the GPS lost signal with satellites. Could be interference from electronic devices?		Open	Club
4/1/2014	1000	Kool scoop broken	Will replace		Open	Club
N98819						
2/24/2014	987	Air cleaner bracket broken on co-pilot side			Open	Image
11/17/2013	964	Co-pilot inertia reel install	backordered for weeks.		Open	Image

Monday, April 14, 2014 Page 1 of 1

OFC Maintenance Report Closed Issues - April 2014

Open Date	ID#	Issue	Resolution	Status	Assigned	Close Date
2/1/2014	984	337s needed for all ELTs installed.	Reliant is working on 84F/61H/62Y. Image is working on 819. Resolved by Steve DeSorbo. A&P log entry is sufficient per Steve's FAA Assigned mechanic	Closed	Club	4/1/2014
N4384F						
3/8/2014	998	50hr oil change		Closed	Club	3/8/2014
N7362Y						
4/12/2014	1003	50hr oil change		Closed		4/12/2014
2/24/2014	988	Primary COM radio has static on transmission		Closed	VIP	4/10/2014
N8261H						
3/18/2014	999	Avionics fan inop?	There is no fan in 61H	Closed	Reliant Air	3/26/2014
3/4/2014	996	50hr oil change		Closed	Club	3/6/2014
3/2/2014	995	Prop Overhaul	Will send out for overhaul while in annual. May want to dynamic balance at some point over the summer. Required a new prop.	Closed	Reliant Air	3/26/2014
3/2/2014	994	New OH engine from Lycoming, w/new cylinders	Inspect baffling and engine mounts.	Closed	Reliant Air	3/26/2014

Open Date	ID#	Issue	Resolution	Status	Assigned	Close Date
2/24/2014	992	Rear leather seats cracking on surface	Not sure what to do with this. Poor leather treatment is all. Cant fix what is already damaged.	Closed	Club	3/26/2014
2/24/2014	991	Several places where paint is starting to flake off	Needs touchup	Closed	Reliant Air	3/26/2014
1/16/2014	980	Uneven CYL temps on 61H per ECI	Baffles rebuilt, not seeing this issue since new engine was installed	Closed	Reliant Air	3/26/2014
1/16/2014	979	Condensation on inside windows	Condensation on the inside windows of 61H. Morici stated it was there when he got into the plane and never cleared. Will keep an eye on this as it may have been due to the unusual cold/warm weather and not a water leak. Checked seals, all good	Closed	Reliant Air	3/26/2014
2/1/2013	837	Remove DME from 61H, not needed anymore.	Need new W&B.	Closed	Reliant Air	3/26/2014
N98819						
4/9/2014	1002	Oil change due to MX reasons	Had to change oil prior to 50hrs due to an unforseen issue	Closed	Image	4/9/2014
3/4/2014	997	50hr oil change		Closed	Club	3/6/2014
9/8/2013	921	Loaner transponder installed while ours is bench tested	Spoke with VIP, do not worry	Closed	VIP	3/26/2014

Maintenance Overview											
1981 Piper Archer II - N8261H (28-8190025)											
		April 14, 2014		Eng. TT	7573.1						
				TTAF	4071.2						
Annual Insp & hours to date	3755.24 315.96			SMOH	8.1						
Tachometer Reading	4071.2	50hr Oil Due	2.8	TBO	1991.9	prop	1991.9				
Engine Overhaul (11/30)	2052.9	oil samples	3/6/2014	Hobbs (calc)	4791.8						

Estimated Engine replacement Dec-2020

Maintenance Overview												
1977 Piper Archer II - N4384F (28-7790026)												
		April 10, 2014		Eng. TT	5538.3							
				TTAF	6913.3							
Annual Insp & hours to date	2464.8 221.3			STOH	954.0							
Tachometer Reading	2686.1	50hr Oil Due	21.9	TBO	-329.0	prop	533.1					
Tach at Replacement	4042.0	oil samples	3/8/2014	Hobbs (calc)	8267.6							

Estimated Engine replacement May-2013

Expect to go 500 beyond TBO with new lycoming cylinders installed 8/2010 Nov-2014

	M	aintenance Overview						
	1985 Cessr	76362)						
		April 14, 2014						
				TTAF	7067.0			
Annual Insp & hours to date	6995.8 71.2			SMOH	1750.0			
Tachometer Reading	7067.0	50hr Oil Due	48.0	TBO	250.0	prop	1000.3	
Engine Overhaul	5317.0	Oil Sample	3/6/2014	Hobbs (calc)	8317.9			

Estimated Engine replacement Apr-2015

Maintenance Overview 1977 Cessna R182 - N7362Y (R18200127)										
		April 14, 2014		Eng. TT	4412.9					
				TTAF	4852.4					
Annual Insp & hours to date	4757.90 94.5			SMOH	1175.4	3237.5	overhauled engine hrs			
Tachometer Reading	4852.4	50hr Oil Due	47.6	TBO	824.7					
Engine Overhaul (11/30)	3677.1	oil samples	4/12/2014	Hobbs (calc)	5711.3					
				Prop TBO	1102.6	or 8/2017				

Estimated Engine replacement Jan-2017

Maintenance Overview 1984 Piper Archer II - N4334X (28-8490040)							
		April 2, 2014		Eng. TT	64.0	3rd run case	
				TTAF	3386.4	1736	in service
Annual Insp & hours to date	1533	3		SMOH	64.0		
Tachometer Reading	1536	50hr Oil Due	50.0	TBO	1936.0	prop 1936	
Engine Overhaul (11/30)	2053	oil samples	1/0/1900	Hobbs (calc)	172.7		

Estimated Engine replacement May-2021