# OXFORD FLYING CLUB MEETING MINUTES

## 11 September 2010

Location: Burt & Molly Stevens' Home

Attendance: Regular: 9 Students: 2 Associates: 3 Quorum: Yes X No\_

Туре	Member	Present
Assoc	Aulet, Maximillian	Х
Reg	Berwick, Kent	
Assoc	Camejo, Christopher	
Assoc	Carmona, Brenda	
Reg	Carr, Tim	
Reg	Chromczak, Ed	Х
Reg	Cohen, Ken	
Assoc	Crabtree, Scott	
Reg	Dobbs, Glen	Х
Stu	Dobbs, Kristi	Х
Reg	Feeney, Richard	
Stu	Feinman, Jason	Х
Reg	Goudy, Jim	

Туре	Member	Present
Reg	Green, Geoffrey	
Reg	Heidrich, Don	
Reg	Hill, Jeremy	
Med Assoc	Johnston, Bob	
Reg	Laine, George	
Reg	Leary, John	
Assoc	Morrow, Bill	
Reg	Nalband, Gary	Х
Reg	Noffke, Karl	
Reg	Oloff, Scott	
Reg	Osborne, Tom	
Reg	Palmatier, Bruce	Х
Assoc	Piwowarski, David	

Туре	Member	Present	
Reg	Reg Pozniak, Jerry		
Reg	Proulx, Brian	Х	
Reg	Richardson, Bruce		
Reg	Robinson, Andy	Х	
Assoc	Sabot, Jay	Х	
Reg	Schindler, Leonard		
Assoc	Schmecker, Ron	Х	
Reg	Stevens, Burt	Х	
Reg	Vallillo, Tony		
Assoc	Vecchiarelli, Angelo		
Reg	Wilson, Richard	Х	
Reg	Zipkin, David		

### **Guests:**

Gary N called the meeting to order at 4:00 pm.

August Minutes accepted as written.

**Membership Report:** by Max A.

26 Regular Members

<sup>&</sup>lt;sup>1</sup> Per By-Laws, quorum = one-third of regular plus student members.

- 2 Student Members
- 0 Mentored Students
- 10 Associate Members
- Several prospective members including Army MAJ Jim Patreno who is on assignment with Sikorsky.
- Report accepted unanimously.

#### Treasurer's Report:

•

**MX Report:** Brian presented the following Maintenance Report.

- 61H issues have been addressed and squawks cleared; 84F is in its final phase of the break-in (25hrs left to go); and 819er is in the shop to have the following items addressed (including the 100hr inspection on the seat rails):
- N98819:

545	N98819	Carb Heat Knob not staying in the off position, creaping	Open
552	N98819	2 cowl fasteners missing on pilot side	Open
556	N98819	Need to install a fire extinguisher	Open
561	N98819	Panel light switch next to dome light on the ceiling is inop	Open
562	N98819	Post light to the left of the pilot on side wall is inop	Open
563	N98819	Rheostat for radio lights is not dimming, its either on or off	Open
574	N98819	SAFO - Cessna Seat Stop inspection and 100hr seat rail inspection	Open

- 84F: Please note that SMOH on 84F was zeroed out, but TBO continues as the new cylinders/pistons do not qualify for a change in TBO.
- Please keep an eye out on a new MX procedure regarding the adding of Oil to our planes, and the associated tach hours when the oil was added.

**Safety:** Jay Sabot presented the Safety Report.

Accepted Unanimously.

#### **Unfinished Business:**

• Long Term Planning Committee – Rich Wilson. Held initial meeting and will compile summary.

#### **New Business:**

- We discussed & agreed to pursue a Night Currency evening at the 121 Restaurant in November, as wells as another Grass Landing Strip Event.
- Other subjects which deserve mention for member thought before we get together in October:
  - 1 Nominations for our 2011 election will be due at the October meeting for the election in November
  - o 2 Bruce Richardson will begin to pull together the plans / thought for the Christmas Party.
  - o 3 We agreed to include a review of the a/c booking rules in October.

Meeting adjourned 4:07 pm.

Respectfully submitted,

Bruce T. Palmatier