OXFORD FLYING CLUB MEETING MINUTES

20 July 2010

Location: 121 Restaurant

Attendance: Regular: 11 Students: 1 Associates: 3 Quorum: 1 Yes X No _

Туре	Member	Present	
Assoc	Aulet, Maximillian	Χ	
Reg	Berwick, Kent	Χ	
Assoc	Camejo, Christopher		
Assoc	Carmona, Brenda		
Reg	Carr, Tim		
Reg	Chromczak, Ed		
Reg	Cohen, Ken		
Assoc	Crabtree, Scott		
Reg	Dobbs, Glen	Χ	
Stu	Dobbs, Christi	Х	
Reg	Feeney, Richard		
Reg	Goudy, Jim		
Reg	Green, Geoffrey		

Type Member		Present
Reg	Heidrich, Don	Х
Assoc	Hill, Jeremy	
Reg	Johnston, Bob	
Reg	Laine, George	
Reg	Leary, John	
Assoc	Morrow, Bill	
Reg	Nalband, Gary	Х
Reg	Noffke, Karl	Χ
Reg	Oloff, Scott	
Reg	Osborne, Tom	
Reg	Palmatier, Bruce	Χ
Assoc	Piwowarski, David	
Assoc	Pozniak, Jerry	

Туре	Member	Present	
Reg	Proulx, Brian	Χ	
Reg	Richardson, Bruce		
Reg	Robinson, Andy		
Assoc	Sabot, Jay	Χ	
Reg	Schindler, Leonard	Χ	
Assoc	Schmecker, Ron	Χ	
Reg	Stevens, Burt	Х	
Reg	Vallillo, Tony	Χ	
Assoc	Vecchiarelli, Angelo		
Assoc	Whitney, Mike		
Reg	Wilson, Richard	Х	

Gary N called the meeting to order at 7:05 pm.

June Minutes accepted as written.

Membership Report: by Max A.,

- 24 Regular Members
- 1 Student Members
- 0 Mentored Students
- 12 Associate Members
- See Unfinished business for Safety Day recap.

¹ Per By-Laws, quorum = one-third of regular plus student members.

Report accepted unanimously.

Treasurer's Report:

- Report emailed prior to meeting and hard copy submitted by Burt S. Please see enclosure.
- Accepted Unanimously.

MX Report: Brian presented the following Maintenance Report.

Mx Report highlights:

61H:

- The squealing from the engine compartment reported last week was due to a loose Alternator belt. When pre-flighting the aircraft, you should be checking the alternator belt for flex. It should move about ½ inch, anything more indicates a loose or damaged belt.
- Brian has calls into VIP regarding intermittent COM1 radio issues. May be related to something that was missed years ago at the pre-buy, the 530 was built for a 28V airplane, not 14V as are the archers. This is why the MSG indicator comes on when transmitting. Discussed several options for addressing the 14v versus 28v issue. At the conclusion of the discussion, it was moved and seconded to authorize Brian to spend up to \$2500 (net) to replace the 530 Garmin with a 14v system. Approved unanimously.
- Brian changed the oil with Classic last week.

84F:

- Should look into refinishing the seats, sharp metal sticking out of the Pilot headrest.
- Currently looking for a side step to replace the broken one. It will be cheaper than trying to re-weld the current one.

819:

- Club changed the oil last month.
- Few minor issues that need addressing.
- Interior is beginning to show its age and exposure to the sun.
- Corrosion becoming apparent on the airframe and will need to be addressed soon.
- This airplane will need another \$6-7K put into it over the next few months.
- Honeywell/KLN-89B VFR GPS has been acting up. Every once and a while it will
 plot a course to OXC and be way off on its measurements. This has been
 identified by the FAA as a software glitch and Honeywell is not repairing it.
 Please use caution when using the GPS and I recommend backing up the GPS
 with VOR Navaids. Bruce will send the Club the KLN advisory.

Open issues as of 20 July 2010:

OFC Maintenance Report Active Issues - July 2010

Open Date	ID#	Issue	Resolution	Scheduled for	Status	Assigned
N4384F						
7/11/2010	558	Step broken	Working on getting a used step.	7/25/2010	Open	Reliant Air
9/14/2009	506	Hand mic mount seems to be unsecure, possibly broken plastic			Open	Club
N8261H						
4/20/2010	542	Wet Baggage compartment			Open	Classic Air
4/21/2009	473	Flap handle interfereing with the plastic bezel	Replacing the Bezel.		Open	Reliant Air
N98819						
7/1/2010	556	Need to install a fire extinguisher			Open	Reliant Air
6/23/2010	554	Fuel tanks indicating erroroneous data	I will address this issue at th	е	Open	Club
6/23/2010	552	2 cowl fasteners missing on pilot side	will need to order new		Open	Classic Air
5/5/2010	545	Carb Heat Knob not staying in the off position, creaping			Open	Classic Air

Safety: Jay Sabot presented the Safety Report.

- Reviewed Currency Matrix as of June—"the offenders."
- Accepted Unanimously.

Unfinished Business:

- Safety Day Recap & Review
 - o Presented Tony (The Voice) Vallillo for his role in a great Safety Day Presentation about flying the Hudson SFRA (Corridor).
 - o Burt also received award on the day of the presentation.
 - Great job by all!
 - o Will relook location and logisitics for next year's Safety Day.

- Long Term Planning Committee Rich Wilson. Nothing yet.
- Complex lease back opportunity follow-up. Shelved indefinitely since we have decided to hold on to 819.
- Summer Picnic Rescheduled for weekend after Labor Day, 11 Sep with Rain Date of 18 Sep.
- Fall Club event. Several ideas floated. Candlewood grass landings appears to have some "traction."

New Business:

• "Active" maintenance officer. Currently have two maintenance assistants, Bruce R, whose focus is 84F, and Jim G, whose focus is 819. Brian P, in addition to overseeing all maintenance, focuses on 61H.

Meeting adjourned 8:15 pm.

Respectfully submitted,

Bruce T. Palmatier

Enclosure

Oxford Flying Club

Current Financial Status

Balance Sheet

07/19/10

	0//19/10		
Assets			
Cash			\$55,391
Accounts Reco	eivables		\$19,507
	N8261H	\$99,209	
	N4384F		
		\$66,000	
Planes	N98819	\$43,000	\$208,209
			Ψ200,207
	7	Total Assets:	\$283,107
Liabilities			
Accounts Payo	able		-\$628
Bank Time			\$11,821
Loans			\$12,580
Engine & Prop	Reserve		\$49,996
	Total	al Liabilities:	\$73,769
		Total Equity:	\$209,338
	Profit & Loss Stat	ement	
		June-10	УTD
Total Incon	1e	\$10,996	\$59,992
Expenses	(Note: 61H Trans - \$5k)	Monthly	УТЬ
N4384F	Includes Annual in 4/10 @ \$2327	\$2,846	\$10,508
N8261H	Includes Annual in 4/10 @ \$3062	\$7,708	\$18,978
N98819	No Annual yet - Due in 11/10	\$1,939	\$5,701
Officers Flyir	ng Time	\$570	\$3,753
Other Expens		\$65	\$627
	Total Expenses:	\$11,771	\$39,567
	Net Income:	(\$2,132)	\$20,425