

Oxford Flying Club									
Name of Reporting Member					on:		Date Reported:		
Note: Optional and will be redacted.	Note: Optional and will be redaction						, Date Nepol	ieu.	
	r)	
1. Date of Event: Local Time (24hi				ppr	ox okay	y):	1900		
2. Type of Event - check all appropriate responses									
Aborted Takeoff	Foreign Object Damage				Collision Hazard				
Abnormal Landing	1	Weather					Hazard		
Hangar Safety	Maintenance Issue/Discrepancy				Other (Please add description)				
3. Weather Conditions - check all appropriate responses									
☐ IMC or VMC		Thunderstorm			Icing				
Cold/Heat Related		Turbulence			Crosswind				
Precipitation		Windshear			Other (Please add description)				
4. Phase of Operation - check all appropriate responses									
Ramp/Hangar Area		Takeoff			Descent				
Preflight		Climb			Approach				
Taxi-Out	✓ Enroute				Landing				
5. Pilot Action - check all appropriate responses									
Declared Emergency	~	✓ Trouble Shooting In Flight			Diverted From Planned Dest.				
Emergency Checklist		Trouble Shooting On Ground			Requested Medical Assist.				
Requested Crash/Rescue		NASA Report Filed			Aircra	Aircraft Grounded			
Contact Airport Manager				Ļ	Other (Please add description)				
6. Comments or Suggestions: Is additional information attached: No									
Reporting Member Summary: Small piece of window (approx 8" diameter) broke off from pilot side window when student was attempting to close the window. Positive control of the aircraft was maintained and flight operations were unaffected aside from turning up the radio volume slightly. Flight was discontinued and the maintenance coordinator was immediately notified. Window crack in the affected area had been noted during preflight and deemed airworthy. The crack had been previously squawked on 6/1/21 with a note from maintenance saying it was safe to fly and will be repaired soon.									
7. Name of Safety Officer or Des	Date Reviewed:								
Probability: - 2 Severity: - 2			Investigation Summary Attached: -No						
Resulting Risk Code: -1			Assigned Tracking # CSR 2021-009						
Committee Summary:									
The committee reviewed the damage and can't conclude whether the air scoop was in or out of the storm window. The area around and aft of the storm window was broken and departed the aircraft. We believe the scenario is unlikely to happen often and the risk to safety is low. We recommend pilots understand the storm window is permitted use in-flight; however, the air scoop is strictly forbidden from use in flight or at speeds above taxi.									
Note: Risk Assessment Code of 4 or more resets the OFC Safety Clock									
Note: Risk Assessment Code of 5 requires immediate notification of Club President.									
Note: Information identifying any member will be redacted for anonymity. Please provide as much as possible.									
Thank you for your interest in your Safety Program.									

Revision: Initial Date: February 23, 2021