


This example Bios was already updated to J61 V01.23

Attempting to update to 3.96 where it failed.

Need to update ME to V8 first.






USB drive formatted to FAT32 and reduced in size to 512Mb as recommended.


Only the .bin file on the thumb drive.

Entered the Bios at boot









Different number of beeps from server, fans ramp up.

All attempts for crisis recovery failed.

Recovered via manually changing .bin file and flashing the bios chip on the mother board.