

1. Property Issue Summary

Inspection Report: Internal and External Dampness, Seepage Issues in Various Areas Detected

2. Area-wise Observations

Area: Hall & Bedroom Skirting Levels

Observation: Significant dampness indicating a possible moisture intrusion or lack of proper waterproofing, particularly in the hall and bedrooms.

Thermal: None

Area: External Wall Crack

Observation: Observed crack on external wall which may contribute to structural weaknesses or moisture ingress issues.

Thermal: None

3. Probable Root Cause

Structural vulnerabilities and possible waterproofing failures leading to damp areas in walls and cracks on external wall.
Lack of structural repairs or maintenance.

4. Severity Assessment

High

5. Recommended Actions

Immediate rectification for any detected moisture ingress, sealing the skirting level cracks with appropriate waterproofing materials; assess and repair all external wall defects. A comprehensive structural evaluation should be conducted to understand underlying issues.

6. Additional Notes

None

7. Missing or Unclear Information

Thermal report data

