REV 0.3
BUGFIX: LCD RW must be set to GND
BUGFIX: ESP32 cannot supply enough current for Relay, added Q1
Moved RFID card to the right to avoid overlap with DEFAULTS button
Changed large caps to 0805 footprints
Replaced variable resistor with more common footprint
Added components values
Added Input protections with fuses
USB tracks rerouted to avoid pads breaking the data lines
Add large cap for LCD power

