
(a) Sensor loss (schematic)
(b) Measurement noise
simulated
with noise, σ = 0.01 p.u.
fault starts
voltage (p.u.)
time step (ms)
1.2
1.1
1.0
0.9
0.8
0
25
50
(c) Unseen resistance
no training resistances in this range
deepest sag (p.u.)
0.8
0.6
0.4
0.2
0.0
0.1
1
10
fault resistance (Ω)
median and range of 50 runs