## **3D Scanner Program Flow Diagram**

By: Pat Maynard, Kevin McClintock

## Python HMI - Raspberry Pi or USB PC

• Note: Threads must be used to avoid blocking the UI Process and freezing the UI





