

F1736 Standalone Benchmark Reassessment: Case 3: Rectangular Notched Plate with Hole and Pins
(Physical Geometry: [0.0, 65.0] × [0.0, 120.0] mm, $\ell_0 = 0.285$ mm)


(a) Original Coarse Mesh
3923 elements (97.2% Q) | 4039 nodes



(b) Authoritative Adapted Mesh
12110 elements (96.7% Q) | 12217 nodes



(c) Spatial Resolution h_e/ℓ_0 (Capped at 3.0)
$h \le \ell_0$: 16.5% count (1.3% area) | $h_{\min} = 80.36\,\mu$m



(d) Process-Zone & Propagation Path Evaluation
Secondary Crack Corridor Insufficiently Resolved

