
Rotational speed [rpm] <= 1386.5
gini = 0.5
samples = 8000
value = [4000.0, 4000.0]
class = No Failure
True
False
Air temperature [K] <= 301.55
gini = 0.283
samples = 1220
value = [539.268, 2627.306]
class = Failure
Tool wear [min] <= 204.5
gini = 0.407
samples = 6780
value = [3460.732, 1372.694]
class = No Failure
Torque [Nm] <= 60.05
gini = 0.422
samples = 923
value = [441.972, 1018.45]
class = Failure
Process temperature [K] <= 312.25
gini = 0.108
samples = 297
value = [97.296, 1608.856]
class = Failure
Torque [Nm] <= 15.4
gini = 0.284
samples = 6395
value = [3285.807, 678.967]
class = No Failure
Torque [Nm] <= 45.25
gini = 0.322
samples = 385
value = [174.926, 693.727]
class = Failure
Tool wear [min] <= 188.5
gini = 0.495
samples = 789
value = [396.947, 324.723]
class = No Failure
Torque [Nm] <= 65.0
gini = 0.114
samples = 134
value = [45.025, 693.727]
class = Failure
Rotational speed [rpm] <= 1380.5
gini = 0.079
samples = 226
value = [64.174, 1505.535]
class = Failure
Torque [Nm] <= 56.7
gini = 0.368
samples = 71
value = [33.122, 103.321]
class = Failure
Torque [Nm] <= 13.45
gini = 0.078
samples = 53
value = [15.008, 354.244]
class = Failure
Torque [Nm] <= 57.05
gini = 0.164
samples = 6342
value = [3270.798, 324.723]
class = No Failure
Torque [Nm] <= 41.35
gini = 0.397
samples = 316
value = [149.567, 398.524]
class = Failure
Tool wear [min] <= 206.5
gini = 0.146
samples = 69
value = [25.359, 295.203]
class = Failure
Air temperature [K] <= 295.55
gini = 0.0
samples = 695
value = [359.684, 0.0]
class = No Failure
Type_L <= 0.5
gini = 0.185
samples = 94
value = [37.262, 324.723]
class = Failure
Tool wear [min] <= 175.0
gini = 0.235
samples = 69
value = [41.92, 265.683]
class = Failure
Process temperature [K] <= 311.8
gini = 0.014
samples = 35
value = [3.105, 428.044]
class = Failure
Process temperature [K] <= 310.55
gini = 0.065
samples = 200
value = [51.753, 1476.015]
class = Failure
Tool wear [min] <= 137.5
gini = 0.417
samples = 26
value = [12.421, 29.52]
class = Failure
Process temperature [K] <= 312.35
gini = 0.0
samples = 50
value = [25.877, 0.0]
class = No Failure
Tool wear [min] <= 91.0
gini = 0.122
samples = 21
value = [7.245, 103.321]
class = Failure
Air temperature [K] <= 304.05
gini = 0.013
samples = 26
value = [2.07, 324.723]
class = Failure
Rotational speed [rpm] <= 2287.0
gini = 0.424
samples = 27
value = [12.938, 29.52]
class = Failure
Tool wear [min] <= 202.5
gini = 0.06
samples = 6293
value = [3253.202, 103.321]
class = No Failure
Rotational speed [rpm] <= 1389.5
gini = 0.136
samples = 49
value = [17.596, 221.402]
class = Failure
Tool wear [min] <= 234.5
gini = 0.362
samples = 257
value = [119.55, 383.764]
class = Failure
Torque [Nm] <= 44.2
gini = 0.442
samples = 59
value = [30.017, 14.76]
class = No Failure
Rotational speed [rpm] <= 1392.5
gini = 0.109
samples = 55
value = [18.114, 295.203]
class = Failure
gini = 0.0
samples = 1
value = [0.518, 0.0]
class = No Failure
gini = 0.0
samples = 694
value = [359.167, 0.0]
class = No Failure
gini = 0.0
samples = 31
value = [16.043, 0.0]
class = No Failure
gini = 0.115
samples = 63
value = [21.219, 324.723]
class = Failure
gini = 0.457
samples = 83
value = [40.367, 73.801]
class = Failure
gini = 0.016
samples = 16
value = [1.553, 191.882]
class = Failure
gini = 0.012
samples = 34
value = [2.588, 428.044]
class = Failure
gini = -0.0
samples = 1
value = [0.518, 0.0]
class = No Failure
gini = 0.004
samples = 40
value = [1.035, 560.886]
class = Failure
gini = 0.1
samples = 160
value = [50.718, 915.129]
class = Failure
gini = 0.0
samples = 18
value = [9.316, 0.0]
class = No Failure
gini = 0.172
samples = 8
value = [3.105, 29.52]
class = Failure
gini = 0.0
samples = 44
value = [4.14, 0.0]
class = No Failure
gini = 0.0
samples = 6
value = [21.736, 0.0]
class = No Failure
gini = 0.0
samples = 6
value = [3.105, 0.0]
class = No Failure
gini = 0.074
samples = 15
value = [4.14, 103.321]
class = Failure
gini = 0.009
samples = 25
value = [1.553, 324.723]
class = Failure
gini = -0.0
samples = 1
value = [0.518, 0.0]
class = No Failure
gini = 0.095
samples = 5
value = [1.553, 29.52]
class = Failure
gini = -0.0
samples = 22
value = [11.386, 0.0]
class = No Failure
gini = 0.052
samples = 6238
value = [3225.256, 88.561]
class = No Failure
gini = 0.452
samples = 55
value = [27.947, 14.76]
class = No Failure
gini = 0.0
samples = 4
value = [2.07, 0.0]
class = No Failure
gini = 0.122
samples = 45
value = [15.526, 221.402]
class = Failure
gini = 0.354
samples = 247
value = [114.374, 383.764]
class = Failure
gini = -0.0
samples = 10
value = [5.175, 0.0]
class = No Failure
gini = 0.0
samples = 48
value = [24.842, 0.0]
class = No Failure
gini = 0.384
samples = 11
value = [5.175, 14.76]
class = Failure
gini = 0.0
samples = 14
value = [7.245, 0.0]
class = No Failure
gini = 0.109
samples = 55
value = [18.114, 295.203]
class = Failure
gini = 0.0
samples = 4
value = [2.07, 0.0]
class = No Failure
gini = 0.098
samples = 51
value = [16.043, 295.203]
class = Failure