CT-200 conveyor Configuration A

Document CT200-A | Revision 1 | Issued 1 November 2025 | Archived copy

1. Applicability

Applies only to CT-200 configuration A. This copy is retained for equipment still using configuration A and for historical maintenance records. It does not cover machines upgraded to configuration B. Check the installed equipment record before using a parts reference.

2. Motor overload

An overload report is a reason to investigate, not confirmation of motor failure. Mechanical resistance and motor-related problems can have similar reported symptoms. Follow the applicable site maintenance process; this fictional extract supplies no electrical settings or detailed repair steps.

3. Roller assembly

Configuration A uses underside return roller assembly RA-200A, including bearings. This reference is not valid for configuration B. Similar part names do not establish interchangeability.

4. Procedure boundary

Physical work and restart require authorised site staff and the site's approved procedures. Refer to current site policy for responsibilities. An archived document does not override current safety requirements.