Maintenance job closeout

WO-604 | Filling area | 15 Oct 2026

Equipment: feed pump (P21). Setup tag: H2.

Call from production

Transfer to the filler slowed during batch 61. Operator heard rattling near the inlet.

Fitter entry

Product residue found on the inlet strainer. No impeller inspection recorded.

Cleaned the strainer and refitted the cover seal. No replacement part booked.

Handover / closure

Flow recovered during a ten-minute water run. Product run deferred until next shift.

Assigned: R. Lim | Time booked: 35 min | Follow-up: product trial outstanding

Exported 18 Oct 2026. Attachment 1 of 2.

Fitter's continuation sheet

16 October 2026 - late shift - WO-611

Called to the rinse pump. Equipment tag field left empty.

Wet patch at the return pump coupling after rinse cycle. Drip continued after wipe-down.

Possibly the cover seal; source of the leak not confirmed.

Work done: none entered. Stores request sent for identification of the seal kit.

Outcome: blank. Day shift to inspect. Configuration field: blank.

Unrelated stores note: two empty chemical drums awaiting collection.

Exported 18 Oct 2026. Attachment 2 of 2.