

ACTIVITY SOLUTION:

CONDITIONS FOR SUCCESSFUL JIT IMPLEMENTATION:

- COMMITMENT OF THE TOP MANAGEMENT
- CONSIDERABLE FINANCIAL OUTLAY IS REQUIRED DURING THE EARLY STAGES

YOUR ORGANIZATION MAY FACE SOME PRODUCTION LOSS AND CHANGES TO MANAGEMENT PROCEDURES

TRUST AND COMMITMENT BETWEEN THE SUPPLIER AND THE CUSTOMER NEEDS TO BE BUILT UP

ACTIVITY SOLUTION:

7 HIGH-LEVEL STEPS TO MAKE JIT IMPLEMENTATION SUCCESSFUL:

STABILIZE AND LEVEL
THE MASTER
PRODUCTION
SCHEDULE

REDUCE OR ELIMINATE SETUP TIMES

REDUCE LOT SIZES (MANUFACTURING AND PURCHASE)

REDUCE LEAD TIMES (PRODUCTION AND DELIVERY)

PREVENTIVE MAINTENANCE

CREATE A FLEXIBLE WORKFORCE

REQUIRE SUPPLIER
QUALITY ASSURANCE
AND IMPLEMENT A
ZERO DEFECT QUALITY
PROGRAM

STABILIZE & LEVEL THE MASTER PRODUCTION SCHEDULE AIGPE

A MASTER PRODUCTION SCHEDULE (MPS) IS A SCHEDULE SHOWING WEEK BY WEEK THE QUANTITY OF EACH PRODUCT THAT MUST BE PRODUCED ACCORDING TO CUSTOMER ORDERS AND DEMAND FORECAST

WORK CENTERS SHOULD BE UNIFORMLY LOADED THROUGH CONSTANT DAILY PRODUCTION

REDUCE OR ELIMINATE SETUP TIMES

SETUP TIMES SHOULD BE REDUCED BY SEPARATING INTERNAL AND EXTERNAL ACTIVITIES

A "ONE-TOUCH" SETUP CAN BE DEVELOPED WITH THE HELP OF BETTER PLANNING, PROCESS REDESIGN, AND PRODUCT REDESIGN

REDUCE LOT SIZES (MANUFACTURING AND PURCHASE)

REDUCTION IN SETUP TIMES ALLOWS ECONOMICAL PRODUCTION OF SMALLER LOTS

CLOSE COOPERATION WITH SUPPLIERS IS NECESSARY TO ACHIEVE REDUCTIONS IN ORDER LOT SIZES FOR PURCHASED ITEMS

JIT REQUIRES MORE FREQUENT DELIVERIES

REDUCE LEAD TIMES (PRODUCTION AND DELIVERY)

PRODUCTION LEAD TIMES CAN BE REDUCED BY:

- MOVING WORKSTATIONS CLOSER
- APPLYING GROUP TECHNOLOGY AND CELLULAR MANUFACTURING CONCEPTS
- REDUCING QUEUE LENGTH
- IMPROVING THE COORDINATION AND COOPERATION BETWEEN SUCCESSIVE PROCESSES

DELIVERY LEAD TIMES CAN BE REDUCED THROUGH:

- CLOSE COOPERATION WITH SUPPLIERS
- INDUCING SUPPLIERS TO LOCATE CLOSER TO THE FACTORY

USE IDLE TIME FOR PREVENTIVE MAINTENANCE

IDLE TIME OF MACHINES AND WORKERS SHOULD BE USED TO:

- MAINTAIN EQUIPMENT AND
- PREVENT BREAKDOWNS

CREATE A FLEXIBLE WORKFORCE

WORKERS SHOULD BE TRAINED TO:

- OPERATE SEVERAL MACHINES
- PERFORM MAINTENANCE TASKS AND
- PERFORM QUALITY INSPECTIONS

THE ATTITUDE OF RESPECT FOR PEOPLE LEADS TO GIVING WORKERS MORE RESPONSIBILITY FOR THEIR WORK

SUPPLIER QUALITY ASSURANCE & ZERO DEFECTS

ERRORS LEADING TO DEFECTIVE ITEMS MUST BE ELIMINATED QUALITY AT THE SOURCE PROGRAM MUST BE IMPLEMENTED TO:

- GIVE WORKERS THE RESPONSIBILITY FOR THE QUALITY OF THEIR WORK
- AUTHORITY TO STOP PRODUCTION WHEN SOMETHING GOES WRONG