

BMW X5 xDrive40i 2023 Owner's Handbook

Model Year: 2023 | Make: BMW | Model: X5

Table of Contents

1. Engine - B58 3.0L Turbocharged
2. iDrive & Digital Systems
3. xDrive AWD System

Engine - B58 3.0L Turbocharged

The B58 inline-6 requires BMW Longlife-04 approved 0W-30 or 5W-30 synthetic oil. BMW Condition Based Service (CBS) monitors oil quality and alerts when a change is required (typically 10,000-15,000 miles).

Boost pressure nominal: 18.1 psi. Fault P0299 (Turbocharger Underboost) indicates a boost leak - common failure points are the charge pipe between the turbo and intercooler.

iDrive & Digital Systems

The BMW Live Cockpit Professional runs BMW OS 7.0. System updates are delivered OTA (Over The Air).

If the iDrive system freezes, hold the volume knob for 30 seconds to perform a hard reset.

U-codes (U0001, U0100) indicate CAN bus communication failures. These often accompany a dead 12V auxiliary battery - replace with a BMW-approved AGM battery (92Ah, Group H8).

xDrive AWD System

The xDrive all-wheel drive system continuously varies torque split between front and rear axles.

Normal rear bias is 40% front / 60% rear. Under wheelspin the system can send 100% torque to either axle.

Fault B2AAA indicates xDrive transfer case motor failure. Do not engage Sport+ mode if this fault is active.