

1	231	Looking out. 注意
2	429	Affirm RVSM. 可以 RVSM
3	117	Request taxi. 请求滑行
4	237	Squawk ident. 应答机识别
5	368	Negative RNAV. 不能 RNAV 进近
6	128	Runway vacated. 已退出跑道
7	238	Squawk standby. 应答机待机模式
8	285	Negative ADS-B. 没有 ADS-B
9	114	Brakes released. 刹车松开
10	273	Request vectors. 请求引导
11	437	CPDLC connected. CPDLC 已连接
12	151	Holding position. 原地等待
13	213	Request de-icing. 请求除冰
14	1	Maintaining FL310. 保持高度层 310
15	218	Request backtrack. 请求 180 度掉头
16	281	Transponder Charlie. 应答机 C 模式
17	282	Transponder unserviceable. 应答机故障
18	306	Runway in sight. 跑道可见
19	602	Unable, TCAS RA. 不同意, TCAC RA 激活
20	232	Traffic in sight. 飞机可见
21	65	No delay expected. 预计无延误
22	107	Stand by pushback. 推出稍等
23	69	Ready for approach. 准备进近
24	101	You are unreadable. 无法听见你的声音
25	217	Request time check. 请求校正时间
26	381	Wilco, words twice. 照办, 发送两次

27	115	Starting Number One. 启动一发
28	135	Ready for departure. 准备起飞
29	264	Resume normal speed. 恢复正常速度
30	180	Request low approach. 请求低空进场
31	308	Passing outer marker. 通过外指点标
32	8	Request further climb. 请求进一步上升
33	55	Omit position reports. 省略位置报告
34	152	Stopping! Engine fire. 停止！发动机起火
35	265	No speed restrictions. 无速度限制
36	356	Remain this frequency. 在该频率保持
37	361	Request RNAV approach. 请求 RNAV 进近
38	36	Maintain present speed. 保持当前速度
39	116	Brakes set, disconnect. 刹车刹住，断开
40	240	Stopping squawk Charlie. 关闭应答机 C 模式
41	287	Stop ADS-B transmission. 停止 ADS-B 发话
42	311	Request visual approach. 请求目视进近
43	50	Request frequency change. 请求转换频率
44	224	Continue present heading. 继续当前航向
45	57	Resume position reporting. 恢复位置报告
46	315	Request holding procedure. 请求等待程序
47	226	Confirm identification lost. 证实识别丢失
48	313	Request holding instructions. 请求等待指令
49	220	Request departure instruction. 请求离场指令
50	280	Advise transponder capability. 告知应答机可用模式
51	100	I read you 5. 我听你信号 5 个
52	103	How do you read? 你听我声音怎样？
53	102	Can you speak slower? 你能说慢点吗

54	230	Orbit left for delay. 左转以推延
55	433	Ready to resume RVSM. 准备恢复 RVSM
56	171	Make a short approach. 做一个小航线进近
57	229	Three sixty turn left. 左转 360 度
58	153	Request return to ramp. 请求返回机坪
59	169	Orbit right. Number Two. 右转一圈, 第二个
60	183	Wind shear, going around. 风切变, 复飞
61	233	Negative contact due IMC. 由于仪表气象条件, 看不见
62	234	Traffic passed and clear. 冲突飞机以通过无影响
63	338	Increasing rate of climb. 增加爬升率
64	367	RAIM alert, going around. RAIM 警告, 复飞了
65	124	Holding, traffic in sight. 等待, 飞机可见
66	108	Pushback at own discretion. 推出时间自己决定
67	432	Unable RVSM due turbulence. 由于颠簸 RVSM 不可用
68	139	Ready for immediate departure. 准备立即起飞
69	140	Cleared for immediate takeoff. 可以立即起飞
70	111	Pushback approved, facing west. 可以推出, 面朝西
71	880	Negative contact due visibility. 由于能见度低, 看不见
72	109	Pushback approved, long pushback. 可以退推出, 多推一点
73	192	Confirm PAPI light unserviceable. 证实坡度指示器不工作
74	215	De-icing completed. Request taxi. 除冰完成, 请求滑行
75	379	Roger, request continue approach. 收到, 请求继续进近
76	235	Squawk 7563. 应答机 7563
77	297	Passing FL70. 通过高度层 70
78	3	Reaching FL190. 到达高度层 190
79	247	Fly heading 285. 飞行航向 285
80	236	Reset squawk 5101. 重置应答机 5105

81	241	Affirm squawk 7500. 确认应答机 7500
82	2	Descending to FL290. 下降到高度层 290
83	309	Report MQR outbound. MQR 背台报告
84	355	Monitor Tower 118.1. 守听塔台频率 118.1
85	242	Altimeter 1003 8000ft. 高度表 1003, 高度 8000 英尺
86	222	Contact Arrival 118.050. 联系进场频率 118.050
87	333	Descend immediately FL250. 立即下降到高度层 250
88	269	Next report at IP. 下一报告点 IP
89	54	Next report at WXA. 下一报告点 WXA
90	138	Lining up Runway 01C. 进入 01C 跑道
91	246	Leave BK heading 190. 离开 BK 航向 190
92	99	Radio check on 118.3. 无线电检查 118.3
93	245	Turn right 20 degrees. 右转 20 度
94	248	Stop turn heading 070. 停止转向航向 070
95	202	Confirm RVR Runway 27. 证实跑道 27 的跑道视程
96	11	Stop descent at FL210. 在 210 高度层停止下降
97	275	Request 15 miles final. 请求五边 15 英里
98	244	Turn right heading 340. 右转航向 340
99	6	Passing FL180 for FL310. 通过高度层 180, 上升到高度层 310
100	351	Expect descent after AK. 预计过 AK 后下降
101	93	Bay24, request start-up. 停机位 24, 请求开车
102	21	Expedite climb to FL190. 加速上升到高度层 190
103	411	Leaving FL220 for FL190. 离开高度层 220, 下降到高度层 190
104	52	Contact Control on 118.9. 联系区调 118.9
105	4	Maintaining FL90 over WXJ. 过 WXJ 时保持高度层 90
106	63	Expected approach time 44. 预计进近时间 44 分
107	253	Indicated speed 270 knots. 指示空速 270 节

108	20	Expedite descent to FL180. 加速下降到高度层 180
109	304	Fully established Runway 24. 完全建立跑道 24
110	303	Established on the localizer. 已建立航向道
111	239	Squawk Charlie and code 5120. 应答机 C 模式, 编码 5120
112	292	Heading 120, correction, 140. 航向 120, 更正, 航向 140
113	387	Maintaining FL310 until advised. 保持高度层 310, 等指示
114	410	Descending immediately to FL190. 立刻下降到高度层 190
115	184	Going around, localizer fluctuation. 复飞, 航向道波动
116	286	Re-enter ADS-B aircraft identification. 重新输入 ADS-B 飞机识别码
117	881	Unable, we are in IMC. 不同意, 我们在仪表气象条件
118	61	Revised slot time at 56. 修改离场时间为 56 分
119	123	Hold short of Runway 24. 24 号跑道外等待
120	260	Do not exceed 280 knots. 速度不要超过 280 节
121	127	Crossing Runway 24, wilco. 穿越跑道 24, 照办
122	854	Unable to comply, TCAS RA. 不能照办, 有 TCAS RA 指示
123	349	Stop descent at 5000 feet. 在 5000 停止下降
124	261	Reduce speed to 240 knots. 减速到 240 节
125	72	Leave JFK VOR heading 210. 离开 JFK VOR 航向 210
126	436	At 144E(east), squawk 2000. 东经 144 度, 应答机 2000
127	105	Stand 27, request pushback. 停机位 27, 请求推出
128	174	Runway 27, cleared to land. 跑道 27, 可以落地
129	254	Maintain 300 knots or less. 保持 300 节或更小
130	263	Increase speed by 10 knots. 速度增加 10 节
131	173	Continue approach Runway 25. 继续进近, 跑道 25
132	225	Resume own navigation to BK. 恢复自主领航至 BK
133	319	Leaving BKM VOR heading 110. 离开 BKM VOR, 航向 110
134	417	Request VMC descent to FL60. 请求目视条件下降到高度层 60

135	106	Pushback approved, Runway 31. 同意推出，跑道 31
136	166	Number Two, traffic in sight. 第二个，看见飞机了
137	897	Standby, high pilot workload. 稍等，飞行员工作负荷大
138	94	Start up approved, QNH 29.91. 可以开车，QNH29.91
139	405	Report 25 miles from BKM VOR. 距离 BKM VOR 台 25mile 报告
140	38	Reduce to minimum clean speed. 减速到最小净空速
141	172	Long final, airfield in sight. 长五边，机场可见
142	499	We have an electrical failure. 我们电气故障了
143	37	Maintain 250 knots or greater. 保持 250 节或更大
144	90	Say again the initial altitude. 再说一遍初始爬升高度
145	110	Pushback to taxiway A approved. 可以推出至滑行道 A
146	366	GPS primary lost, going around. 失去 GPS 主用，复飞了
147	268	Omit position reports until LN. 省略位置报告直到 LN
148	250	Confirm danger area 113 active. 证实危险区域 113 有活动
149	175	Short final, request wind check. 短五边，请求风向风速
150	288	Stop squawk transmit ADS-B only. 停止应答机，只使用 ADS-B 发话
151	896	Transmission blocked, say again. 发话被干扰，再说一遍
152	47	Request join downwind Runway 31. 请求加入三边，跑道 31
153	249	Request heading 180 due weather. 由于天气，请求航向 180
154	307	Number One, contact Tower 118.7. 第一个，联系塔台 118.7
155	402	Estimating crossing LV NDB 1123. 预计在 1123 分飞越 LV NDB
156	205	Confirm stop-end RVR 150 meters. 证实停止端跑道视程 150m
157	39	Reduce to minimum approach speed. 减小到最小进近速度
158	270	Report required only at boundary. 只要求在交接点报告
159	339	Unable expedite climb due weight. 不能加速爬升，因为重量
160	354	Request change to London Control. 请求转换至伦敦管制频率
161	427	Confirm radar control is resumed. 证实雷达管制恢复

162	26	Leaving FL200, climbing to FL280. 离开高度层 200, 上升到高度层 280
163	70	Request leave the holding pattern. 请求离开等待程序
164	64	Revised expected approach time 54. 修改预计进近时间 54 分
165	312	Cleared visual approach Runway 24. 可以目视进近, 跑道 24
166	353	Contact Control 80 miles after BK. 过 BK80mile 后联系区调
167	187	After vacated contact Ground 121.6. 脱离跑道后, 联系地面 121.6
168	407	Report crossing 270 radial BKM VOR. 过 BKM VOR 台 270 径向线报告
169	113	Ground, Cockpit. Ready for pushback. 地面管制, 驾驶舱, 准备推出
170	425	Confirm radar service is terminated. 证实雷达服务终止
171	137	Cancel SID, maintain runway heading. 取消标准离场程序, 保持跑道航向
172	164	Join right-hand downwind, Runway 34. 加入右起落三边, 跑道 24
173	350	Expedite descent until passing FL80. 加速下降直到通过高度层 80
174	431	Request clearance into RVSM airspace. 请求加入 RVSM 的许可
175	464	Request further climb due wind-shear. 由于风切变请求进一步爬升
176	207	Confirm threshold Runway 27 displaced. 证实 27 号跑道入口内移
177	430	Negative RVSM due equipment downgraded. 由于设备降级, 不可使用 RVSM
178	167	Straight-in visual approach, Runway 34. 直接目视进近, 跑道 34
179	826	Terrorists started to injure passengers. 恐怖分子开始伤害乘客
180	200	Confirm visibility more than 1000 meters. 证实能见度大于 1000m
181	284	ADS-B receiver 1090 (ten-ninety) data link. ADS-B 接收机 1090 数据链
182	449	Our pressurization system has malfunctioned. 我们的增压系统已故障
183	178	Landing clearance canceled. Continue approach. 取消落地许可, 继续进近
184	283	ADS-B transmitter 1090 (ten-ninety) data link. ADS-B 发射机 1090 数据链
185	155	Negative intersection departure due performance. 由于性能限制, 不能在交叉口起飞
186	310	Procedure turn completed, localizer established. 程序转弯已完成, 并建立好航向道
187	635	GPS unreliable, terminating ADS-B transmissions. GPS 不可靠, 终止 ADSB 发话
188	191	Confirm centerline taxiway lighting unserviceable. 证实滑行道中线灯不工作

189	92	Destination Beijing, request departure information. 目的地北京, 请求离场信息
190	258	Cross CK at 35 or later. 穿越 CK 在 35 分或以后
191	96	Start up at 35, QNH 997. 开车时间 35, QNH 997
192	189	Taxi to the end of Runway. 滑行至跑道末端
193	259	Cross DG at 24 or earlier. 在 24 分或 24 分之前穿越 DG
194	201	Is mid-point RVR available? 请求中点跑道视程
195	203	RVR Runway 27 is 600 meters. 27 号跑道的跑道视程是 600m
196	144	The airbus on final in sight. 看见五边上的空客
197	194	Flock of birds 3 miles final. 五边 3 英里处有鸟群
198	88	Say again all after 3000 feet. 3000 英尺后的内容再说一次
199	296	Direct to JO, descend to FL50. 直飞 JO, 下降到高度层 50
200	35	Maintain Mach point 80 or less. 保持马赫数 0.80 或更小
201	325	Three sixty turn left for delay. 右转一圈, 以推延
202	15	Descend at 2000 feet per minute. 以 2000 英尺每分钟的下降率下降
203	33	Reduce speed to Mach decimal 76. 减速到马赫数 0.76
204	419	Request join airway A1 at DAPRO. 请求在 DAPRO 加入航路 A1
205	216	Request start engine at the gate. 请求在停机位开车
206	451	We have a cabin altitude problem. 我们座舱高度有问题
207	331	Descend to reach 5000 feet by BK. BK 点之前下降到高度 5000 英尺
208	12	Descending to reach FL150 by WXI. 到 WXI 前下降到高度层 150
209	181	Runway not in sight, going around. 跑道不可见, 复飞
210	34	Maintain Mach point 84 or greater. 保持马赫数 0.84 或更大
211	10	After passing CGO descend to FL80. 过 CGO 后下降到高度层 180
212	424	Confirm we are under radar control. 证实我们在雷达管制区
213	330	Cleared to JEMMY via BK 1A Arrival. 可以经由 BK—1A 去往 JEMMY
214	363	Cleared for LDA approach Runway 24. 可以 LDA 进近, 跑道 24
215	23	Unable to expedite climb due weight. 由于重量原因不能加速爬升

216	182	No contact at minimum, going around. 决断高不可见跑道，复飞
217	170	Number Two, follow airbus 320 ahead. 第二个，跟着前面的空客 320
218	278	Confirm ILS frequency for Runway 17L. 证实 17 左跑道盲降频率
219	409	Climb to FL220, report passing FL170. 上升到高度层 220，通过高度层 170 报告
220	149	Take off immediately or vacate runway. 立刻起飞，或退出跑道
221	530	We are having flight control problems. 我们有飞行操纵问题
222	142	Cleared for takeoff, Runway 06, wilco. 可以起飞，跑道 06，照办
223	359	Expect commencing approach at time 50. 预计开始进近时间 50 分
224	41	Maintain 160 knots until outer marker. 保持 160 节直到外指点标
225	328	QNH1003, threshold elevation 196 feet. QNH1003，跑道入口标高 196 英尺
226	49	Request taxi to south maintenance ramp. 请求滑行道南边的维护机坪
227	157	Request intersection departure from C2. 请求从交叉口 C2 起飞
228	439	SELCAL CODE EFFG, request SELCAL check. 选择呼叫代码 EFFC，请求选呼检查
229	125	Cross Runway 24, report runway vacated. 穿越跑道 24，退出跑道报告
230	267	Request speed 250 knots due turbulence. 由于颠簸，请求速度 250 节
231	5	Continue descent to 3000 feet, QNH 1012. 继续下降到高度 3000 英尺，QNH1012
232	56	Omit position reports on this frequency. 本频率省略位置报告
233	345	Unable FL390 by boundary, request FL330. 交接点之前不能到达高度层 390，请求高度层 330
234	59	Approach time not determined due weather. 由于天气原因，进近时间待定
235	89	Say again all before departure frequency. 离场频率前的内容再说一次
236	853	Request right turn for traffic avoidance. 请求右转避让航空器
237	879	Unable to expedite climb due performance. 由于性能，不能加速爬升
238	120	Request taxi back for maintenance purpose. 请求滑回，以进行维护
239	154	Tire burst, possible evacuation on runway. 爆胎，可能需要在跑道上撤离
240	197	Is the weather improving or deteriorating? 天气在好转还是恶化？
241	378	Disregard. We made the wrong transmission. 作废，发话错误
242	883	Unable noise abatement due company policy. 由于公司政策，不能使用降噪程序

243	28	Reaching 8000 feet, request further climb. 到达 8000 英尺，请求进一步爬升
244	266	Request speed 200 knots due configuration. 由于构型问题，请求速度 200 节
245	301	Airfield in sight, request visual approach. 机场可见，请求目视进近
246	299	Request straight-in ILS approach Runway 24. 请求直接盲降进近，跑道 24
247	95	Start up approved, altimeter setting 29.91. 可以开车，高度表设定值 29.91（英寸汞柱）
248	58	Delay not determined due runway obstruction. 由于跑道障碍物，延误待定
249	24	Descending immediately to FL200 due traffic. 由于冲突的飞机，立即下降到高度 200
250	112	Cancel pushback, we have maintenance problem. 取消推出，我们出现问题需要维护
251	223	Request remote apron for maintenance purpose. 请求在远机坪进行维护
252	484	Our operations manual forbids this procedure. 我们的运行手册禁止该程序
253	243	Negative squawk ident due transponder failure. 由于应答机失效，无法识别应答机
254	441	The air conditioning system has malfunctioned. 空调系统故障
255	340	Climb to 6000 feet, follow KODAP 01 Departure. 爬升到 6000 英尺，按照 KODAP01 号标准离场程序
256	856	Clear of conflict, request further instructions. 冲突已脱离，请求下一步指令
257	382	Maintaining FL350, expect descent after BKM VOR. 保持 35000 英尺，预计在 BKM VOR 台之后下降
258	31	Icing condition encountered. Request further climb. 遭遇结冰，请求进一步爬升
259	30	Experiencing icing condition. Request further descent. 遭遇结冰，请求进一步下降
260	32	Experiencing severe turbulence. Request further descent. 遭遇严重颠簸，请求进一步下降
261	104	QNH 997, I say again, QNH 997. QNH997，我再说一次，QNH997
262	188	Taxi to Stand 27 via Taxiway A. 经由滑行道 A 滑行至 27 停机位
263	97	Expect start up at 35, QNH 1030. 预计开车时间 35，QNH1030
264	344	Climb to FL290, level at time 55. 爬升到高度层 290,55 分改平飞
265	9	Fly direct to SHA, not below FL180. 直飞 SHA，不低于高度层 180
266	212	Tow approved via A to remote apron. 同意经滑行道 A 拖至远机坪
267	321	Position 10 miles north east of LN. 位置 LN 东北 10mile
268	322	Turn right heading 180 for base leg. 右转航向 180 加入四边
269	406	Report 34 miles from Top of Descent. 距离下降顶点 34mile 报告

270	133	Taxi to holding point C3, Runway 36. 滑行至 36 号跑道 C3 等待点
271	391	Affirm, cross BKM VOR at or before 55 同意, 在 55 分或之前, 穿越 BKM
272	165	Number Two, follow airbus 330 on base. 第二个, 跟着四边的空客 330
273	179	Behind the Boeing737, cleared to land. 在波音 737 后, 可以落地
274	214	Request frost removal only at the gate. 请求只在停机位除霜
275	262	Increase speed to 300 knots or greater. 增速到 300 节或更大
276	40	Maintain 160 knots until 4 miles final. 保持 160 节直到五边四英里
277	408	Report 28 miles DME 210 radial BKM VOR. BKM VOR 210 度径向线 28mile 报告
278	389	Affirm, cross BKM VOR at or above FL190 同意, 在高度层 190 或以上穿越 BKM VOR
279	48	Request taxi to holding point Runway 13. 请求滑行至 13 号跑道等待点
280	334	Descend to altitude 12000 feet QNH 1000. 下降到高度 12000 英尺, QNH1000
281	422	If FL240 not available, we accept FL220. 如果高度层 240 不可用, 我们可以接受高度层 220
282	380	Stand by. We are carrying out procedures. 稍等, 我们正在执行程序
283	227	Identified, position 50 miles east of BK. 已识别, 位置 BK 以东 50 英里
284	143	Airborne, passing 500 feet for 4000 feet. 离地, 正通过 500 英尺, 爬升至 4000 英尺
285	199	Confirm current RVR less than 400 meters. 证实当前跑道视程少于 400m
286	60	Slot time not determined due flow control. 由于流控, 离场时间待定
287	348	We are far above profile. Request holding. 我们高于下降程序, 请求等待
288	466	We cannot make RNP approach due equipment. 由于设备原因, 我们无法使用 RNP 进近
289	473	The flight path is unstable. Going around. 飞行轨迹不稳定, 复飞了
290	375	Cleared for CAT IIILS approach Runway 24. 准许二类盲降进近跑道 24
291	206	Confirm midpoint RVR more than 550 meters. 证实中间段跑道视程大于 550m
292	163	Airbus 330 heavy, 8000 feet, Information X. 空客 330, 重型机, 8000 英尺, 通波 X 收到
293	291	Right heading 120, my own terrain clearance. 右转航向 120, 自行避让地形
294	347	After passing North Cross, descend to FL150. 过了 North Cross, 下降到高度层 150
295	22	Climb to FL280 expedite until passing FL180. 上升到高度层 180, 加速直到通过高度层 180
296	147	Request right turn when airborne due weather. 由于天气, 离地后请求右转

297	209	Confirm the reason for our flight suspension. 证实航班暂停原因
298	341	Passing altitude 2300 feet, climbing to FL80. 通过高度 2300 英尺，爬升到 8000 英尺
299	415	Request to leave controlled airspace by climb. 请求通过爬升离开管制空域，
300	438	Continue CPDLC make position report via CPDLC. 继续 CPDLC，由 CPDLC 做位置报告
301	545	We are leaking fuel slowly. Request diversion. 我们正慢速漏油，请求改航。
302	895	Unable CAT II approach due crew qualification. 由于机组资质，不能使用二类进近
303	190	Confirm construction work adjacent to Gate 37. 证实 37 停机位附近正在施工
304	204	Confirm touchdown RVR greater than 350 meters. 证实接地点跑道视程大于 350m
305	390	Negative, unable to cross BKM VOR below FL170. 不同意，飞越 BKM VOR 不能低于高度层 170
306	211	Confirm the reason for impounding our aircraft. 证实扣押我们飞机的原因
307	324	No ATC speed restrictions. Contact Tower 118.9. 无管制速度限制，联系塔台 118.9
308	320	Leaving FL60, descending to 2500 feet, QNH1008. 离开高度层 60，下降到 2500 英尺，QNH1008
309	414	Request to leave controlled airspace by descent. 请求通过下降离开管制空域
310	791	Is the preceding aircraft crossing our altitude? 前机正穿越我们的高度吗？
311	141	Runway 06, cleared for takeoff. Report airborne. 跑道 06，可以起飞，升空报
312	228	30 miles from touchdown, contact Approach 118.1. 距离接地点 30 英里，联系进近 118.1
313	274	Unable to receive transmission on that frequency. 在那个频率无法收到发话
314	463	Our FMS has malfunctioned. Request radar vectors. 飞行管理系统故障，请求雷达引导
315	276	Maintain 3000 feet until glide path interception. 保持 3000 英尺，直到切入下滑道
316	337	Maintain own separation and VMC, descend to FL50. 自己保持间隔和目视气象条件，下降到高度层 50
317	377	Continue approach, prepare for possible go around. 继续进近，做好可能复飞的准备
318	318	Overhead YV, maintaining 3000 feet, entering hold. 飞越 YV，保持 3000 英尺，进入等待
319	196	Confirm airport rescue and fire facilities category. 证实机场救援以及防火设施的类别
320	290	Unable identify the way-point, request radar vectors. 不能识别此航路点，请求雷达引导
321	376	Join right hand downwind, visual approach Runway 24. 加入右起落三边，目视进近跑道 24

322	122	Approaching holding point, request crossing Runway 24. 靠近等待点, 请求穿越跑道 24
323	219	Unable BK-1A Departure due performance. Request BK-1B. 由于性能原因, 不能 BK-1A 离场, 请求 BK-1B
324	612	Our instruments indicate excessive high cabin altitude. 仪表显示座舱高度过高
325	27	Maintaining own separation and VMC, descending to FL80. 保持自己间隔, 和目视气象条件, 下降到高度层 80
326	364	Unable RNAV due equipment, request conventional arrival. 由于设备, 不能 RNAV 进近, 请求常规进场
327	195	Runway covered with patches of water, braking action medium. 跑道覆盖积水, 刹车效应中等
328	158	Request Take-offRunway Available (TORA) from intersection C2. 请求从 C2 起飞的可用起飞滑跑长度
329	613	Our instrument indicates abnormal cabin pressure differential. 仪表显示有不正常的座舱压差
330	160	Request Take-offDistance Available(TODA) from intersection E3. 请求从 E3 进跑道的可用起飞距离
331	14	Climbing to FL290, to be level by 55. 上升到高度层 290,55 分前改平飞
332	492	We are receiving an ELT signal on 121.5. 我们正在 121.5 频率接收一个紧急定位发射机信号
333	346	Descend to FL100, cross YU FL150 or above. 下降到高度层 100 英尺, 穿越 YU 在高度层 150 或以上
334	357	We can see the approach lights at 200 feet. 在 200 英尺我们能看到进近灯
335	17	When ready, descend to FL210, level at PLT. 准备好时下降到高度层 210, 在 PTL 改平飞
336	16	Climbing at 1000 feet per minute or greater. 以 1000 英尺每分钟或更大的爬升率上升
337	145	Behind Airbus on short final, line up behind. 在短五边的空客后, 进跑道
338	148	Take off immediately or hold short of runway. 立即起飞, 或在跑到外等待
339	289	Fly no further west of your current position. 当前位置不要再往西飞了
340	704	We are on emergency descent due severe icing. 由于严重积冰, 我们正紧急下降
341	162	Taxi via A2, backtrack and line-up Runway 18. 经 A2 滑行, 180 度掉头进入跑道 18
342	13	Unable to reach FL150by ZHO due performance. 由于性能原因, 到 ZHO 前不能到达高度层 150
343	562	Our left engine failed due to fuel starvation. 由于燃油不足, 我们左发失效
344	684	We have an engine oil leak. Request diversion. 我们有一个发动机漏油了, 请求备降

345	130	Follow the greens to holding point Runway 05R. 沿着绿灯滑行至等待点 跑道 05 右
346	365	Unable RNAV, loss of RAIM, request NDB approach 由于 RAIM 丢失, 不能 RNAV 进近, 请求 NDB 进近
347	893	We had to overshoot because of wake turbulence. 由于尾流, 我们不得不复飞
348	19	Descend to 3000 feet, information P is current. 下降到 3000 英尺, 现在的通波是 P
349	279	In case of going around, turn left heading 210. 如复飞, 左转航向 210
350	208	The runway surface is damp. Braking action good. 跑道表面潮湿, 刹车效应好
351	833	What do the bomb-disposal experts suggest we do? 拆弹专家建议我们怎么做?
352	860	Some passengers have been scalded by hot drinks. 一些乘客被热饮料烫伤了
353	255	Maintain 180 knots until 8 miles from touchdown. 保持 180 节直到离接地点 8 英里
354	400	Clear of weather, request to resume flight route. 已绕飞天气, 请求恢复计划航路
355	168	Extend downwind, Number Two, airbus 320 in sight. 延长三边, 第二个, 空客 320 可见
356	335	Descend to height 2000 feet QFE 997 hectopascals. 下降到场高 2000 英尺, QFE997 百帕
357	42	Descend to FL120, on speed conversion, 250 knots. 下降到 120, 速度转换至 250 节
358	25	When ready, climb to FL280, report leaving FL200. 准备好时上升到高度层 280, 离开高度层 200 时报告
359	882	Unable, we are only authorized during daytime VMC. 不能够, 我们只具备在白天使用目视气象条件的资格
360	257	Maintain speed 280 knots or greater for separation. 保持速度 280 节或更大以调整间隔
361	332	When ready, descend to FL200. Report leaving FL300. 准备好时, 下降到高度层 200, 离开高度层 300 报告
362	738	Roger heavy rain. Request to terminate our approach. 收到, 暴雨, 请求终止进近
363	176	Request low pass due unsafe landing gear indication. 由于不安全起落架指示, 请求低空通场
364	7	Cleared to enter controlled airspace not above FL100. 可以进入管制空域, 但不高于高度层 100
365	450	We have difficulty in controlling the cabin pressure. 我们控制座舱压力困难
366	156	Affirm. We can accept intersection departure from C2. 同意, 我们能接受从交叉口 C2 起飞
367	256	Maintain Mach decimal 82, transition speed 310 knots. 保持马赫数 0.82, 转换速度 310 节

368	485	Our Aviation Authority does not permit this procedure. 我们航空当局不允许该程序
369	136	A^er departure, climb straight ahead until 3000 feet. 起飞后直线爬升直到 3000 英尺
370	186	Take first right. When vacated, contact Ground 118.35. 第一个路口右转, 脱离跑道后, 联系地面 118.35
371	498	Sorry for blocking the frequency due to microphone jammed. 抱歉占用此频率, 话筒故障了
372	603	We are clear of conflict. Request further instructions. 我们已脱离冲突, 请求进一步指令
373	888	Request runway change for departure due to high crosswind. 由于大侧风, 请求换跑道起飞
374	43	Cancel speed restriction, continue descent to 7000 feet. 取消速度限制, 继续下降到 7000 英尺
375	489	All stations, transmitting blind due to receiver failure. 所有各台, 由于接收机失效, 盲发
376	758	There is an obstruction ahead. Confirm taxi instructions. 前方有障碍物, 证实滑行指令
377	132	After landing Airbus 320, cross Runway 24, report vacated. 空客 320 落地后, 穿越跑道 24, 脱离后报告
378	878	Confirm we have enough separation from preceding aircraft. 证实我们与前机有足够的间隔
379	44	LMN-02 Departure, passing 2500 feet climbing to 9000 feet. LMN-02 离场, 通过 2500 英尺, 爬升到 9000 英尺
380	465	Unable to maintain altitude, request leaving RVSM airspace. 无法保持高度, 请求离开 RVSM 空域
381	847	The conflicting traffic is military. Request avoiding action. 冲突飞机是军用机, 请求避让措施
382	327	Surveillance radar approach Runway 27, maintaining 2200 feet. 监视雷达进近, 跑道 27, 保持 2200 英尺
383	440	CPDLC unserviceable, request to revert to voice communication. CPDLC 不工作, 请求恢复语音通信
384	702	We are encountering moderate icing. Request immediate descent. 我们正遭遇中度结冰, 请求立即下降
385	360	Unable circling approach due to company policy. Request diversion. 由于公司政策, 不能盘旋进近, 请求改航
386	789	Unable circling approach due to company policy. Request diversion. 由于公司政策, 无法盘旋进近, 请求备降
387	45	Maintaining FL350, cleared to destination, flight planned route. 保持高度层 350, 准许飞往目的地, 飞行计划航路
388	159	Request Accelerate-Stop Distance Available (ASDA) from intersection D1. 请求交叉口 D1 的加速停止可用距离
389	590	We made the go around due to GPS error. 我们复飞了是因为 GPS 误差
390	592	We made the go around due to CDU failure. 我们复飞是因为 CDU 故障
391	343	Climb to FL 210, cross AU at FL100 or below.

		爬升到高度层 210, 穿越 AU 时在高度层 100 或不低于
392	900	We had to go around due to unstable approach. 我们必须复飞是因为进近不稳定
393	118	Taxi via taxiway C to holding point Runway 24. 经由滑行道 C 滑行至 24 跑道等待点
394	129	Giving way to B747 passing from left to right. 给从左向右穿过的 747 让路
395	493	We are picking up a broadcast signal on 121.5. 我们在 121.5 里提取到一个广播信号
396	193	The Runway light is too bright. Request dim it. 跑道灯太亮, 请求调暗
397	566	We have shut down one of the hydraulic systems. 我们已经关断了一个液压系统
398	121	Negative. We need 10 minutes to cool the brakes. 不行, 我们需要 10 分钟冷却刹车
399	710	We made the go around due to wind-shear warning. 我们复飞是由于风切变警告
400	177	Low pass approved Runway 27, not below 500 feet. 同意低空通场, 跑道 27, 不低于 500 英尺
401	392	Negative, unable to cross BKM VOR at 43 or later. 不同意, 不能在 43 分或之后穿越 BKM VOR
402	119	Taxi to holding point Runway 24, traffic in sight. 滑行至 24 跑道等待点, 飞机可见
403	62	Expect hold at HUR VOR for 10 minutes due traffic. 由冲突, 预计在 HUR VOR 等待 10 分钟
404	388	Descend to FL170, cross BKM VOR at or above FL210. 下降到高度层 170, 在高度层 210 或以上穿越 BKM VOR
405	394	Request lose time en route to finish the checklist. 请求在航路上消耗时间以完成检查单
406	683	We aborted takeoff due loss of engine oil pressure. 由于发动机失去了滑油压力, 我们中断起飞了
407	840	We have navigation map drift. Request climb to MEA. 我们有导航地图漂移, 请求爬升到最低航路高度
408	86	Gate15, information C, ready to copy ATC clearance. 停机位 15, 通波代码 C, 准备抄收放行许可
409	46	Request radar vectors for visual approach Runway 22. 请求雷达引导, 目视进近, 跑道 22
410	564	We suspect there is contamination in our fuel tanks. 我们怀疑油箱燃油污染
411	51	15NM to HBR, FL290, tracking to JMU, squawking 6543. 距离 HBR15nm, 高度层 290, 直飞 JMU, 应答机编码 6543
412	462	There are unusual noises coming from the avionics bay. 电子设备舱出现异常噪音
413	458	We have a problem with the avionics ventilation system. 我们的电子通风系统有问题
414	889	Request delay the approach due tail wind beyond limits. 由于顺风超出限制, 请求推迟进近

415	126	Unable to vacate via A2, request full length of runway. 不能经由滑行道 A2 退出跑道, 请求全长跑道
416	91	Unable to cross LX FL150 due weight, maintaining FL130. 由于重量原因, 不能在高度层 150 穿越 LX, 保持高度层 130
417	846	We almost had a mid-air collision with another aircraft. 我们差一点与另一架飞机空中相撞了
418	77	Gate 26, request clearance to London with information F. 停机位 26 号, 请求去伦敦的放行许可, 通波 F
419	834	The cabin crew reports a passenger is behaving strangely. 乘务员报告说有乘客举止怪异
420	385	Continue climb to FL 290, cross BKM VOR not above FL 230. 继续爬升到高度层 290, 穿越 BKM VOR 不高于高度层 230
421	677	The windshield is cracked on the outside. Request descent. 风挡外部裂开了, 请求下降
422	150	Hold position, cancel takeoff, I say again, cancel takeoff. 原地等待, 取消起飞, 我再说一次, 取消起飞
423	294	Confirm we are still above your minimum vectoring altitude. 证实我们仍然高于你们的最低引导高度
424	706	Rime ice was reported by previous aircraft during approach. 进近过程中, 前机报告说有毛冰
425	824	Some of the hijackers are carrying sharp protruding weapons. 一些劫机犯携带着尖锐的锋利的武器
426	830	A suspicious suitcase was found during the cabin inspection. 客舱检查过程中发现了可疑的手提箱
427	395	Request parallel offset from current track due weather ahead. 由于前方天气, 请求平行偏离当前航迹
428	565	One of our hydraulic systems has exceeded temperature limits. 我们的一个液压系统超过温度限制
429	629	We have errors with our navigation. Request radar monitoring. 我们的导航有误差, 申请雷达监控
430	611	Cabin altitude is increasing abnormally. Request to level off. 座舱高度异常增高, 请求改平飞
431	453	We have a slow cabin decompression. Request immediate descent. 我们出现缓慢失压, 请求立即下降
432	624	Request diversion to a nearby airport with foaming capability. 申请备降到就近能够喷洒防火泡沫的机场
433	849	The conflicting traffic is gray, possibly a military aircraft. 冲突飞机是灰色的, 可能是军用飞机
434	131	Cross red stop-bar at A1, we understand stop-bar unserviceable. 在 A1 穿越红色停止灯, 我们已了解停止灯不工作
435	496	Our data-link has malfunctioned. Request ATC clearance by voice. 我们的数据链故障了, 申请语音发布放行许可
436	788	Unable visual approach due company policy. Request radar vectors. 由于公司政策, 无法目视进近, 请求雷达引导
437	662	CPDLC has malfunctioned. We are reverting to voice communication. CPDLC 已故障, 我们正恢复语音通信
438	342	Climb to FL210, level restrictions of KODAP01 Departure canceled. 爬升到高度层 210, 取消 KODAP-01 号标准离场程序的高度限制
439	664	CPDLC terminated due to failure, reverting to voice communication.

		由于故障, CPDLC 终止, 恢复话音通信
440	890	Request holding instructions due weather near the runway threshold. 由于跑道入口附近天气, 请求等待指令
441	421	Remain outside controlled airspace, expect further clearance at 55. 保持在管制空域外, 预计下一步许可时间 55 分
442	326	Continue present heading, expect through the localizer for spacing. 继续当前航向, 预计穿越航向道, 以调整间隔
443	596	Our landing capability has degraded. Request terminate our approach. 我们的着陆能力降级, 申请终止进近
444	370	Request hold for weather improvement, visibility below company minima. 请求等待天气好转, 能见度低于公司最低标准
445	859	Some passengers were injured because their seatbelts weren't fastened. 一些旅客受伤了, 因为他们没有系紧安全带
446	66	Delay not determined, numerous aircraft holding for weather improvement 延误待定, 大量飞机等待天气好转.
447	588	We made the go around due to FMS position error. 我们复飞是因为飞行管理系统位置误差
448	398	Cleared offset 25 miles left of track for 30 minutes. 可以左偏离航迹 25 英里飞 30 分钟
449	474	We made a missed approach due to unstable ILS signals. 由于盲降信号不稳定, 我们执行了复飞
450	514	We have had a bird strike. Our windshield has cracked. 我们遭遇鸟击, 风挡碎裂
451	774	We have a suspicious bag on board. Request bomb squad. 机上有可疑的包, 请求拆弹小组
452	790	Are we being vectored too close to the parallel aircraft? 有架飞机平行飞行, 我们是不是被雷达引导过近了?
453	543	Some of our fuel pumps have low pressure. Request descent. 一些燃油泵压力低, 请求下降。
454	591	We made the go around due to lateral deviation exceedance. 我们复飞是因为横向偏差超出限制
455	775	The passengers are evacuating. The bomb is still on board. 乘客正在撤离, 炸弹还在飞机上
456	374	Request extended holding to burn fuel to reduce the weight. 请求延长等待以消耗燃油减轻重量
457	587	We made the go around due to navigation accuracy downgrade. 由于导航精度降低, 我们复飞了
458	416	Descending to 5000 feet QNH 1014, report passing 7000 feet. 下降到 5000 英尺, 修正海压 1014, 通过 7000 英尺报告
459	397	Proceed offset 10 miles right of track until abeam BKM VOR. 右偏航迹 10mile 直到正切 BKM VOR
460	497	My apologies, I wasn't aware the boom mike was transmitting. 抱歉, 我没有意识到吊挂式话筒正在发话
461	757	There are red lights ahead of us. Confirm taxi instructions. 前方有红色灯, 证实滑行指令
462	399	Offset canceled, turn right to rejoin the A1 before BKM VOR. 偏航取消, 在到达 BKM 之前, 右转重新加入 A1 航路
463	302	When established on the localizer, descend on the glide path. 建立好航向道后, 沿下滑道下降

464	277	NOTAM says glide slope for Runway15 is unserviceable, confirm. 飞行员通告表明跑道 15 下滑道故障，证实
465	76	Information P received, stand 03, ready to copy ATC clearance. 通波 P 已收到，停机位 03 号，准备抄收放行许可
466	298	Descending to 4000 feet QNH1005, expect ILS approach Runway24. 下降到 4000 英尺，QNH1005，预计盲降进近，跑道 24
467	610	We are reading high engine vibration. Request to delay takeoff. 发动机抖动显示读数高，请求推迟起飞
468	885	Is there a frequency change at this compulsory reporting point? 在这个强制报告点有没有频率转换？
469	606	Our engine parameters are unstable. Request stop climb at FL220. 我们的发动机参数不稳定，请求在高度层 220 停止下降
470	640	Our airspeed is unreliable. Request radar vectors for long final. 我们的空速显示不可靠，请求雷达引导到长五边
471	783	Request a large airspace to maneuver due flight control problems. 由于飞行操纵出现问题，请求大空域机动
472	386	Negative, unable cross BKM VOR at or above FL230 due performance. 不同意，由于性能原因，不能在高度层 230 或以上穿越 BKM VOR
473	461	We have severe vibration coming from the avionics ventilation fan. 我们的电子通风扇严重抖动
474	594	We no longer have altitude warning. Request leaving RVSM airspace. 我们不再具有高度警告，请求离开 RVSM 空域
475	362	RNAV approach not available due FMS database. Request VOR approach. 由于 FMS 数据库原因，RNAV 进近不可用，请求 VOR 进近
476	828	Terrorists are threatening to start killing passengers and the crew. 恐怖分子正威胁说要开始杀害乘客和机组人员
477	305	Cleared VOR-DME approach Runway 24, descending to 3000 feet QNH1007. 可以 VOR-DME 进近，跑道 24，下降到 3000 英尺，QNH1007
478	185	Follow the standard missed approach procedure, climbing to 3000 feet. 按照标准复飞程序，爬升至 3000 英尺
479	210	Confirm our flight has been suspended due bio-hazards at destination. 证实我们航班暂停是由于目的地机场生物泄露
480	570	Two of our hydraulic systems have failed. Request immediate diversion. 我们有两套液压系统失效，请求改航
481	373	Request to extend the holding pattern for accomplishing the checklist. 请求延长等待程序以完成检查单
482	634	ADS-B equipment degradation, will advise when able to resume operations. ADSB 设备降级，当能够恢复运行时将告知
483	413	Remain outside controlled airspace, expect joining clearance attime 55. 保持在管制空域外，预计在 55 分许可加入
484	875	A crew member is incapacitated. Request diversion and medical assistance. 一名机组人员失能了，请求备降和医疗援助
485	491	Our SELCAL has malfunctioned. We will continue monitoring your frequency. 我们的选择呼叫系统失效，我们将继续守听你的频率
486	221	When airborne, track extended center-line, cleared for takeoff, Runway 18. 离地后，按照跑道中心延长线，可以起飞，跑道 18
487	721	We have encountered severe clear airturbulence. Request immediate descent. 我们遭遇了严重晴空颠簸，请求立即下降

488	652	Many passengers have suffered from smoke inhalation. Request medical services. 许多乘客遭遇烟雾吸入，请求医疗援助
489	352	Continue approach Runway 36R, maintain visual separation with preceding traffic. 继续进近，跑道 36R，与前机保持目视间隔
490	793	I see wild fire at my 10 o'clock, about 8 miles. 我在 10 点钟方向大约 8 英里的地方看到了野火
491	404	BKM 47, FL170 descending to FL120, abeam NLD VOR at 55. BKM47 分，高度层 170 下降到高度层 120，55 分正切 NLD VOR
492	336	Descend to 8000 feet at 1000 feet per minute or greater. 下降到 8000 英尺，以 1000 英尺每分或更大的下降率
493	627	I think we blew a nose wheel tyre. Request holding position. 我认为我们的前轮爆胎了，申请原地等待
494	698	We heard an explosion from the cabin. Request to stop climb. 我们在客舱内听见爆炸声，请求停止爬升
495	161	Line up and wait. Understand one aircraft to depart from A2. 进跑道等待，明白有飞机从 A2 离场
496	631	We made the go around because the GPWS warning was triggered. 我们复飞是因为触发了近地警告系统
497	98	Expect departure at 49, start up at own discretion, QNH 1004. 预计离场时间 49 分，开车时间自己掌握，QNH1004
498	29	Cancel SID, track direct to LLK, climb to and maintain FL110. 取消标准离场，直飞 LLK，爬升并保持高度层 110
499	252	50 miles right of track approved, when able, proceed direct TB. 可以向右偏离航迹 50mile，如可能，直飞 TB
500	628	We no longer have airspeed and altitude on our primary displays. 我们的主显示器上没有空速和高度的显示了
501	753	Request immediate one eighty turn to the right due volcanic ash. 由于火山灰，请求立即右转 180 度
502	848	Does the flight path of the unknown aircraft converge with ours? 这个不明航空器的飞行路线与我们汇聚吗？
503	452	Our cabin rate of climb has red-lined. Request immediate descent. 我们的座舱上升率已经到达红线，请求立即下降
504	369	Proceed to AK, hold as published, expect approach clearance at 30 飞往 AK，按公布航图等待，预计进近许可 30 分
505	372	Holding northwest of W VOR FL120, what is the delay for approach? W VOR 台，西北等待，高度 12000 英尺，请问进近的延误情况
506	528	Request descent to 10000 feet to ventilate the aircraft due smoke. 由于烟雾，请求下降到 10000 英尺使飞机得到通风。
507	850	We have traffic indication at 2 o'clock, 300 feet above our level. 我们有冲突飞机显示在 2 点钟方位，高于我们的高度层 300 英尺
508	358	Cleared VOR approach Runway 36, followed by circling to Runway 18. 可以 VOR 进近，跑道 36，然后盘旋着陆跑道 18
509	483	Our Airline policy does not allow us to perform CAT IIIC approach. 我们的公司政策不允许我们执行 IIIC 类进近
510	623	We cannot extend the left landing gear. Request foaming the runway. 我们不能放出左起落架，申请在跑道上喷洒泡沫

511	393	Request lose time en route due landing delay at destination airport. 由于目的地机场落地延误，请求在航路上消耗时间
512	709	We have a “Wind-shear Ahead” warning. Request to delay our approach. 我们收到“前方风切变”的告警信息，请求推迟进近
513	797	Request offset 10 miles left to avoid the reported strong downdraft. 请求向左偏离航道 10 英里以避让报告的下沉气流
514	598	We performed the go-around because we had a ground proximity warning. 我们执行了复飞是因为出现了近地警告
515	501	Request diversion to the nearest suitable airport due AC BUS failure. 由于交流汇流条失效，请求备降到就近合适机场
516	84	Recleared to destination via B213,WHA, R343, rest of route unchanged. 重新允许经由 B213, WHA, R343 飞往目的地，剩余路线不变。
517	503	We have a problem with the aircraft battery. Request priority landing. 我们的飞机电瓶有问题，请求优先着陆
518	641	We made the go-around because the radio altimeter triggered flare mode. 我们复飞了是因为无线电高度表触发了拉平模式
519	615	Cockpit oxygen cylinder pressure is low. Request to return for landing. 驾驶舱氧气瓶压力低，请求返航
520	272	Traffic indication at our 1 o'clock, 4 miles, same altitude, converging. 飞机显示在我们 1 点钟方向，4 英里，相同高度，正在汇聚
521	146	After departure, turn left heading 190, Runway 24R, cleared for takeoff. 起飞后，左转航向 190，跑道 24R，可以起飞
522	53	Position OBLIK at 0646, maintaining FL310, estimating ZF 0658, WUH next. 当前位置 OBLIK，当前时间 0646，保持高度 310，预计到达 ZF 时间为 0658，下一位置 WUH
523	862	We overran the runway end. We are evacuating. Request emergency services. 我们冲出了跑到头，正在撤离，请求紧急服务
524	300	Cleared straight-in ILS approach Runway 24, descend to 3000 feet, QNH1011. 可以直接盲降进近，跑道 24，下降到 3000 英尺，QNH1011
525	495	Our data-link has malfunctioned. Request re-release the flight plan by voice. 我们的数据链故障了，申请语音重新发布飞行计划
526	329	Precision radar approach Runway 27 heading 260, descending to 2500 feet, QNH1014. 精密雷达进近，跑道 27，航向 260，下降到 2500 英尺，QNH1014
527	633	Our ADS-B transmitter appears to be malfunctioning. Terminating further ADS-B transmissions. 我们的 ADSB 发射机似乎出现故障，停止继续使用 ADSB 发话
528	722	Request a general heading of 050 due to multiple cells ahead. 申请航向大致 050，由于前方有多个单体雷雨区
529	864	We will reach our minimum fuel if we are delayed any further. 如果延误情况继续下去，我们将达到最低油量
530	295	Right heading 040 until passing FL70 then track direct to BK. 右转航向 040 直到通过高度层 70，然后直飞 BK
531	558	Request climb for dumping fuel and vectors to the fuel dump zone. 请求爬升进行应急放油，雷达引导至放油区域。
532	777	Request a remote apron for parking our aircraft due bomb on board. 由于机上有炸弹，请求将飞机停在远机坪
533	502	We are not supplying power to our DC BUS. Request priority landing. 我们不再为直流汇流条供电，申请优先着陆

534	455	We are now depressurized and will fly a more shallow descent profile. 我们现在遭遇失压，需要以较平缓的下降剖面飞行
535	867	We are declaring fuel emergency. Request priority landing Runway 03R. 我们正宣布紧急油量，请求优先着陆跑道 03R
536	870	The military aircraft is commanding us to land at the airfield below. 这架军用机指示我们在下面的机场着陆
537	477	We have lost our flight plan after a flight management computer reset. 由于飞行管理计算机重新设置，飞行计划丢失
538	567	The backup hydraulic system is operational but we still want to divert. 备份液压系统工作，但我们仍然需要改航
539	593	We made the go around because we exceeded the vertical deviation limit. 我们复飞是因为我们超出了纵向偏离限制
540	522	The APU is still on fire. We are evacuating. Request emergency services. APU 仍然起火，我们正在撤离，请求紧急服务
541	581	I had to abort take-off because I didn't receive any airspeed indication. 我不得不中断起飞，因为我无法看到任何速度指示
542	535	We cannot fully extend the flaps. Request the longest runway for landing. 我们不能完全放出襟翼，申请使用最长的跑道落地。
543	467	Our navigation accuracy is low. Request to climb to minimum safe altitude. 我们的导航精度低，请求爬升到最低安全高度
544	482	We do not meet GPS approach requirement due to flight crew qualifications. 由于飞行员资质原因，我们不符合 GPS 进近要求
545	486	We are unable to conform to the noise abatement procedure due performance. 由于性能原因，我们不能遵守降噪程序
546	800	Request immediate one-eighty turn to the right due to possible hail ahead. 我们机上有三名重伤，五名轻伤，请求救护车到场
547	884	Did the previous controller tell you about our problem during radar handoff? 前面的管制员有没有在雷达移交时把我们的情况告诉你？
548	637	We made an overshoot because our ADS-B indicated a possible runway incursion. 我们复飞了是因为，ADSB 显示可能会有跑道入侵
549	872	We are being escorted towards the national boundary by two military aircraft. 我们正被两架军用机护送至国境线
550	636	Our ADS-B has malfunctioned. Is there any weather advisory at our destination? 我们的 ADSB 故障了，我们的目的地有什么天气报告吗？
551	844	The cabin crew have used up all the portable extinguishers. Request diversion. 乘务员已经用完了所有的手提式灭火器，请求备降
552	831	The air marshal is searching the aircraft interior for any suspicious articles. 空保正在搜查飞机内部的任何可疑物体
553	852	We have a possible traffic conflict ahead. Request radar vectors for avoidance. 我们前方可能会有交通冲突，请求雷达引导避让
554	396	Request parallel offset from current airway for 30 minutes due icing condition. 由于结冰条件，请求平行偏离当前航路
555	494	Our satellite phone is unserviceable. We are unable to call company operations. 我们的卫星电话故障了，无法联系公司运控部门
556	657	We are expediting descent to enable a windmill start-up. Request further descent. 我们正加速下降，为使风转启动发动机，请求进一步下降
557	857	We have injuries resulting from our TCAS maneuver. Request ambulance on arrival. TCAS 机动导致部分旅客受伤，请求救护车到场
558	686	Engine Number One has a temperature problem. Request holding to perform checklist. 一号发动机温度有问题，请求等待以完成检查单

559	448	Many passengers are suffering from smoke inhalation. Request medical assistance on arrival. 很多旅客遭遇烟雾吸入，请求医疗援助在到达时准备就绪
560	460	The avionics ventilation is unserviceable. Request diversion to the closest suitable airport. 电子通风故障，请求改航到就近合适机场
561	719	We won't have to deviate if you allow us to climb to FL430. 如果允许我们爬升到高度层 430，我们就不用偏离航道了
562	667	We are at bay15. We have an APU fire. Request fire services. 我们在 15 停机位，APU 起火，请求消防服务
563	384	Descend to and maintain FL 270. Do not exceed Mach number decimal 79. 下降并保持高度层 270，不要超过马赫数 0.79
564	403	Passing POU at 43, maintaining FL310, estimating MLT at 55, next NLD. 在 43 分通过 POU，保持高度层 310，预计 55 分到达 MLT，下一航路点 NLD
565	705	We are encountering clear ice. Request immediate right turn to heading 130. 我们遇到了明冰，请求立即右转向 130
566	423	Cleared to leave A1 via BKM VOR, maintain FL230 while in controlled airspace. 准许经由 BKMVOR 台离开 A1，在管制空域保持高度层 230
567	18	Right heading 330, descending to 3000 feet, cleared for ILS approach Runway 36R. 右转向 330，下降到 3000 英尺，可以盲降进近，跑道 36 右
568	443	All our air conditioning packs have malfunctioned. Request rapid descent to MEA . 全部的空调组件均已故障，请求快速下降到最低航路高度
569	83	Recleared to destination via ZF01 Departure, Runway 36R, rest of clearance unchanged. 重新许可经由 ZF-01 标准离场程序飞往目的地，跑道 36R，其余许可不变
570	676	The cockpit windshield has cracked. Request descent to FL220. 驾驶舱风挡裂了，请求下降到高度层 220
571	589	We made the go around due to map drift on our navigation display. 我们复飞是因为导航显示上的地图漂移
572	712	We are unsure of our position due heavy fog. We are holding position. 由于浓雾，我们没法确定当前位置，请求原地等待
573	271	We have traffic at our 12 o'clock, 5 miles, 500 feet below, climbing. 我们有冲突活动，在 12 点方位，无英里，低于我们 500 英尺，正在爬升
574	673	We had a smoke warning from the forward cargo hold. We are evacuating. 我们的前货舱有烟雾警告，我们正在撤离
575	476	The DME indication is not correct. Confirm the DME is still in service. DME 显示不正确，证实 DME 还在运行中
576	67	Cleared to exit the hold, fly direct to ML. Contact Approach on 128.35. 可以离开等待，直飞 ML，联系进近 128.35
577	746	Runway is covered with patches of ice. Braking action is medium to poor. 跑道被大片结冰覆盖，刹车效应较差
578	513	There was a fire from the avionics bay. Request radar vectors for final. 航电设备舱起火，请求雷达引导至五边
579	785	My apologies for the level deviation. We were caught in a strong updraft. 抱歉高度偏离了，我们遇到了强上升气流
580	557	We are too heavy for landing. Request fuel-dump at the fuel dumping area. 我们的着陆重量过重，请求在放油区域应急放油。
581	251	Your radar vector appears to be taking us to the prohibited area, confirm. 雷达引导似乎把我们带入禁飞区，证实

582	832	Some explosives were discovered behind a panel near the back of the cabin. 客舱后部的一块面板后面发现了一些爆炸物
583	488	Our VHF number One receiver has failed. We are no longer monitoring 121.5. 我们的甚高频 1 号接收机失效，不再守听 121.5
584	134	Behind Boeing 747 passing left to right, taxi to holding point A1 Runway 24. 在从左向右通过的波音 747 后，滑行至 24 号跑道 A1 等待点
585	487	We are not qualified for CAT IIIB approach and auto-land. Request diversion. 我们不具备 IIIB 类进近和自动着陆资格，请求改航
586	762	We are stopping taxi. The boarding bridge is not at its designated position. 我们停止滑行了，登机桥不在指定位置
587	563	We are near the freezing temperature of jet fuel. Request descent to FL 390. 喷气发动机燃油接近冰点温度，请求下降到高度层 390
588	579	Our pitot static heating system has failed. We might have an altitude error. 我们的皮托静压加温系统故障，我们可能会有高度误差
589	685	We have a low oil pressure warning from engine Number Two. Request diversion. 我们的二号发动机出现了滑油压力警告，请求备降
590	877	Confirm we are being vectored to fly overhead the airport for right downwind. 证实我们正被雷达引导飞越机场加入右起落三边
591	456	Request descent rate less than 500 feet per minute due to unpressurized cabin. 由于客舱失压，请求下降率小于 500 英尺每分钟
592	527	We have smoke coming from our avionics bay. We are disembarking the passengers. 我们的航电设备舱出现烟雾，我们正在撤离旅客。
593	561	We are indicating fuel filter clog. Request descent and to maintain high speed. 我们显示有燃油过滤阻塞，请求下降并保持大速度。
594	573	We still have only one hydraulic system. Request the longest runway for landing. 我们仍然只有一套液压系统，请求最长跑道着陆。
595	607	Our oil pressure reading is lower than normal. Request hold at present position. 我们的滑油压力读数低于正常值，请求原地等待
596	605	We are having abnormal engine indications. Request to reduce speed to 250 knots. 我们的发动机显示不正常，请求减速到 250 节
597	678	Neither of us can see through our windshield. Does your airport permit auto-land? 我们机长副驾驶都无法通过风挡看清，你机场允许自动着陆吗
598	713	We had a rapid airspeed decay due to turbulence. Request immediate descent to FL390. 由于颠簸，我们的空速出现快速衰减，请求立即下降到高度层 390
599	544	We have a problem with fuel temperature. Request holding position on the taxiway. 我们的燃油温度有问题，请求在滑行道上原地等待。
600	632	We have to recalibrate our instruments. Request to level off and maintain heading. 我们需要重新校准仪表，申请改平飞保持航向
601	643	Our weather radar has malfunctioned. What is the highest available level for cruise? 我们气象雷达故障了，最高可用巡航高度是多少？
602	608	The oil temperature is higher than normal. We are monitoring other engine parameters. 滑油温度高于正常值，我们正在监控其他发动机参数
603	735	We were struck by hail. Our airframe is severely damaged. Request emergency services. 我们被冰雹击中了，我们的机身严重受损，请求紧急服务
604	597	Request to climb to minimum safe altitude due to malfunction of navigation computers. 由于导航计算机故障，申请爬升到最低安全高度
605	674	We have a cargo smoke warning. We are disembarking passengers. Request fire services. 我们有货舱烟雾警告，我们正在让旅客下飞机，请求消防车
606	780	We cannot get good climb profile due to engine problems. Request maintain runway heading. 由于发动机问题，我们不能获得良好的爬升剖面，请求保持跑道航向

607	539	Request vectors for long final. We are controlling the airplane with mechanical backup. 请求雷达引导至长五边，我们正用机械备用设备操纵飞机。
608	639	Our airspeed is unreliable. Request climb to minimum safe altitude to perform checklist. 空速显示不可靠，请求爬升到最低安全高度以完成检查单
609	531	RVSM Our flight control computers are not functioning well. We are having difficulty maintaining level flight,unable 我们的飞行控制计算机运转不正常，我们保持平飞有问题，不能在 RVSM 空域飞行
610	680	Our engine control has malfunctioned. We cannot get much thrust. Request immediate descent. 我们的发动机控制故障，无法获得较大推力，请求立即下降
611	894	Not ready for immediate takeoff due possible wake turbulence from departing heavy aircraft. 由于刚起飞的重型机可能会产生尾流，我们尚未准备立即起飞
612	784	My apologies forthe deviation due the wrong altitude setting. Request further instructions. 抱歉，由于高度设置错误偏离航道，请求下一步指令
613	741	Request holding instructions.We'U attempt another approach when the rain showers become lighter. 申请等待指令，当阵雨减弱我们将尝试重新进近
614	479	We need to reconfigure the flight management computers for approach. Request holding instructions. 进近前我们需要重新设置飞行管理计算机，请求等待指令
615	87	Cleared to destination, BK02 RNAV Departure, initially 3000 feet, departure frequency 125.4, squawk 3311. 准许飞往目的地机场，BK02 号 RNAV 离场，起始爬升高度 3000 英尺，离场频率 125.4，应答机编码 3311
616	836	We are evacuating on the runway. Be advised the bomb is still on board. 我们正在跑道上撤离，注意炸弹仍在飞机上
617	584	We have a master caution. I will notify you if a diversion is required. 我们有一个主警告灯亮了，如果需要改航我会告知你。
618	435	At 150W(west) contact San Francisco Radio, primary 3494, secondary 11342. 在西经 150 度联系旧金山无线电台，主高频 3494，备份高频 11342
619	898	Are you banning us from entry because of our airline or our aircraft type? 你禁止我们飞入是因为我们公司还是我们的机型？
620	642	Our weather radar has failed and we are in IMC. Request return for landing. 我们气象雷达失效了，我们在仪表气象条件下飞行，请求返航
621	582	We have an error in our airspeed. Request to climb to minimum safe altitude. 空速有误差，请求爬升到最低安全高度
622	825	There is a stand-off in the cabin. Some of the hijackers are carrying blades. 客舱内陷入僵局，一些劫机犯拿着刀片
623	787	We were not informed of a frequency change. I will now monitor your frequency. 我们未被告知改变频率，我现在将守听你的频率
624	835	A bomb has exploded and the cabin is full of smoke. Request emergency descent. 炸弹爆炸，客舱满是烟雾，请求紧急下降
625	622	We have exhausted all options. We will land without the nose gear fully locked. 我们已经用尽了全部选项，现在只能在前轮没有完全锁住的情况下落地。
626	418	Descending to FL60, maintain VMC FL90 to FL70, report traffic in sight at FL80. 下降到高度层 60，在高度层 70 和 90 之间保持目视气象条件，在高度层 80 看见活动飞机报告
627	811	We have an 8-month old infant with head injuries. Request ambulance on arrival. 我们有个 8 个月大的婴儿头部受伤，请求救护车到场
628	703	We made a diversion due to reports of freezing rain at our original destination. 由于目的地机场有冻雨报告，我们改航了

629	691	Engine Number Three has smoke coming out of the pylon section. We are evacuating. 三号发动机吊架部位出现烟雾，我们正在撤离
630	198	Thicker patches of fog exist further along the runway. RVR significantly reduced. 跑道后端有浓雾，跑道视程显著减少
631	711	We have received information of a new volcanic eruption. Will it affect our route? 我们收到关于火山爆发的最新信息，这是否会对我们的航路构成影响？
632	526	We have smoke coming from our avionics bay. We are evacuating. Request fire trucks. 航电设备舱出现烟雾，我们正在撤离，请求消防车。
633	572	Request the longest runway and vectors for a wide downwind due to hydraulic failure. 由于液压失效，请求最长跑道，以及雷达引导到宽三边。
634	695	Our left engine has ingested FOD. We are shutting down engines and holding position. 左发吸入外来物损坏，我们将马上关车原地等待
635	512	We had an electrical fire from the galley, now extinguished. Request return to land. 厨房电器起火，现在已被扑灭，请求返航。
636	480	We are now flying with basic navigation due to systems failure. Request radar vectors. 由于系统失效，我们正使用基本导航飞行，请求雷达引导
637	490	All of our VHF transmitters have failed, now transmitting on HF radio. Please respond. 我们的所有甚高频发射机均已失效，现在使用高频无线电发话，请回复
638	801	We have three serious and five minor injuries on board. Request ambulances on arrival. 我们机上有三名重伤，五名轻伤，请求救护车到场
639	383	Climb to and maintain FL310. Maintain Mach number decimal 81 or greater until BKM VOR. 爬升并保持高度层 310，在过 BKM VOR 之前保持马赫 0.81 或更大
640	644	Our weather radar has failed. How did the preceding aircraft deviate from the weather? 我们天气雷达失效了，前机是如何绕飞的？
641	772	Our cabin crew will direct all passengers to stay outside the runway after evacuation. 紧急撤离后我们的乘务员将指挥所有乘客待在跑道外
642	412	Request clearance to enter controlled airspace northeast of BKM VOR at FL240 at time 43. 请求在 BKM VOR 东北方向 高度 240，时间 43 分，进入管制空域
643	420	Cleared to destination airport via DAPRO, flight planned route, FL240, join A1 at FL240. 可以经由 DAPRO 计划航路飞往目的地机场，巡航高度层 240，并在高度层 240 加入 A1
644	808	A pregnant passenger is in severe pain. Request priority landing and ambulance on arrival. 有孕妇出现剧痛，请求优先着陆，以及救护车到场。
645	478	We need a few minutes to reprogram the flight management computers. Request radar vectors. 我们需要几分钟时间对飞行管理计算机进行重新编程，请求雷达引导
646	630	Our inertial reference system has failed, unable GPS approach. Request ILS or VOR approach. 我们的惯性基准系统失效，无法使用 GPS 进近，申请 ILS 或 VOR 进近
647	805	We have a hostage situation. Request stair vehicles on standby to disembark the passengers. 我们有一名人质被劫持了，请求客梯车待命以便让旅客下飞机
648	818	We have a hijack situation on board. Can our destination airport provide armed intervention? 我们遭遇劫机，目的地机场能否提供武装干预？
649	541	We have a problem with yaw damping. The aircraft is oscillating severely. Request diversion. 偏航阻尼出现问题，飞机摇摆严重，请求改航。
650	585	Some of our instruments are not indicating correctly. Request level off to perform checklist. 一些仪表显示不正确，请求改平飞以完成检查单

651	752	A Pilot overflying reported seeing virga above the runways. Request to terminate our approach. 飞越的飞行员报告说机场上空有雨幡，请求终止进近
652	804	A stressed passenger attempted to open an emergency exit. Request airport security on arrival. 一名闹情绪的乘客试图打开紧急出口，请求机场安保到场
653	600	We have conflicting traffic at eleven o'clock, 8 miles, climbing. Request vectors for avoidance. 我们发现冲突的飞机，在 11 点方向，8 英里，正在爬升，请求雷达引导避让
654	595	We have autopilot disconnection. We are no longer RVSM qualified. Request leaving RVSM airspace. 我们的自驾断开，我们不再具备 RVSM 资格，请求离开 RVSM 空域
655	519	We cannot extinguish the engine fire. Request priority landing and emergency services on arrival. 我们无法扑灭发动机火情，请求优先着陆和紧急服务在到达时准备就位。
656	469	Inertial reference system has failed. We are navigating on raw data. Request conventional approach. 惯性基准系统失效，我们正在使用原始数据，请求传统进近。
657	720	The thunderstorms will last for about 40 minutes according to the weather update. Request diversion. 根据最近的天气情况，雷暴将持续大约 40 分钟，请求改航
658	688	We have performed our procedures but engine vibration still exists. Request diversion. Request diversion. 我们已完成了程序，但发动机抖动仍然存在，请求备降
659	707	We cannot continue holding in icing conditions. Request descent immediately and cancel speed restrictions. 我们不能在结冰条件下继续等待，请求立即下降并取消速度限制
660	508	If there is no airport within 100 miles, we have to make a forced landing. 如果 100mile 内没有机场，我们将不得不进行迫降
661	892	Sorry, there was a problem with my audio equipment. How do you read me now? 抱歉，我的声音设备出了问题，你听我声音怎样？
662	559	We need about 18 minutes to jettison fuel before coming in for the approach. 在进近前，我们大约需要 18 分钟进行应急放油。
663	554	We might have a fuel leak near the wing root. Request fire trucks on arrival. 翼根部位可能漏油，请求消防车在我们到达时准备就位。
664	529	We had emptied most of our fire extinguishers, but the cabin fire is still on. 我们已经释放了大部分灭火瓶，但是客舱火情仍然存在。
665	863	We veered off the runway. We are evacuating near the runway and rapid exit J5. 我们偏出了跑道，正在撤离，当前位置在跑道和快速脱离道口 J5 附近
666	504	One of our transformers has failed. I'll let you know if a diversion is required. 变压器故障了，如果需要备降我会通知你
667	661	We are leaking bleed air. Request turn right heading 095 to avoid the icing area. 我们的引气正在泄漏，请求右转航向 095 避开结冰区域
668	786	We used too much speed brakes and penetrated our level. Did we cause any conflict? 我们使用减速板过度，导致穿越了当前高度，我们引起冲突了吗？
669	447	We have unusual smell from air conditioning packs. Request stop climb at 7000 feet. 我们的空调组件出现异常味道，请求在 7000 英尺停止爬升
670	841	Our cargo manifest shows that there are 80 kilograms of lithium batteries on board. 我们的货物舱单表明机上有 80kg 的锂电池
671	851	We have a possible traffic conflict at 10 o'clock, converging with our flight path.

		我们可能在 10 点钟方位有冲突飞机，飞行路线和我们汇聚
672	759	The NOTAM says this part of the taxiway is closed during this period, please verify. 航行通告说，该部分滑行道在此期间关闭，请核实
673	756	Lining up Runway 35. Runway lights are too bright. Request to dim the runway lights. 进跑道 35，跑道灯太亮，请求调暗跑道灯
674	444	We had a malfunction of one air conditioning pack. Request descent to a lower level. 我们有一个空调组件故障，请求下降到较低高度。
675	293	We are too low to the surrounding terrain. Confirm we are still being radar vectored. 我们高度过低，周围有地形，证实我们仍然被雷达引导
676	858	Some of the cabin crew are injured. They were serving meals during the TCAS maneuver. 部分乘务员受伤了，TCAS 机动时，他们正在供餐
677	616	We are holding at present position. It appears one of the over-wing exits has unlocked. 我们正在原地等待，机翼上方似乎有松锁
678	401	Climb to and maintain FL290, re-cleared to track direct to BKM VOR, the rest unchanged. 爬升并保持高度层 290，重新许可直飞 BKM VOR，剩余路线不变
679	71	A^er passing SY VOR, leave the hold on heading 250, cleared for VOR approach Runway 06. 过 SY VOR 后，离开等待，航向 250，可以 VOR 进近，跑道 06
680	586	Two of our display units have failed. We are no longer RNP qualified. Request diversion. 两个显示器失效，我们不再具备 RNP 资格，请求备降
681	468	We have a navigation map shift, unable to perform the RNAV approach. Request radar vectors. 我们的导航地图漂移，无法执行 RNAV 进近，申请雷达引导
682	524	A passenger ignited the lavatory waste bin. Advise the airport police to await our arrival. 有一个乘客点燃了厕所的垃圾桶，告知机场警察在我们到达时就位待命。
683	807	We have a passenger with a suspected heart attack. Request diversion to a suitable airport. 我们有一名乘客有疑似心脏病，请求备降到就近机场
684	575	We must descend immediately to exit icing conditions. Our right engine bleed air has failed. 我们必须立即下降脱离结冰情况，右发引气失效
685	626	The tyres are deflated. We will have to hold at present position for maintenance inspection. 轮胎漏气了，我们必须原地等待机务人员来进行检查
686	574	Our left engine anti-ice system has failed. Request immediate climb to leave the icing area. 我们的左发防冰系统失效，请求立即爬升离开结冰区域
687	459	We have an avionics ventilation problem. The skin heat-exchangers and blower fan have failed. 我们的电子通风有问题，蒙皮热交换器和吹风扇都故障了
688	556	We are evacuating. Advise emergency personnel that fuel odors are still present in the cabin. 我们正在进行紧急撤离，告诉地面人员，客舱内仍然有燃油味道
689	871	The military aircraft has made an abrupt maneuver indicating we may continue on this heading. 这架军用飞机突然机动了一下，示意我们可以继续保持当前航向
690	323	Reduce to minimum approach speed, turn right heading 230, cleared for ILS approach Runway 27. 减小至最小进近速度，右转航向 230，准许 ILS 进近，跑道 27
691	583	We have master warning lights in the cockpit. Request landing at the nearest suitable airport. 我们的驾驶舱主警告灯亮了，请求就近合适机场着陆。

692	537	Request high speed approach. Part of our flight control surfaces have separated from the wing. 请求高速进近，部分飞机操纵面与机翼分离。
693	620	Our brakes have seized. The tyres might burst during touchdown. Request fire trucks on arrival. 我们的刹车卡住了，接地过程中可能会爆胎，请求消防车到场
694	656	Our APU bleed air malfunctioned during engine start-up. We are calling the ground staff, standby. APU 引气在发动机开车过程中故障了，我们正在呼叫地面人员，稍等
695	829	The air marshal and passengers have restrained five suspects. The situation is now under control. 安全员和乘客已经制服了五名嫌疑犯，局面已经得到了控制
696	314	Hold over BKM VOR at FL100, inbound track 280 degrees, left hand pattern, outbound time 1 minute. 在 BKM VOR 台上空等待，高度层 100 英尺，入航航迹 280，左等待，出航时间 1 分钟
697	782	The center of gravity is disturbed. We will relocate passengers prior to approach. Request holding. 重心被干扰了，进近前我们将重新安排旅客，请求等待
698	599	We have conflicting traffic at one o'clock, 6 miles, descending. Request heading 130 for avoidance. 我们发现冲突的飞机，在 1 点钟方位，6 英里，正在下降，请求航向 130 以避免
699	726	We made the go-around because strong convective currents on short final made our approach unstable. 我们复飞的原因是短五边较强的对流气流使我们的进近不稳定
700	445	We have lost electrical power to the cabin air compressor. Request immediate descent to 10,000 feet. 我们的客舱空气压缩机失去电源，请求立即下降到 10000 英尺
701	79	Cleared to destination via ZAM, flight planned route, D03 Departure, cruising level 230, squawk 3763 可以经由 ZAM 飞往目的地机场，飞行计划航路，D03 离场，巡航高度 230，应答机编码 3763
702	779	We have veered off the runway due asymmetric thrust. We are evacuating. Request emergency assistance. 由于推力不对称，我们转向偏离了跑道，正在撤离，请求紧急援助
703	645	We do not have that route in our database. Which heading should we maintain for now? 我们数据库没有那个航路，我们现在应该保持什么航向？
704	743	We have observed blowing sand in the vicinity of the airport. How long will this last? 我们观察到机场附近有扬沙，这会持续多久？
705	471	The ILS signal seems to be very unstable. Did any other pilot report a similar situation? 盲降信号似乎不稳定，有无其他飞行员报告类似情况？
706	533	The aircraft has a tendency to roll to the right. I need additional airspace to maneuver. 飞机有向右横滚的趋势，我们需要额外的空域进行机动。
707	560	We cannot shut off the fuel dump valve. Request radar vectors for short final, Runway 17. 我们无法关闭应急放油活门，请求雷达引导至短五边，跑道 17.
708	739	Request to cancel our approach. The runway is not long enough and there are water patches. 请求取消进近，跑道不够长，而且有部分积水
709	717	I apologize for the level bust, but we needed the altitude loss to recover from wind-shear. 抱歉刚刚出现了高度偏离，但我们需要减小高度以改出风切变
710	506	We are operating with only the emergency generator. Request track direct to final, Runway 26. 我们仅有紧急发电机正在运转，请求直飞五边，跑道 26
711	73	Cleared to LHR, hold at LHR as published. Maintain 8000 feet. Expect further clearance at 18. 准许飞往 LHR，按公布程序在 LHR 等待，保持 8000 英尺，预计下一步许可时间 18

712	507	We are flying with batteries only. Is there any airport available within 25 minutes of flying? 我们仅依靠电瓶飞行，有无 25 分钟之内可以飞抵的机场
713	708	We have a “Wind-shear Ahead” warning message. Request to delay takeoff or change to another runway. 我们收到“前方风切变”的告警信息，请求推迟起飞或者更换跑道
714	475	The ILS signal was unstable. Request approach to another runway or request another type of approach. 盲降信号不稳定，请求更换跑道进近，或使用另一种进近方式
715	601	Traffic at our twelve o'clock, 10 miles, climbing. Should we expedite our descent to cross altitudes? 冲突活动，在 12 点方向，10 英里，正在爬升，能否加速下降穿越高度？
716	647	We have a navigation malfunction. Request diversion to a suitable airport that has less complex terrain. 我们导航故障了，请求备降到就近较少复杂地形的机场
717	802	One passenger is having difficulty breathing. Request descent to a lower level to reduce cabin altitude. 一名乘客有呼吸困难，请求下降至较低高度以减少座舱高度
718	778	We have had a tail strike. Request to stop climb at 3000 feet and return for landing. 我们刚刚擦机尾了，请求在 3000 英尺停止下降，并返场着陆
719	511	We have cut off the electrical system to the cabin and the onboard fire is under control. 我们已经切断了客舱电力系统，机上火情已经得到控制
720	672	Smoke is coming from the cabin floor. We are performing an evacuation. All slides have been deployed. 客舱地板有烟雾冒出，我们正在执行紧急撤离，所有滑梯都已经释放
721	671	We have an abnormal noise coming from one of our cabin doors. Request rapid descent to 5000 feet. 我们有一个客舱门出现异常噪音，请求快速下降到 5000 英尺