

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



1-Risk

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Risk overview



2-Risk

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Risk identifier

Photo Sheet

Eberl Claims Service

**3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax**

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



3-Risk

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though this church building was built in 1983.



4-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Eight cap and collar sets are present on the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



5-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Four pipe jacks are present on the roof surface.



6-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The left and front slopes are joined together, using tar at the valley.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



7-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The right slope underlays the front slope at the valley.



8-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



9-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.



10-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



11-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.



12-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



13-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.



14-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 100 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



15-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The right facing slope has been inspected and found to be free from storm related damage. Please note, the slope is tucked under the damaged front facing slope at the valley.



16-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The right facing slope has been inspected and found to be free from storm related damage. Please note, the slope is tucked under the damaged front facing slope at the valley.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



17-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The right facing slope has been inspected and found to be free from storm related damage. Please note, the slope is tucked under the damaged front facing slope at the valley.



18-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



19-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.



20-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



21-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.



22-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



23-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.



24-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged five shingles on the left facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



25-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.



26-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



27-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.



28-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



29-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.



30-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 15 shingles on the front facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



31-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.



32-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



33-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.



34-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



35-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.



36-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged 11 shingles on the rear facing slope of the church building roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



37-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.



38-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.

Photo Sheet


Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



39-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.



40-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



41-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.



42-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Ridge cap throughout the church building roof has been damaged by wind.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



43-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.



44-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



45-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.



46-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



47-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.



48-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



49-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.



50-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



51-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.



52-Building Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The rear most slope has been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



53-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Front elevation overview



54-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia have been damaged by wind on the front elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



55-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia have been damaged by wind on the front elevation of the church building.



56-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia have been damaged by wind on the front elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



57-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia have been damaged by wind on the front elevation of the church building.



58-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia have been damaged by wind on the front elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



59-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though wind has damaged the Styrofoam and stucco trim around the double doors on the front elevation.



60-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though wind has damaged the Styrofoam and stucco trim around the double doors on the front elevation.

Photo Sheet


Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



61-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though wind has damaged the Styrofoam and stucco trim around the double doors on the front elevation.



62-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Right elevation overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




63-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia has been damaged by wind on the right elevation of the church building.



64-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia has been damaged by wind on the right elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



65-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia has been damaged by wind on the right elevation of the church building.



66-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia has been damaged by wind on the right elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



67-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Vinyl soffit and aluminum facia has been damaged by wind on the right elevation of the church building.



68-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on the upper triangle on the right elevation.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



69-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on the upper triangle on the right elevation.



70-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on the upper triangle on the right elevation.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



71-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

1 meter mast is fastened through the vinyl siding on the right elevation.



72-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Four pipe penetrations and various cables are attached over the vinyl siding on the right elevation.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



73-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

A fifth pipe penetration is installed over the siding on the right elevation.



74-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Rear elevation overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




75-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged soffit and facia on the rear elevation of the church building.



76-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged soffit and facia on the rear elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



77-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged soffit and fascia on the rear elevation of the church building.



78-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Left elevation overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




79-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.



80-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



81-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.



82-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



83-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.



84-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged the vinyl siding on one of the upper triangles on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



85-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and facia on the left elevation of the church building.



86-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and facia on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




87-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and facia on the left elevation of the church building.



88-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and facia on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



89-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and fascia on the left elevation of the church building.



90-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and fascia on the left elevation of the church building.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




91-Building Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged, soffit and fascia on the left elevation of the church building.



92-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Sanctuary overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




93-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Sanctuary overview



94-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Sanctuary overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



95-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.



96-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



97-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.



98-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



99-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.



100-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



101-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.



102-Sanctuary

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water has entered through the roof during the storm and caused damage to the lavender colored suspended ceiling tiles in the sanctuary.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



103-Womens Restroom

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Women's restroom identifier



104-Womens Restroom

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Women's restroom overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



105-Womens Restroom

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Women's restroom overview



106-Womens Restroom

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears the water through the roof during the storm has damaged one ceiling tile in the women's restroom.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



107-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Kitchen overview



108-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Kitchen overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



109-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as though water through the roof during the storm has damaged the smooth textured drywall ceiling in the kitchen.



110-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Two fluorescent light fixtures, one ceiling fan, and two register covers are installed over the ceiling surface in the kitchen.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825


Policy #: 001100452



111-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski



112-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Fellowship hall overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



113-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Fellowship hall overview



114-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the water has come through the roof during the storm damaging 2 x 2 suspended ceiling tiles in the fellowship hall.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



115-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the water has come through the roof during the storm damaging 2 x 2 suspended ceiling tiles in the fellowship hall.



116-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the water has come through the roof during the storm damaging 2 x 2 suspended ceiling tiles in the fellowship hall.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



117-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the water has come through the roof during the storm damaging 2 x 2 suspended ceiling tiles in the fellowship hall.



118-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the water has come through the roof during the storm damaging 2 x 2 suspended ceiling tiles in the fellowship hall.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



119-Kitchen

Date Taken: 10/21/2024

Taken By: Steven Kujawski



120-Shed

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Shed overview

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




121-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

25 year three tab shingles are present on the shed roof.



122-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

The shed roof is a 3/12 pitch.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



123-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.



124-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.

Photo Sheet


Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



125-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.



126-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



127-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.



128-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452




129-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.



130-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



131-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.



132-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 50 shingles on the front facing slope of the shed roof.

Photo Sheet


Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



133-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



134-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST
CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



135-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



136-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



137-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



138-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



139-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



140-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



141-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



142-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



143-Shed Roof

Date Taken: 10/21/2024

Taken By: Steven Kujawski

It appears as the wind has damaged over 40 shingles on the rear facing slope of the shed roof.



144-Shed Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

All elevations of the storage shed have been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



145-Shed Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

All elevations of the storage shed have been inspected and found to be free from storm related damage.



146-Shed Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

All elevations of the storage shed have been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



147-Shed Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

All elevations of the storage shed have been inspected and found to be free from storm related damage.



148-Shed Elevations

Date Taken: 10/21/2024

Taken By: Steven Kujawski

All elevations of the storage shed have been inspected and found to be free from storm related damage.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



149-Signs

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Eight parking signs have been blown over and need to be rectified following the storm.



150-Signs

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Eight parking signs have been blown over and need to be rectified following the storm.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



151-Signs

Date Taken: 10/21/2024

Taken By: Steven Kujawski

Eight parking signs have been blown over and need to be rectified following the storm.



152-Fencing

Date Taken: 10/21/2024

Taken By: Steven Kujawski

40 lineal feet of chain-link fence with privacy slats surrounding the electrical feed need to be replaced following the storm.

Photo Sheet

Eberl Claims Service

3900 S Wadsworth Blvd, Suite 800
Lakewood, CO 80235
(800) 607-3604 - Phone
(303) 986-27765 - Fax

Insured: NEW ZION HILL MISSIONARY BAPTIST CHURCH INCORPORATED

Claim #: AA190825

Policy #: 001100452



153-Fencing

Date Taken: 10/21/2024

Taken By: Steven Kujawski

40 lineal feet of chain-link fence with privacy slats surrounding the electrical feed need to be replaced following the storm.



154-Fencing

Date Taken: 10/21/2024

Taken By: Steven Kujawski

40 lineal feet of chain-link fence with privacy slats surrounding the electrical feed need to be replaced following the storm.