

Statement 20260016 for LONGACRE WORKS

Reference 20260016

Item	Units	Rate	Amount	Note
001 - Measured survey of the north elevation and of its two return walls	1	12.5	12.5	less 2
002 - Removal of the failed pointing between courses four and eleven, by hand	2	15.75	31.5	
003 - Repointing in a lime mortar matched to the original, struck flush	3	19	57	
004 - Supply and fitting of a lead saddle over the string course	4	22.25	89	
005 - Easing the two casement windows upstairs, with new brass fasteners	1	25.5	25.5	
006 - Taking down the loose chimney stack and setting the sound bricks aside	2	28.75	57.5	less 4
007 - Measured survey of the north elevation and of its two return walls	3	32	96	
008 - Removal of the failed pointing between courses four and eleven, by hand	4	12.5	50	
009 - Repointing in a lime mortar matched to the original, struck flush	1	15.75	15.75	
010 - Supply and fitting of a lead saddle over the string course	2	19	38	
011 - Easing the two casement windows upstairs, with new brass fasteners	3	22.25	66.75	less 3
012 - Taking down the loose chimney stack and setting the sound bricks aside	4	25.5	102	
013 - Measured survey of the north elevation and of its two return walls	1	28.75	28.75	
014 - Removal of the failed pointing between courses four and eleven, by hand	2	32	64	

Brought forward

734.25

Item	Units	Rate	Amount	Note
015 - Repointing in a lime mortar matched to the original, struck flush	3	12.5	37.5	
016 - Supply and fitting of a lead saddle over the string course	4	15.75	63	less 2
017 - Easing the two casement windows upstairs, with new brass fasteners	1	19	19	
018 - Taking down the loose chimney stack and setting the sound bricks aside	2	22.25	44.5	
019 - Measured survey of the north elevation and of its two return walls	3	25.5	76.5	
020 - Removal of the failed pointing between courses four and eleven, by hand	4	28.75	115	
021 - Repointing in a lime mortar matched to the original, struck flush	1	32	32	less 4
022 - Supply and fitting of a lead saddle over the string course	2	12.5	25	
023 - Easing the two casement windows upstairs, with new brass fasteners	3	15.75	47.25	
024 - Taking down the loose chimney stack and setting the sound bricks aside	4	19	76	
025 - Measured survey of the north elevation and of its two return walls	1	22.25	22.25	
026 - Removal of the failed pointing between courses four and eleven, by hand	2	25.5	51	less 3
027 - Repointing in a lime mortar matched to the original, struck flush	3	28.75	86.25	
028 - Supply and fitting of a lead saddle over the string course	4	32	128	
029 - Easing the two casement windows upstairs, with new brass fasteners	1	12.5	12.5	
030 - Taking down the loose chimney stack and setting the sound bricks aside	2	15.75	31.5	

Brought forward

1601.5

Item	Units	Rate	Amount	Note
031 - Measured survey of the north elevation and of its two return walls	3	19	57	less 2
032 - Removal of the failed pointing between courses four and eleven, by hand	4	22.25	89	
033 - Repointing in a lime mortar matched to the original, struck flush	1	25.5	25.5	
034 - Supply and fitting of a lead saddle over the string course	2	28.75	57.5	
035 - Easing the two casement windows upstairs, with new brass fasteners	3	32	96	
036 - Taking down the loose chimney stack and setting the sound bricks aside	4	12.5	50	less 4
037 - Measured survey of the north elevation and of its two return walls	1	15.75	15.75	
038 - Removal of the failed pointing between courses four and eleven, by hand	2	19	38	
039 - Repointing in a lime mortar matched to the original, struck flush	3	22.25	66.75	
040 - Supply and fitting of a lead saddle over the string course	4	25.5	102	
041 - Easing the two casement windows upstairs, with new brass fasteners	1	28.75	28.75	less 3
042 - Taking down the loose chimney stack and setting the sound bricks aside	2	32	64	
043 - Measured survey of the north elevation and of its two return walls	3	12.5	37.5	
044 - Removal of the failed pointing between courses four and eleven, by hand	4	15.75	63	
045 - Repointing in a lime mortar matched to the original, struck flush	1	19	19	
046 - Supply and fitting of a lead saddle over the string course	2	22.25	44.5	less 2

Brought forward

2455.75

Item	Units	Rate	Amount	Note
047 - Easing the two casement windows upstairs, with new brass fasteners	3	25.5	76.5	
048 - Taking down the loose chimney stack and setting the sound bricks aside	4	28.75	115	
049 - Measured survey of the north elevation and of its two return walls	1	32	32	
050 - Removal of the failed pointing between courses four and eleven, by hand	2	12.5	25	
051 - Repointing in a lime mortar matched to the original, struck flush	3	15.75	47.25	less 4
052 - Supply and fitting of a lead saddle over the string course	4	19	76	
053 - Easing the two casement windows upstairs, with new brass fasteners	1	22.25	22.25	
054 - Taking down the loose chimney stack and setting the sound bricks aside	2	25.5	51	
055 - Measured survey of the north elevation and of its two return walls	3	28.75	86.25	
056 - Removal of the failed pointing between courses four and eleven, by hand	4	32	128	less 3
057 - Repointing in a lime mortar matched to the original, struck flush	1	12.5	12.5	
058 - Supply and fitting of a lead saddle over the string course	2	15.75	31.5	
059 - Easing the two casement windows upstairs, with new brass fasteners	3	19	57	
060 - Taking down the loose chimney stack and setting the sound bricks aside	4	22.25	89	
Net total			3305	

Net 3305 less 247.88 leaves 3057.12

Due 2026-05-01, end of that month 2026-05-31, reduced lines 12

How to settle

By transfer to the account named in the remittance advice, quoting the reference.

Payment is due on the date shown above, without deduction. Interest at the statutory rate runs from the day after that date on any part left unpaid, and the recovery costs allowed by law are added to it. Goods remain the property of the issuer until the invoice is settled in full. Any dispute about a line of this statement is to be raised in writing within thirty days of its issue, quoting the reference at the head of every sheet; a line not disputed within that period is taken as accepted.

DUPLICATA