


VCarEA 测试报告

2026-08-18

报告概览


项目路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01		
测试名称	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01Cases\TS-06-上下电基准.case		
测试配置路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01\Configurations\TestConfiguration_VCU_HIL.tcf		
测试台配置路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01\Configurations\TestbenchConfiguration_VCU_HIL.tbf		
开始时间	结束时间	执行时间	
2026-08-18 10:59:44	2026-08-18 11:00:12	00:00:27.637	
测试步骤	通过步骤	失败步骤	
25	25	0	
测试用例	通过用例	失败用例	
1	1	0	

测试用例评估统计



通过：100.0000%
失败：0.0000%

测试步骤评估统计



通过：100.0000%
失败：0.0000%

TS-06-上下电基准

开始时间： 2026-08-18 10:59:45.450

结束时间： 2026-08-18 11:00:11.774

执行时间： 26324 ms

测试步骤： 25

通过步骤： 25

失败步骤： 0

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
☐ 正常上下电	2026-08-18 10:59:45.455	2026-08-18 10:59:58.185	12730 ms			成功		执行成功		
Write	2026-08-18 10:59:45.457	2026-08-18 10:59:45.711	254 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	100	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	制动踏板 0-100
Wait	2026-08-18 10:59:45.711	2026-08-18 10:59:46.215	504 ms		500 ms	成功		执行成功,等待500.0ms		
Write	2026-08-18 10:59:46.215	2026-08-18 10:59:46.331	116 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	拧钥匙 1-开 0-关
Wait	2026-08-18 10:59:46.331	2026-08-18 10:59:49.334	3003 ms		3000 ms	成功		执行成功,等待3000.0ms		
Read	2026-08-18 10:59:49.335	2026-08-18 10:59:49.461	126 ms	[0]: env_1/网络模型/CAN/VCU/RxMsg/GW_VCU_1 (0x403)/VCU_bReadyLightSts	1.0	成功	==1	评估成功	VCU_HIL/[0]: env_1/网络模型/CAN/VCU/RxMsg/GW_VCU_1 (0x403)/VCU_bReadyLightSts	ready灯
Wait	2026-08-18 10:59:49.461	2026-08-18 10:59:54.463	5002 ms		5000 ms	成功		执行成功,等待5000.0ms		
Write	2026-08-18 10:59:54.464	2026-08-18 10:59:54.571	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	制动踏板 0-100
Wait	2026-08-18 10:59:54.571	2026-08-18 10:59:55.074	503 ms		500 ms	成功		执行成功,等待500.0ms		
Write	2026-08-18 10:59:55.074	2026-08-18 10:59:55.181	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	拧钥匙 1-开 0-关
Wait	2026-08-18 10:59:55.181	2026-08-18 10:59:58.184	3003 ms		3000 ms	成功		执行成功,等待3000.0ms		
☐ 高压故障紧急下电	2026-08-18 10:59:58.185	2026-08-18 11:00:11.773	13588 ms			成功		执行成功		
Write	2026-08-18 10:59:58.187	2026-08-18 10:59:58.293	106 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	100	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	制动踏板 0-100

步骤名称	开始时间		结束时间		执行时间	名称	值	评估	期望	消息	信号源	注释
Write	2026-08-18 10:59:58.293	2026-08-18 10:59:58.400	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key		1	成功			执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	拧钥匙 1-开 0-关
Wait	2026-08-18 10:59:58.400	2026-08-18 10:59:58.904	504 ms			500 ms	成功			执行成功,等待500.0ms		
Write	2026-08-18 10:59:58.904	2026-08-18 10:59:59.011	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_per		0	成功			执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_per	制动踏板 0-100
Wait	2026-08-18 10:59:59.011	2026-08-18 11:00:02.014	3003 ms			3000 ms	成功			执行成功,等待3000.0ms		
Write	2026-08-18 11:00:02.014	2026-08-18 11:00:02.121	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail		1	成功			执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail	BMS故障注入
Wait	2026-08-18 11:00:02.121	2026-08-18 11:00:02.224	103 ms			100 ms	成功			执行成功,等待100.0ms		
Read	2026-08-18 11:00:02.224	2026-08-18 11:00:02.335	111 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail		1.0	成功	==1		评估成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail	观察故障是否注入成果
Wait	2026-08-18 11:00:02.335	2026-08-18 11:00:05.337	3002 ms			3000 ms	成功			执行成功,等待3000.0ms		
Write	2026-08-18 11:00:05.337	2026-08-18 11:00:05.444	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail		0	成功			执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail	BMS故障恢复
Wait	2026-08-18 11:00:05.444	2026-08-18 11:00:05.546	102 ms			100 ms	成功			执行成功,等待100.0ms		
Read	2026-08-18 11:00:05.547	2026-08-18 11:00:05.657	110 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail		0.0	成功	==0		评估成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/FromVCU/CAN/VCU_Body/GW_BMS_6/BMS__BattContFail	观察故障信号是否恢复
Wait	2026-08-18 11:00:05.657	2026-08-18 11:00:08.661	3004 ms			3000 ms	成功			执行成功,等待3000.0ms		
Write	2026-08-18 11:00:08.661	2026-08-18 11:00:08.769	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key		0	成功			执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	拧钥匙 1-开 0-关

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
Wait	2026-08-18 11:00:08.769	2026-08-18 11:00:11.772	3003 ms		3000 ms	成功		执行成功,等待3000.0ms		