1. What gain parameters did you end up using for your PI controller?

• Describe the response of the system to speed changes.

Kp = 5

Ki = 5, when I used these parameters the motor speed increased exponentially