

## MICROS 32 BITS STM - SERVOMOTOR

**ROBINSON JIMENEZ MORENO** 









```
#include <stdio.h>
 2 #include "STM32F7xx.h"
 3 #include <math.h>
   int paso=0;
 7 | extern "C" {
      void SysTick Handler ( void )
10
       paso++;
11
12
13
14 -
      int main (void) {
15
16
      RCC->AHBIENR =0xff; //TODOS LOS RELOJES ON -> Puerto A, B, C, E, F.
17
18
      GPIOC->MODER = 0x000055; //Pines del PBO al PB11 como salida
19
     GPIOC->OTYPER = 0;
20
      GPIOC->OSPEEDR = 0x5555555; //medium speed
21
      GPIOC->PUPDR = 0x100000000; //pull up
23
24
      SystemCoreClockUpdate();
      SysTick Config(SystemCoreClock/10000); //velocidad //tiempo minimo
25
26
27
      while(true) {
28
      paso=0;
29
      GPIOC->ODR=1;
30
      while (paso<10);
31
     paso=0;
32
      GPIOC->ODR=0;
33
      while (paso<200);
34
       }}
```

```
#include <stdio.h>
  #include "STM32F7xx.h"
  #include <math.h>
 int paso=0;
 int limite=0;
⊟extern "C" {
    void SysTick Handler ( void )
     paso++;
int main(void) {
    RCC->AHBIENR =0xff; //TODOS LOS RELOJES ON -> Puerto A, B, C, E, F.
  GPIOC->MODER = 0x000055; //Pines del PBO al PB11 como salida
  GPIOC->OTYPER = 0;
  GPIOC->OSPEEDR = 0x555555; //medium speed
GPIOC->PUPDR = 0x100000000; //pull up
    SystemCoreClockUpdate();
    SysTick Config(SystemCoreClock/10000); //velocidad //tiempo minimo
    while(true) {
       for(int i=0;i<10;i++){
    paso=0;
   GPIOC->ODR=1;
         limite=i+10;
  while(paso<limite);</pre>
  paso=0;
  GPIOC->ODR=0;
  while (paso<250);
     }}
```

```
#include <stdio.h>
 #include "STM32F7xx.h"
 #include <math.h>
 int paso=0;
 int servo=0;
 int limite=1;
⊟extern "C" {
   void SysTick Handler ( void )
     paso++;
   int main (void) {
   RCC->AHBIENR =0xFF; //TODOS LOS RELOJES ON -> Puerto A, B, C, E, F.
   GPIOC->MODER = 0x000055; //Pines del PB0 al PB11 como salida
   GPIOC->OTYPER = 0;
   GPIOC->OSPEEDR = 0x555555; //medium speed
   GPIOC \rightarrow PUPDR = 0x100000000; //pull up
   SystemCoreClockUpdate();
   SysTick Config(SystemCoreClock/10000); //velocidad //tiempo minimo
   while(true)
if((GPIOC->IDR & 0X2000)==0X2000){
  servo+=servo;}
   paso=0;
   GPIOC->ODR=1;
   limite=servo+10;
   while (paso<limite);
   paso=0;
   GPIOC->ODR=0;
   while (paso<250);
```

```
#include <stdio.h>
 #include "stm32f7xx.h"
 #include <stdlib.h>
 int dato=500;
= int main(void) {
   RCC->AHBIENR |= 0x47; //PUERTO A,B,C,G
   GPIOB->MODER |= 0x10004001; //Colocar en salida para encender los leds
   GPIOB->OTYPER |=0x0; //PUSH PULL
   GPIOB->OSPEEDR |=0x10004001; //Velocidad Medio
   GPIOB->PUPDR |=0x10004001;//PULL UP
   GPIOC->MODER &= \sim (3UL<<2*13);
   //----PTA6 -> TIM3 CH1----//
   GPIOA->MODER = 0x02000; //PTA6 en MODO ALTERNO
   GPIOA->OTYPER = 0;
                                 //PUSH PULL -> PTA6
   GPIOA->OSPEEDR = 0x01000; //MEDIUM SPEEED -> PTA6
   GPIOA->PUPDR = 0; //PULL-UP -> PTA6
   GPIOA->AFR[0] = 0x20000000; //PTA6 funcion alterna AF2= TIM3 CH1
   //----TIM3 CH1----//
   RCC->APBIENR |= (1UL << 1); //HABILITA CLOCK TIM3
   TIM3 \rightarrow EGR = (1UL << 0); //UG = 1 , RE-inicializar el contador
                              //señal de reloj HSI=16Mhz, se necesita generar 1Mhz por lo tanto PSC=15
   TIM3->PSC = 15;
                               //con una frecuencia de lMhz -> T=luS :
   TIM3->ARR = 25000;
                                //UIE = 1, update interrupt enable
   TIM3->DIER |= (1UL<<0);
                                  //conteo hasta 20000 significa 20000*luS = 20ms //periodo de la señal de control del servo
   TIM3->CR1 |= (1UL<<0);
                           //Enable counter
   TIM3->CCMR1 = 0x60;
                           //PWM modo 1, preload del CCRl deshabilitado, CHl configurado como salida
   TIM3->CCER |= (1UL<<0); //OCl signal is output on the corresponding output pin
   while(true) { GPIOB->ODR=0xffffffff;
if(GPIOC->IDR &= 0X2000){
   dato=dato+50;
 for(int i=0;i<20000;i++);}
   if (dato>2400) {dato=2400;}
   TIM3->CCR1=dato;
  }//WHILE
-}//MAIN
```