# Introduction to Robotics and Mechatronics

## **GROUP 2.5**

Benson Chalethu Pietro Griffa Ingvar Groza

PreLab 07

Q1

Being:

Nominal step angle = 1.8°

We can easily calculate:

**Steps per revolution** =  $360^{\circ}/1.8^{\circ} = 200$ 

```
lab07.ino
 1
 2
     IRM Lab07 : Closed-loop control I
 3
 4
 5
 6
     // Include the required libraries here (already done for you)
 7
     #include <string.h>
 8
     #include <Adafruit_MotorShield.h>
9
     #include <Wire.h>
10
11
     // global variables to control each motor
12
13
    Adafruit_MotorShield AFMS = Adafruit_MotorShield();
     Adafruit_StepperMotor *myMotor1 = AFMS.getStepper(200, 1);
14
15
     Adafruit_StepperMotor *myMotor2 = AFMS.getStepper(200, 2);
16
17
     // pinouts for limit switches
18
     int switch1 = 6; // motor 1
19
     int switch2 = 7; // motor 1
20
     int switch3 = 4; // motor 2
21
     int switch4 = 5; // motor 2
22
23
     // step size (Number of steps in each iteration)
24
     int stepSize = 20;
     // maximum speed in rpm of each motor
25
     int maxSpeed = 500;
26
27
     // Functions
28
29
     int move_steps (int steps, int dir, int motor) {
30
31
        int switch_check;
        int step_limit, step_stop, step_count, out = 0;
32
33
        int ls, switch_press, ref;
34
35
       // Check the motor and direction of movement, and set the limiting switch accordingly
        if (motor == 1) {
36
37
           if (dir == 1) {
38
              ls = 7; // limiting switch = switch 2
39
           else if (dir == 2) {
40
           ls = 6; // limiting switch = switch 1
41
42
43
           else {
44
           out = 53; // if a problem occour in the function, 5 is returned
45
46
        else if (motor == 2) {
47
48
           if (dir == 1) {
49
           ls = 5; // limiting switch = switch 4
50
51
           else if (dir == 2) {
52
           ls = 4; // limiting switch = switch 3
53
54
           else {
55
           out = 53;
           }
56
        }
57
58
        else {
59
           out = 53;
60
```

61 62

63

64

65 66

67

68

69

70

71 72

73

74 75

76

81 82

83

84 85

86

87

88

89 90 91

96 97

98

99 100

106

107

109

110

111

112

113 114

115 116 117

118

119

120

121

122

123

124 125

```
// Limit the total number of steps to 999
       step_limit = 999;
       // Create a loop, which is executed if steps > 0 and the limit switch has not been reached,
       // in the loop, move the desired motor in small steps (stepsize). Execute the loop until you moved
       // the whole distance
       step_count = 0;
       switch_check = -1;
       ref = digitalRead(ls);
       if(step_limit <= steps) {</pre>
         step_stop = step_limit;
       else {
       step_stop = steps;
       if (steps != 0 & out == 0) {
         while (step count <= step_stop) {
            if (ls == 7) {
             myMotor1.step(1, FORWARD, MICROSTEP);
           else if (ls == 6) {
             myMotor1.step(1, BACKWARD,MICROSTEP);
           else if (ls == 5) {
             myMotor2.step(1, FORWARD,MICROSTEP);
           else if (ls == 4) {
             myMotor2.step(1, BACKWARD,MICROSTEP);
           switch_press = digitalRead(ls);
           if (switch_press != ref) {
             switch_check = 0;
             break;
           step count++
        if (steps > 0 & out == 0) {
          if (1s == 7) {
            while (step count <= step stop) {</pre>
             myMotor1->step(1, FORWARD, MICROSTEP);
108
              switch_press = digitalRead(ls);
              if (switch_press != ref) {
                switch_check = 0;
                break;
              step_count++ ;
          else if (ls == 6) {
            while (step_count <= step_stop) {</pre>
              myMotor1->step(1, BACKWARD,MICROSTEP);
              switch press = digitalRead(ls);
              if (switch_press != ref) {
                switch_check = 0;
                break;
              step_count++;
```

128

129

130 131

132

133

134

135 136

137 138 139

140

141

142

143

144

145

146 147

154

155

156

157

158159

160

161162

163

164

165

166

167

168

170

171

173

174

179

180

181 182 183

169 ▼

172 ▼

```
else if (1s == 5) {
    while (step_count <= step_stop) {</pre>
      myMotor2->step(1, FORWARD,MICROSTEP);
      switch_press = digitalRead(ls);
      if (switch press != ref) {
        switch check = 0;
        break;
     step_count++;
 else if (ls == 4) {
   while (step count <= step stop) {</pre>
     myMotor2->step(1, BACKWARD,MICROSTEP);
     switch_press = digitalRead(ls);
      if (switch_press != ref) {
        switch_check = 0;
        break;
     step_count++;
// After running the loop, return ASCII for the switches
  if (switch check == 0) {
    switch (ls) {
     // If switch 2 is pressed, return '2'
      case 7:
        out = 50;
        break;
     // If switch 1 is pressed, return '1'
        out = 49;
       break;
     // If switch 4 is pressed, return '4'
     case 5 :
       out = 52;
        break;
      case 4:
     // If switch 3 is pressed, return '3'
       out = 51;
       break;
      default :
        out = 53;
        break;
 // Else, return '0'
  else {
  out = 48;
 return out; // return the correct message
```

188

190

191

192

193 194

195

196

197

198

199 200

201

202

210

211212

213

214215

216

217

218219

220221222

223 224

225

226227

228229

230231

232233

234235236237

238

239

240

241

242

243

244

245246

247 248

```
void setup() {
  // Start the serial communication at 9600 baud rate
  Serial.begin(9600);
  // Set serial communication timeout to 10
  Serial.setTimeout(10);
  // Start the Adafruit Motor Shield and set the maximum speed of the stepper to 500 rpm
  AFMS.begin();
  myMotor1->setSpeed(maxSpeed);
  myMotor2->setSpeed(maxSpeed);
  // Set the input pins
  pinMode(switch1, INPUT);
  pinMode(switch2, INPUT);
  pinMode(switch3, INPUT);
  pinMode(switch4, INPUT);
void loop() {
  // Initialize parameters
  char command[50];
  char check;
  byte read check;
  int int check;
  int steps, dir, motor;
  int c4, c3, c2;
  // Check if there is a command on the serial port
  if (Serial.available() > 0)
    read_check = Serial.readBytes(command,20);
    // If the command is not 5 bytes long, discard it
    if ((int)read check == 5)
      command[5] = '\0';
      check = '0';
    else
      command[0] = ' (0');
      check = '5';
      Serial.print(check);
  // Proper command contains 5 bytes:
  // First byte is the stage number: 1 or 2
  // Second byte is the direction: 1 or 2
  // Third - Fifth bytes are number of steps: 000 - 999
  if (command[0]!=0)
    // Check the first byte and if it is not '1' or '2' discard it
    // First byte determines the stage (stepper motor) that needs to be moved
    motor = (command[0]-'0');
   if (motor != 1 / motor != 2) {
    check = '5';
    }
```

188

190

191

192

193 194

195

196

197

198

199 200

201

202

210

211212

213

214215

216

217

218219

220221222

223 224

225

226227

228229

230231

232233

234235236237

238

239

240

241

242

243

244

245246

247 248

```
void setup() {
  // Start the serial communication at 9600 baud rate
  Serial.begin(9600);
  // Set serial communication timeout to 10
  Serial.setTimeout(10);
  // Start the Adafruit Motor Shield and set the maximum speed of the stepper to 500 rpm
  AFMS.begin();
  myMotor1->setSpeed(maxSpeed);
  myMotor2->setSpeed(maxSpeed);
  // Set the input pins
  pinMode(switch1, INPUT);
  pinMode(switch2, INPUT);
  pinMode(switch3, INPUT);
  pinMode(switch4, INPUT);
void loop() {
  // Initialize parameters
  char command[50];
  char check;
  byte read check;
  int int check;
  int steps, dir, motor;
  int c4, c3, c2;
  // Check if there is a command on the serial port
  if (Serial.available() > 0)
    read_check = Serial.readBytes(command,20);
    // If the command is not 5 bytes long, discard it
    if ((int)read check == 5)
      command[5] = '\0';
      check = '0';
    else
      command[0] = ' (0');
      check = '5';
      Serial.print(check);
  // Proper command contains 5 bytes:
  // First byte is the stage number: 1 or 2
  // Second byte is the direction: 1 or 2
  // Third - Fifth bytes are number of steps: 000 - 999
  if (command[0]!=0)
    // Check the first byte and if it is not '1' or '2' discard it
    // First byte determines the stage (stepper motor) that needs to be moved
    motor = (command[0]-'0');
   if (motor != 1 / motor != 2) {
    check = '5';
    }
```

250

251

252

253

254255256257

258

259

260

261

262263

264265

266267

268269270

271

272273

274275

276

277

278279

280 281

282

283

284

285

286

287 288

289 290

291

292293294

295

```
// Check the second byte and if it is not '1' or '2' discard it
 // Second byte determines the direction
  dir = (command[1]-'0');
  if (dir != 1 | dir != 2) {
  check = '5';
 // Check that third to fifth bytes are between '0' and '9'
 // make sure to convert from chars to integers (subtract 48, the ASCII constant) and multiply accordingly
 c4 = (command[4]-'0');
 c3 = (command[3]-'0');
  c2 = (command[2]-'0');
  if (c4 \ge 0 \& c4 \le 9 \& c3 \ge 0 \& c3 \le 9 \& c2 \ge 0 \& c2 \le 9) 
   steps = c4+10*c3+100*c2;
  else {
  check = '5';
 //steps = 1*(command[4]-'0')+10*(command[3]-'0')+100*(command[2]-'0');
 // If everything is fine, move the motors
  if (check == '5') {
   // if check == '5' something went wrong
   // do nothing, it will print out '5'
 else {
  int_check = move_steps (steps, dir, motor);
   check = int check; // divided into two steps to make sure the conversion is made correctly
 // Check is sent over the serial back to microprocessor:
         '0' if motor moved
 //
         '1' if switch 1 is pressed
  //
 //
            if switch 2 is pressed
 //
            if switch 3 is pressed
         '4' if switch 4 is pressed
 //
         '5' if command is bad
 //
  Serial.print(check);
  // Reset the command
 command[0] = '\0';
  Serial.flush();
// Delay in ms
delay(5);
```