



Field Service Action 22N08

Reissue 1: March 7, 2023 (Destroy previous copy).

Reason of Reissue: ***Added some Administrative Information.*** Changes are highlighted in *Yellow Italic font.*

To: All Ford Dealerships

February 09, 2023

Attention: Ford Dealer Principal
Ford Dealer Service, Parts, Sales & Pre-Delivery Managers
Ford Dealer Stock Controllers & Campaign Coordinators

EXTENDED WARRANTY SERVICE PROGRAM

SUBJECT: 22N08 - EVEREST - DOOR CORROSION REPAIR

Special Attention: The Dealer Field Service Action Co-ordinator has overall responsibility for implementing this action within your Dealership and Branches.

Introduction

Some affected vehicles may exhibit corrosion on the inner door closure surfaces where the inner and out panels meet – known as the ‘closure hem’. The main reason for this corrosion is due to the excessive hem gap allowing water ingress into the hem area. Corrosion presents as minor bubbling under the paint surface.

Program Terminology

All references to Corrosion in this FSA are limited to Filiform Corrosion.
Non-Filiform corrosion is not covered by this FSA.

Reason for Extension

In some of the affected vehicles, customers may return to the dealer with complaints after the original warranty period expires.

This program extends the Door Corrosion Warranty coverage to 10 years of service from the warranty start date of the vehicle.

This program is only applicable if corrosion is identified and has been approved by Ford in FSA 22M02.

This is a one-time repair program. Once the program has expired, Service Part Warranty (SPW) and Extended Service Plan (ESP) may be eligible. Coverage is automatically transferred to subsequent owners.

Dealer Action

Refer to the lead program FSA 22M02: Everest – Door / Hood / Liftgate Corrosion Inspection Only to determine if this FSA is applicable.

Once the Prior Approval is received on FSA 22M02 for repairs on Door Corrosion, only then dealers to proceed with repair following Service Procedure in this FSA 22N08 Bulletin.

This service must be performed at no charge to the vehicle owner.

Xtime FSA/ Recall Integration

As this is an extended warranty, it is a field service action that is only actioned if the vehicle actually experiences the concern or is found to be an issue during a schedule service. Therefore, customers will not be using Xtime to book in for this repair, and the repair is not automatically required on every vehicle.



Field Service Action 22N08

Vehicles Affected

<u>Vehicle Line</u>	<u>Model Year</u>	<u>Plant</u>	<u>Earliest Production</u>	<u>Latest Production</u>
Everest	2015 - 2020	AAT (Thailand)	11 th June 2015	17 th December 2019

A total of 21,790 vehicles are affected in Australia.

NOTE: All Dealers can obtain a copy of the Campaign via the FMC Dealer or PTS websites.

NOTE: Dealers can obtain a list of eligible vehicles from the PTS Website www.proservicetech.com by selecting Quick Links and then FSA VINs.

Service Procedure

Refer to the Service Procedure.

Parts Requirement

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>
NIWZ 7823640 A	Kit Door Assembly Front and Rear (All 4 Doors)	1

Claim Instructions

Claim Type 41, Causal Part No. 22N08, Condition Code 79.

<u>Pre-Defined Repair</u>	<u>PDR No.</u>	<u>Labour Time</u>
Admin and Post Sublet Repair Inspection	FSA22N081	0.4 Hours

Sold Vehicles

- *Correct only affected vehicles if corrosion identified and approved in FSA 22M02.*
- *Dealers are to prioritise repairs of customer vehicles over repairs of new and used vehicle inventory.*

Stock Vehicles

- *Do not perform this program unless the affected vehicle exhibits the covered condition during regular vehicle stock audits.*

Owner Refunds

- *Dealers are also entitled for refunds on extra repairs OR any removal & refitment for accessories that may be required to replace the effected closures. Please mention all the details while submitting the Prior-approval request. Non-covered repairs, or those judged by Ford to be excessive, will not be reimbursed.*

Rental Vehicles

- *Dealers are pre-approved for providing customer with a rental vehicle for FSA approved repairs only.*
- *All rental vehicles to be claimed in the connected repair FSA.*

NOTE: Rental vehicles are not permitted for Inspection FSA 22M02.

Displaced Parts

All displaced parts (if any) must be handled in accordance with the Warranty and Policy Manual (Section G, Attachment G).

Completion Date

It is estimated that this campaign will be completed by Dec 31, 2023. If, however, the campaign remains outstanding after this date, affected vehicles identified on the Vehicle Inquiry Screen in SERVIS2 must continue to be completed and claimed.

TIM NETHERCOTE
Service Engineering Manager
FCSD
(* +61 3 8301 2903)

Enquiries to Anna Wu - Email: awu6@ford.com



22N08 - EVEREST - DOOR CORROSION REPAIR - EXTENDED WARRANTY PROGRAM

RECOMMENDED REWORK PROCEDURES

Thoroughly read and understand rework instructions prior to rework.

OVERVIEW

Some affected vehicles may exhibit corrosion on the inner door closure surfaces where the inner and out panels meet – known as the ‘closure hem’. The main reason for this corrosion is due to the excessive hem gap allowing water ingress into the hem area. Corrosion presents as minor bubbling under the paint surface.

PROGRAM TERMINOLOGY

All references to Corrosion in this FSA are limited to Filiform Corrosion.
Non-Filiform corrosion is not covered by this FSA.

SERVICE PROCEDURE

Refer to the lead program FSA 22M02: Everest – Door / Hood / Liftgate Corrosion Inspection Only to determine if this FSA is applicable. Once the Prior Approval is received based on FSA 22M02 including the decision on the Body Panel repairer from Ford, only then are dealers to follow this repair procedure.

REPAIR INSTRUCTIONS

1. If any door exhibits corrosion, all 4 doors must be replaced, use the repair kit part no. as detailed.
2. Parts department to order the repair kit and forward to the Body Panel Repairer.

NOTE: Please advise your sublet repairer that Ford recommends that a fast-flowing cavity wax (equivalent to Teroson from Henkel WX215) and butyl anti vibration closure patches (equivalent to 3M™ Sound Deadening Pads 08840) be used in the repair – please refer to GSB 22-7054 (published on PTS) for further information and provide them with a copy of this document if needed.

3. Dealers are reminded that it is their responsibility to ensure the standard of repairs completed by their sublet repairers is of an acceptable standard to their customer. Any repeat repairs for poor workmanship, paint finish etc. will not be covered under Ford Warranty OR the FSA and should be at the expense of the sublet repairer or Ford dealership.

[END]