



Field Service Action FSA 26B04

19 May 2026

Customer Satisfaction Program 26B04

Certain 2025-2026 Model Year Ranger / Super Duty and Everest Vehicles Driveline Control Module (DLCM) Replacement

To: All Ford Dealerships
Attention: Ford Dealer Principal
Ford Dealer Service, Parts, Sales & Pre-Delivery Managers
Ford Dealer Stock Controllers & Campaign Coordinators

OWNER-NOTIFIED SERVICE PROGRAM

**SUBJECT: 26B04 - Certain 2025-2026 Model Year Ranger / Super Duty and Everest Vehicles
Driveline Control Module (DLCM) Replacement**

Special Attention: The Dealer Field Service Action Co-ordinator has overall responsibility for implementing this action within your Dealership and Branches.

Introduction

In some of the affected vehicles, the Driveline Control Module (DLCM) was not completely water sealed during the manufacturing process. In the event of water ingress into the DLCM, the vehicle will lose 4x4 functionality and the ability to select 4x4 drive modes via the switch. The switch will lose illumination, and a "check 4x4" message will appear on the cluster display. The vehicle's default 2x4 (2WD) functionality will not be affected.

NOTE: In some markets the DLCM is referred to as the AWD or 4WD module.

Service Action

Dealers are to replace the DLCM. This service must be performed on all affected vehicles at no charge to the vehicle owner.

Program Terms

This program will be in effect through 31 May 2029. There is no mileage limit for this program.

Owner Notification Mailing Schedule

Owner notification will be communicated. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

Xtime FSA/ Recall Integration

For Service appointments Xtime will reflect an FSA time of 0.4hrs preloaded in line with the PDR code. For Dealers who wish to adjust the time, please firstly create the corresponding operation code in your DMS using your preferred choice of prefix and the new field service action number of 26B04: e.g. 99FOFSA26B04. The operation code that you create in your DMS can allow for labour time and/or parts required to complete this FSA. Please contact Xtime support on 03 8585 3000 if you are unsure of the operation code format prior to the creation.



Models Affected: A total of 120 vehicles are affected in Australia.

Vehicle	Model Year	Assembly Plant	Build Dates
Ranger	2025	FTM	September 15, 2025 through September 30, 2025
	2026	AAT- RAYONG	October 2, 2025 through October 15, 2025
Everest	2026	AAT- RAYONG	September 17, 2025 through October 8, 2025

NOTE: Affected vehicles may be held in Dealer new/used car stock or be present at the Dealership for service-related purposes. **All** vehicles should be checked on PTS for Field Service Action eligibility and **any** outstanding Field Service Actions completed **prior** to vehicle departure in accordance with the Warranty & Policy Manual, Section E 3.4 and I 3.

NOTE: All Dealers can obtain a copy of the Campaign (which includes a sample copy of the Customer Letter) via the FMC Dealer or PTS websites.

NOTE: Dealers can obtain a list of eligible vehicles from the PTS Website www.proservicetech.com by selecting Quick Links and then FSA VINs.

Parts Requirements

Part Number	Claim Qty	Package Order Qty	No.in Package	Description
P1WZ-7P238-J	1	1	1	DLCM Ranger/Everest/Raptor
P1WZ-7P238-D	1	1	1	DLCM – Super Duty

Additional Repair (Labor Time And/Or Parts)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For vehicles within new vehicle bumper-to-bumper warranty coverage, follow existing warranty and policy guidelines for related damage claims. No approval is required for these vehicles.
- For vehicles outside new vehicle bumper-to-bumper warranty coverage, please send a request for prior approval to the Prior Approval team.

Claims Preparation And Submission

Software Verification Approval Code Requirement: This Field Service Action is exempt from the Software Verification Approval Code Requirement.

Related Damage/Additional labor and/or parts: Must be claimed as Related Damage on a separate repair line from the FSA with the same claim type and subcode as described in Claim Entry above.

IMPORTANT: Click the Related Damage Indicator radio button.

Labor Allowances

Description	Labor Operation	Labor Time
For Ranger and Everest: Remove and replace the DLCM Includes time to run PMI process using FDRS This labor operation code closes the FSA.	26B04B	0.4 Hours
Mobile Service: Can be used when the repair takes place away from the dealership	26B04MM	0.5 Hours
PDR Description	PDR No.	Labor Time
For Ranger and Everest: Remove and replace the DLCM Includes time to run PMI process using FDRS	FSA26B041	0.4 Hours
For Ranger Super Duty: Remove and replace the DLCM Includes time to run PMI process using FDRS	FSA26B042	0.4 Hours



NOTE: Where Mobile Repair was used, Dealers should also use an additional line on the same repair order and on the same day to ensure the additional 0.5 hours labor operation code is captured.

Mobile Repair

This FSA is suitable for Mobile Repairs.

Displaced Parts

All displaced parts must be handled in accordance with the Warranty and Policy Manual (Section G, Attachment G).

Completion Date

It is estimated that this campaign will be completed by 31 May 2027. If, however, the campaign remains outstanding after this date, affected vehicles identified on the Vehicle Inquiry Screen in PTS must continue to be completed and claimed.

TIM NETHERCOTE

Service Engineering Manager AUS/NZL - FCSD

(* +61 3 8301 2903)

Matthew Price

Service Operations Manager AUS/NZL - FCSD

(mprice63@ford.com)

Customer Satisfaction Program 26B04

Certain 2025-2026 Model Year Ranger, Ranger Super Duty and Everest Vehicles
Driveline Control Module (DLCM) Replacement

Thoroughly read and understand rework instructions prior to rework.

OVERVIEW

In some of the affected vehicles, the Driveline Control Module (DLCM) was not completely water sealed during the manufacturing process. In the event of water ingress into the DLCM, the vehicle will lose 4x4 functionality and the ability to select 4x4 drive modes via the switch. The switch will lose illumination, and a "check 4x4" message will appear on the cluster display. The vehicle's default 2x4 (2WD) functionality will not be affected.

NOTE: In some markets the DLCM is referred to as the AWD or 4WD module.

SERVICE PROCEDURE

NOTE: Before beginning any service procedure refer to the Workshop Manual (WSM) Section 100-00 General Information - Health and Safety Precautions. Failure to follow this instruction may result in serious personal injury.

Ranger/Everest Vehicles

1. Replace the DLCM/AWD module. Follow the Workshop Manual (WSM) procedures in section 307-07A *Four-Wheel Drive Systems – All-Wheel Drive (AWD) Module*

NOTE: Long sleeves recommended for removal of module, take care on the edges of the fender.

Bronco Vehicles

1. Replace the DLCM/AWD module. Follow the WSM procedures in section 307-07 for Automatic transmission vehicles and 307-08 for manual transmission vehicles.

[END]



SAMPLE LETTER ONLY

xxxxxx, 2026

VIN NUMBER / 26B04M1

Name

Organisation

Address1

Address2

Address3

Service Program 26B04

Your Vehicle Identification Number: VIN NUMBER

Registration Number: REGNUMBER

At Ford Motor Company, we are committed not only to building high-quality, dependable products but also to building a community of happy, satisfied customers. To demonstrate that commitment, we are providing a no-charge Customer Satisfaction Program for your vehicle with the VIN shown above.

What is the issue?

On your vehicle, it may be possible that the waterproof seal on the Driveline Control Module (DLCM) was not fully sealed during the manufacturing process..

What is the effect?

This improper sealing may result in water intrusion, leading to part failure. In the event of water intrusion to the DLCM, the vehicle will lose 4x4 functionality and the ability to select 4x4 drive modes via the switch. The switch will lose illumination, and a "check 4x4" message will appear on the cluster display. The vehicle's default 2x4 (2WD) functionality will not be affected.

What will Ford and your dealer do?

Parts are now available to repair your vehicle.

In the interest of customer satisfaction, Ford Motor Company has authorized your dealer to replace the DLCM free of charge (parts and labor) under the terms of this program.

This Customer Satisfaction Program will be in effect until May 31, 2029 regardless of mileage. Coverage is automatically transferred to subsequent owners.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do?

Please call your dealer without delay to schedule a service appointment for Customer Satisfaction Program 26B04. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

If you do not already have a servicing dealer, you can access www.ford.com.au for dealer addresses, maps, and driving instructions.

Ford wants you to have this service action completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed, Therefore please have this service action performed as soon as possible.



NOTE: If available in your market, you can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play.

Mobile Service

Ford Mobile Service may be offered by your dealer, contact your dealer for details.

What if you no longer own this vehicle?

You have received this notice because our records indicate that you are the current owner of the vehicle described at the start of this letter. If you are no longer the owner of this vehicle, please complete the owner details change advice (following page).

Can we assist you further?

If you still have concerns, please call us on 13 FORD (13 3673) and one of our Customer Relationship representatives will be happy to help you.

Yours faithfully,
TIM NETHERCOTE
Service Engineering Manager
Ford Motor Company of Australia Pty Ltd



CHANGE OF DETAILS NOTIFICATION

V.I.N.

VIN NUMBER

Owner Details

If you still own the vehicle but your details have changed, would you please complete the section below with your new details and then return this complete letter in the pre-addressed/pre-paid envelope. **Please also refer to Privacy Collection Statement below.**

State

New Registration Number (if applicable)

New Name

New Address

New Suburb

New Postcode

New Phone Number

New Mobile Number

New Email Address

Primary Driver Details

If you are the registered owner, but not primary driver, and would like Ford to make contact with the primary driver of this vehicle, please ask the primary driver to complete their details below and we will organise for a recall notice to be sent to that address. **Primary driver, please refer to Privacy Collection Statement below.**

Driver Name

Driver Address

Driver Suburb

Driver Postcode

Driver Phone Number

Driver Mobile Number

Driver Email Address

OTHER CHANGES

Please tick (✓) the appropriate box and sign:

☐ I no longer own this vehicle

Print Name: _____

☐ This vehicle has been written off.

☐ This vehicle has been stolen

Signature: _____



VIN NUMBER