



TECHNICAL SERVICE BULLETIN

26-2227

Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) P2C7A-00

18 May 2026

Model:

Ford 2026 Ranger Super Duty	Equipped With A 3.0L Power Stroke Diesel Engine
--------------------------------	---

Issue: Some 2026 Ranger Super Duty vehicles equipped with a 3.0L Power Stroke diesel engine may exhibit an illuminated MIL with only DTC P2C7A-00 stored in the Powertrain Control Module (PCM)

Action: Should a vehicle present with the above condition, technicians are advised to refer to the Service Procedure below.

Labor Times

Description	Operation No.	Time
Connect the Ford Diagnosis and Repair System (FDRS) to the vehicle and Reflash the Powertrain Control Module (PCM) to the latest service calibration using the latest FDRS software release	262227A	0.5 Hrs.
Road test the vehicle and ensure correct operation	262227B	0.2 Hrs.

Repair/Claim Coding

Causal Part:	12A650
Condition Code:	04

PDR Table

PDR Code	Description	Time
TSB262227	Connect the Ford Diagnosis and Repair System (FDRS) to the vehicle and Reflash the PCM to the latest service calibration using the latest FDRS software release and Road test the vehicle and ensure correct operation	0.7 Hrs.

Service Procedure

1. Connect the Ford Diagnosis and Repair System (FDRS) to the vehicle.
2. Reflash the Powertrain Control Module (PCM) to the latest service calibration using the latest FDRS software release.
3. Road test the vehicle and ensure correct operation.

© 2026 Ford Motor Company
All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.