



To: All Ford Dealerships

August 25, 2023

Attention: Ford Dealer Principal
Ford Dealer Service, Parts, Sales & Pre-Delivery Managers
Ford Dealer Stock Controllers & Campaign Coordinators

EXTENDED WARRANTY SERVICE PROGRAM

SUBJECT:22N17 ESCAPE - Power Window Switch Chrome Tip Replacement - Single Repair

Special Attention: The Dealer Field Service Action Co-ordinator has overall responsibility for implementing this action within your Dealership and Branches.

Introduction

On the affected vehicles, one or more power window switch chrome tips may peel or separate and expose a sharp edge.

If an affected vehicle exhibits this condition, Dealers are requested to replace all seven-power window switch chrome tips on the vehicle. This service must be performed at no charge to the vehicle owner.

Program Terms

This program provides a no-cost, one-time repair (if needed) to the power window switch chrome tips for 10 years of service or 240,000 kilometers from the warranty start date of the vehicle, whichever occurs first.

If a vehicle has already exceeded either the time or mileage limits, this no-cost, the one-time repair will last through November 30, 2023. This is a one-time service program. Coverage is automatically transferred to subsequent owners.

Sold Vehicles

- Only owners with affected vehicles that exhibit the covered condition will be directed to dealers for repairs.
- Dealers should repair any affected vehicles that experience power window switch chrome tips peeling, whether or not the customer has received a letter.
- Dealers are to prioritise repairs of customer vehicles over repairs of new and used vehicle inventory.

Stock Vehicles

- Do not perform this program unless the affected vehicle exhibits the covered condition.

Owner Refunds

- Ford Motor Company is offering a refund for owner-paid repairs covered by this program if the repair was performed before the date of the Owner Notification Letter. This refund offer expires 30th November 2023.
- Dealers are also pre-approved to refund owner-paid emergency repairs that were performed away from an authorized servicing dealer after the date of the Owner Notification Letter. Non-covered repairs, or those judged by Ford to be excessive, will not be reimbursed
- Refunds will only be provided for the cost associated with replacement of the window switch assembly due to chrome peeling on the switch tip.



Field Service Action 22N11

Xtime FSA/ Recall Integration

As this is an extended warranty, it is a field service action that is only actioned if the vehicle actually experiences the concern or is found to be an issue during a schedule service. Therefore, customers will not be using Xtime to book in for this repair, and the repair is not automatically required on every vehicle.

Vehicles Affected

<u>Vehicle Line</u>	<u>Model Year</u>	<u>Plant</u>	<u>Earliest Production</u>	<u>Latest Production</u>
Escape	2020	Valencia (Spain)	9 th May 2019	31 st July 2020

A total of 784 vehicles are affected in Australia.

NOTE: Affected vehicles may be held in Dealer new/used car stock or be present at the Dealership for service-related purposes. All vehicles should be checked on SERVIS2 for Field Service Action eligibility and any outstanding Field Service Actions completed prior to vehicle departure in accordance with the Warranty & Policy Manual, Section E 3.4 and I 3.

NOTE: All Dealers can obtain a copy of the Campaign via the FMC Dealer or PTS websites.

NOTE: Dealers can obtain a list of eligible vehicles from the PTS Website www.proservicetech.com by selecting Quick Links and then FSA VINs.

Service Procedure

Refer to the attached procedure.

Parts Requirement

Part Number	Description	Quantity
LB5Z-14A268-AB	Window Switch Chrome Tip (7 required, 7 per pkg)	1

Claim Instructions

Claim Type 42, Causal Part No. 22N17, Condition Code 79.

<u>Pre-Defined Repair</u>	<u>PDR No.</u>	<u>Labour Time</u>
Replace all 7 power window chrome tips	FSA22N171	0.3 Hrs

All displaced parts (if any) must be handled in accordance with the Warranty and Policy Manual (Section G, Attachment G).

Completion Date

It is estimated that this campaign will be completed by August 31, 2024. If, however, the campaign remains outstanding after this date, affected vehicles identified on the Vehicle Inquiry Screen in SERVIS2 must continue to be completed and claimed.

TIM NETHERCOTE
FCSD Service Engineering Manager
(* +61 3 8301 2903)

Enquiries to Anna Wu (Email: awu6@ford.com)

22N17 ESCAPE - Power Window Switch Chrome Tip Replacement - Single Repair

RECOMMENDED REWORK PROCEDURES

Thoroughly read and understand rework instructions prior to rework.

OVERVIEW

On the affected vehicles, one or more power window switch chrome tips may peel or separate and expose a sharp edge

SERVICE PROCEDURE

NOTE: A video of the service procedure can be found in below link or by clicking 

https://players.brightcove.net/5803674275001/iwgRlzpny_default/index.html?videoId=6320929321112

Inspect all window switches to check if any of the window switch chrome tips are peeling.

Yes	Proceed to Step 1.
No	This recall does not apply

1. Using a pair of diagonal cutting pliers, cut halfway through the chrome tip with taking care to not damage the black painted part of the window switch assembly. Refer Figure 1.

NOTE: If the black painted part of the window switch assembly is damaged the window switch assembly must be replaced. Refer to the Workshop Manual (WSM) procedures in Section 501-11.

NOTE: Passenger side window switch assembly shown, all other window switch assemblies are similar.



FIGURE 1

NOTE: The diagonal cutting pliers must be inserted at a 90° angle to the window switch assembly to prevent damage to the window switch assembly. Refer Figure 2.

NOTE: Passenger side window switch assembly shown, all other window switch assemblies similar.



FIGURE 2

2. Using the diagonal cutting pliers remove the chrome tip. Refer Figure 3.

NOTE: Driver side window switch assembly shown, all other window switch assemblies are similar.



FIGURE 3

3. Visually confirm no broken or loose parts are left inside the window switch assembly

4. Align the new window switch tip with the window switch assembly and press firmly until the new window switch tip locks into place. Refer Figure 4

NOTE: Passenger side window switch assembly shown, all other window switch assemblies are similar.



Figure 4

5. Repeat Inspection and steps 1-4 for all other window switch assemblies.
6. Cycle all the windows up and down a couple of times to make sure no debris is affecting the functionality of the window switches

[END]



SAMPLE CUSTOMER LETTER – DO NOT DISTRIBUTE

xxxxxx, 2023

VIN NUMBER / 22N17

Name

Organisation

Address1

Address2

Address3

Service Program 22N17

Your Vehicle Identification Number: VIN NUMBER	Registration Number: REGNUMBER
--	--------------------------------

At Ford Motor Company, we are committed not only to building high quality, dependable products, but also to building a community of happy, satisfied customers. To demonstrate that commitment, we are providing a no-charge Customer Satisfaction Program for your vehicle with the Vehicle Identification Number shown above.

What is the issue?	On your vehicle, one or more of the power window switch chrome tips may peel or separate.
What is the effect?	If the window switch chrome tip peels or separates, it may result in an exposed sharp edge.
What will Ford and your Dealer do?	If your vehicle's power window switch chrome tips require replacement due to peeling or separating and your vehicle is within the indicated time/mileage limitations below, Ford Motor Company has authorized your dealer to replace all seven power window chrome tips free of charge (parts and labor). This is a one-time repair program. This one-time repair of power window switch chrome tip is available for a total of 10 years or 240,000 kilometres from the warranty start date, whichever occurs first. If your vehicle has already exceeded either time or mileage limits listed above, this one-time repair offer will last through 30th November 2023. Coverage is automatically transferred to subsequent owners.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.
What should you do?	You do not need to return to your dealer for this repair unless you have one or more of the power window switch chrome tips peeling or separating. Please keep this letter as a reminder of the one-time repair offer for your power window switch chrome tips. If any of the power window switch chrome tips requires replacement, and your vehicle is within the indicated time/mileage limitations, contact your dealer to schedule a service appointment. Provide the dealer with the VIN of your vehicle to schedule a service appointment for Customer Satisfaction Program 22N17. The VIN is printed near your name at the beginning of this letter. Your dealer will replace the part at no charge. If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instruction.
Have you previously paid for this repair?	If you paid to have this service done before the date of this letter, you may be eligible for a refund. Refunds will only be provided for service related to repair description. To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer before 30th November 2023 . To avoid delays, do not send receipts to Ford Motor Company.



FORD MOTOR COMPANY OF AUSTRALIA PTY LTD
Lvl 1, 600 Victoria St
Richmond VIC 3121

What if you no longer own this vehicle?

You have received this notice because our records indicate that you are the current owner of the vehicle described at the start of this letter. If you are no longer the owner of this vehicle, please complete the owner details change advice (overleaf).

Can we assist you further?

If you still have concerns, please call us on 13 FORD (13 3673) and one of our Customer Relationship representatives will be happy to help you.

Yours faithfully,

TIM NETHERCOTE
Service Engineering Manager
Ford Motor Company of Australia Pty Ltd



V.I.N.

VIN NUMBER

If you still own the vehicle but your details have changed, would you please complete the section below with your new details and then return this complete letter in the pre-addressed/pre-paid envelope. ***Please also refer to Privacy Collection Statement below.***

If you are the registered owner, but not primary driver, and would like Ford to make contact with the primary driver of this vehicle, please ask the primary driver to complete their details below and we will organise for a recall notice to be sent to that address.
Primary driver, please refer to Privacy Collection Statement below.

Driver Mobile Number Driver Email Address

Please tick (✓) the appropriate box and sign:

- ☐ I no longer own this vehicle
- ☐ This vehicle has been written off
- ☐ This vehicle has been stolen

Print Name: _____

Signature: _____



VIN NUMBER

Please fill in below if you are no longer the owner of the vehicle and know of who you disposed the vehicle to. This can include the details of your car dealer, insurance company or private citizen whom you transferred the vehicle to.

[illegible][illegible][illegible][illegible][illegible]

Thank you for completing this form. The personal information you have provided will be used by Ford Motor Company of Australia Pty Ltd (Ford Australia) to contact you about your Ford vehicle or related products and services and for quality assurance and market research purposes. Ford Australia may disclose your personal information to its dealers, its related companies and third parties who provide it with (or help it provide) products and services, including to overseas locations such as the USA, India, China and Singapore. Ford Australia's privacy policy is available at www.ford.com.au and states how you can seek to access or correct any personal information Ford holds about you, how to complain about a privacy breach by Ford and how Ford will deal with a privacy complaint. You can contact Ford Australia on 13FORD (13 36 73) or by emailing foacust1@ford.com.