PSU+ Power Supply Unit +	
PSU- Power Supply Unit -	
RX3 Resistor Strip 100 <sub>Ω</sub>	
X2 Terminator Block to Arduino	
U11 Hall Effect Sensor R11 Resistor 100.	
U12 Hall Effect Sensor R12 Resistor 100.	
U13 Hall Effect Sensor R13 Resistor 100 <sub>Ω</sub>	
U14 Hall Effect Sensor R14 Resistor 100Ω	
U21 Hall Effect Sensor R21 Resistor 100₁	
U22 Hall Effect Sensor R22 Resistor 100 <sub>0</sub>	
U23 Hall Effect Sensor R23 Resistor 100 <sub>Ω</sub>	
U24 Hall Effect Sensor R24 Resistor 100Ω	
U31 Hall Effect Sensor R31 Resistor 100₁	
U32 Hall Effect Sensor R32 Resistor 100 <sub>0</sub>	
U33 Hall Effect Sensor R33 Resistor 100₁	
U34 Hall Effect Sensor R34 Resistor 100 <sub>Ω</sub>	
U41 Hall Effect Sensor R41 Resistor 100 <sub>Ω</sub>	
U42 Hall Effect Sensor R42 Resistor 100.	
U43 Hall Effect Sensor R43 Resistor 100 <sub>Ω</sub>	
U44 Hall Effect Sensor R44 Resistor 100.	
Date:   Ver:   Ext:   By:   Drawing Name:   Drawing Nr:   Updated By:   Original By:   16.02.2021   1.00   Eivind Lundeberg	
16.02.2021 1.00 Eivind Lundeberg 4x4 Sensor Array 3-01 E.L. Eivind Lundeberg	cī UiA