Evaluation Warning: The document was created with Spire.PDF for Python. Evaluation Warning: The document was created with Spire.PDF for Python.

PERSONNEL TRACKING CEDIVICE TYPE (DECTORATION)



The color of the								SERVICE	TYPE (RES	TUKAI	ION)										PROPE	RTYRESTOR	ATION
Process Proc	<u> </u>	FORM VERIFIER L	± 1 1111						LOSS CAUSE		CODE	LOCATION				WEATHER					CODE VE	HICLE NAME (TABLE)
Property	C # C	START DATE	START DAY		10110	08149			FIRE		L00	Site				HUMID	Ne	w		RETURN	529 PIC	KUP, SUV OR CA	R
Martin M	DO	1/15/24	Monday	JOB NAME					WATER/FLOOD		L01				_ [TEMP 2	Ongoin	ıg 🗖	Date -		530 VAI	N, PASSENGER/C	ARGO
151-24 Monday M	TS	STOP DATE	END DAY	Greystar 401	ate St			WIND		L02				· F	SNOW	1 = ;				518 TRI	JCK-MOVING/BO	OX/BOARD UP	
Selection Sele		1/15/24	Monday	•											- =	_			•				
EST - 11524 - 35 Pro	CREW SHE		TVIOITAL J	1401 S StateSt					=						- =	_	Hol	d _	(explain why in	description)			
Sect 115 24 35			GIT DATE-LAST 3 #'S OF VERIFIERS JDE							HQUAKE					. 누	ן עטאוועע ן	Othe	, F					
Second Company Property Second Company Second Com		_ 1	1 7 0 4 0 7				TOOL BOY TRAINING		 						. 片	J		_					1
The contract The	ES	- I	1524 - 35						⊔		L06				. L	J	_		2.1				
Second Part Commence Comm			250001115) / XC			FILL IN VEHIC	CLE CODE AND C	НЕСК ВОХ
101									TOTAL HOURS	Z		HOURS	ILS				IDE SHEET	Σ	SEE TABLE	VOLID SIGNAT	PERSONN	STUE ADDROVAL TO	O DAY VOLID
101 1786035 Alex morales	OFFICE	ID#				START	START TIME	STOP TIME		ATI		RY	100	T TES	ARNESS	5			VEHICLE	DOCUMENTED HO	JURS WORKED. A	A LACK OF SIGNATU	RE MAY RESULT
101 1786035 Alex morales							STOP TIME				CODE	PHASE	MALL	?P - F	ا <u>ب</u>			SHAR	CODE				
1011 1786035 Alex mora les 1530 0 2300 7.50 1.00 EME 7.50 1.01	1		PRINT FIRST <u>THEN</u> LAST NAME		\vdash						ГМГ		SN		<u> </u>	<u> </u>	+-	1.	520	SIC	NATURE-I	END OF SHIF	
1011 1910994 Gustavo galvez 1530 0 2300	1011	1786035 Alex mc		orales		1530			7.50	LUU		7.50	N	N N	N	N Na	Na	N					
1011 1910994 Gustavo galvez 1530 0 2300 8.00 0.00 EME 8.00 N N N N N N N N N	2			1		1.700			7.50	1.00	EME	7.50		+		3. T	\	\Box					VERIFIER
1011 707 Se bastian flores 1500	1011	₁₁ 1910994 Gustavo		galvez		1530		2300	, 10 0	200		7.00	N N	1 N	N	N Na	Na	N					Am
101 707 Oscar mendez	3		Q . 1		1500	0	2200	8.00	L00	EME	8.00			N.	N NT-	N.T.	T _N					VERIFIER	
1011 707 Oscar mendez 1500 0 2300 8.00 150 EME 8.00 N N N N N N N N N	1011	/0/	Se bastia	n nores		1500	0	2300					N I	N N	IN	Na	Na	IN	RENTAL				Am
1011 707 Juan david osario 1500 0 2300 8.00 100 EME 8.00 N N N N N N N N N	4	1011 707 Osca r m		nandaz		1500	0	2300	8.00		EME	8.00	N N	N N	N	N NTO	No	N					
1011 707 July and avid osario 1500 0 2300 000 100	1011			ie nuez		1300	0									" INa	INa	\vdash					
	1011	707	707 Iuan david o			1500	0	2300	8.00	L00	EME	8.00	N N	ı N	N	$N \mid Na$	Na	N					
Control Cont	1011	101	Juan davi			1300	0	2300					+	+	\vdash	114	114	\vdash	RENTAL				
March Marc								-					N 1	I N	N	N		N	RENTAL				VEIII IEIX
	7												+	+	\vdash			\vdash	LINENIAL				VERIFIER
Section													N I	1 N	N	N		N	RENTAL				
STEP - PROVED REPORT NAME STEP - ADDIT NAME OF	8																						VERIFIER
RESPONSIBILITY OF APPROVINCE PLANT COVER PER AL INCLUSION SHEET COVER PER								1					1 N	N N	N	N		N	RENTAL				
20	9												N. P	ı Nı	N.	N		I NI					VERIFIER
12 N N N N N N N N N													IN I	N 10	IN	IN .		IN	RENTAL				
12 N N N N N N N N N	10												N I	, l	$ _{N} $	N		$ _{N} $					VERIFIER
22 N N N N N N N N N													4	+	\sqcup			Ш	RENTAL				VEDIEIED
13 STEP 1-POINT REPROVER PLANE COMPLETE ALL REQUESTS BELOW	111												N 1	ı N	N	N		N	Пасити				VERIFIER
13 N N N N N N N N N N N N N N N N N N	12												+	+	\vdash	_		\vdash	KENTAL				VERIFIER
RESPONSIBILITY OF APPROVER: PLENE COMPLETE ALL REQUESTS BELOW Verification V								1					N 1	I N	N	N		N	RENTAL				
RESPONSIBILITY OF APPROVER: PLEASE COMPLETE ALL REQUESTS BELOW VERIFIED VERIFIED	13																						VERIFIER
RESPONSIBILITY OF APPROVER: PLEASE COMPLETE ALL REQUESTS BELOW Visinify Total Links Visinify Links Visinif								1					ו א	1 N	N	N		N	RENTAL				
RESPONSIBILITY OF APPROVER; PLEASE COMPLETE ALL REQUESTS BELOW STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-TOTAL MISS STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-TOTAL MISS STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-TOTAL MISS STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-TOTAL MISS STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION? STEP 3-DID THIS FORM FOR COMPLETION. STEP 3-DID THI	14												N I	J N	N	N		N					VERIFIER
STEP 1-PRINT APPROVER NAME JORDAN HANKEY II "NOU MUST VERIFY & COMPLETTE ALL OUTSTANDING ISSUES IN "ULDING TOP SECTION OF FORM WORK DESCRIPTION: BASED ON LOCATION(S) WORKED AND PHASE CODE(S), PLEASE DESCRIBE WHAT WORK THE CREW PERFORMED Arrived on site & met with engineer. We did a walkthrough of the affected areas 5 units affected in total unit 502,503,513,415 and gym area. Before starting work we got a work authorization signed. Updates for the units in 1401 Unit 514 The water was coming from the electrical room it affected the wall in the back towards the electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover 6th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the waiter puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and air mover to dry of fthe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some raps and then we set up a dehumidifier We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some raps and then we set up a dehumidifier We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some raps and then we set up a dehumidifier														11					RENTAL				
JORDAN HANKEY IF "N", YOU MUST VERIFY & COMPLETE ALL OUTSTANDING ISSUES NCLUDING TOP SECTION OF FORM WORK DESCRIPTION: BASED ON LOCATION(S) WORKED AND PHASE CODE(S), PLEASE DESCRIBE WHAT WORK THE CREW PERFORMED Arrived on site & met with engineer. We did a walkthrough of the affected areas 5 units affected in total unit 502,503,515,415 and gym area. Before starting work we got a work authorization signed. Updates for the units in 1401 Unit 514 The water was coming from the electrical room it affected the wall in the back lowards like electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover 6th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the celling of the door entrance and then we set up a dehumidifier and a air mover to dry of the celling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier We wished down the water puddles and what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier				-	O TOTALS																		
WORK DESCRIPTION: BASED ON LOCATION(S) WORKED AND PHASE CODE(S), PLEASE DESCRIBE WHAT WORK THE CREW PERFORMED Arrived on site & met with engineer. We did a walkthrough of the affected areas 5 units affected in total unit 502,503,515,415 and gym area. Before starting work we got a work authorization signed. Updates for the units in 1401 Unit 514 The water was coming from the electrical room it affected the wall in the back towards the electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover 5th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of the ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier			IE "N" VOLLI				ioiv:	П						+	□W⊦				WHEN				
Arrived on site & met with engineer. We did a walkthrough of the affected areas 5 units affected in total unit 502,503,515,415 and gym area. Before starting work we got a work authorization signed. Updates for the units in 1401 Unit 514 The water was coming from the electrical room it affected the wall in the back towards the electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover 5th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a ir mover to dry of the ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier									39	\leftarrow	\longrightarrow	39		wo							Jordan	Hankey	-
Unit 514 The water was coming from the electrical room it affected the wall in the back towards the electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover 5th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of fithe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier	WORK DE	SCRIPTION: BASED	ON LOCATION(S) WORKED AN	D PHASE CODE(S), PLEASE D	ESCRIBE W	/HAT WORK T	HE CREW PERI	FORMED															
The water was coming from the electrical room it affected the wall in the back towards the electrical room so we removed the baseboard and he wiped it down with microban and set up a dehumidifier and air mover The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of fthe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier	Arrived on sit	e & met with engineer. W	Ve did a walkthrough of the affected areas 5	5 units affected in total unit 502,503,515	,415 and gym	n area. Before start	ing work we got a v	vork authorization	signed. Updates for t	he units in 140	1												
5th floor electrical room The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of the ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier	Unit 514																						
The floor was all wet and trying into ice so we had to crush some of the ice and then we mopped up the whole floor 4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of fthe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier		•	rical room it affected the wall in the back to	wards the electrical room so we remov	ed the basebo	ard and he wiped i	t down with microba	an and set up a de	ehumidifier and air mo	ver													
4th floor exercise room We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of fthe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier																							
We wiped down the water puddles and what was effected on the ceiling of the door entrance and then we set up a dehumidifier and a air mover to dry of fthe ceiling Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier																							
Unit 415 We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier																							
We entered to check what was effected by the water and the only effected area was in the mbr behind the bed so we removed the baseboard and wiped it down and dried it up with some rags and then we set up a dehumidifier		,	•		_	,	J																
FORM VERIFIER-PLEASE CHECK BOX AND ENTER QUANTITY FOR A E& PAGES I CLUDED WITH THIS SHEET NONE OF PAGE # OF PAGE 5 RECIEPT TRACKING FORMS																							
	FORM VI	ERIFIER-PLEASE	CHECK BOX AND ENTER QU	JANTITY FOR A E& PA	GES I CL	UDED WITH	I THIS SHEET	-	NONE		OF PA	GE			# OF	PAGE 5			RECIEPT	TRACKING	FORMS		

PAGE 1