

**AMENDMENT NO. 1 DECEMBER 2006
TO
IS 14448 : 1997 CODE OF PRACTICE FOR
REINFORCEMENT OF ROCK SLOPES
WITH PLANE WEDGE FAILURE**

(Page 1, clause 3.5.2, heading and line 1) — Substitute 'Tendon' for 'Tandon'.

(Page 2, clause 4.1, line 5) — Substitute 'parameters affecting the slope stability' for 'slope parameters'.

(Page 2, clause 4.2.4, line 8) — Insert 'that is' after 'parallel'.

(Page 3, clause 6.1, line 3) — Substitute 'occurs' for 'occures'.

(Page 3, clause 6.3.6, line 7) — Substitute 'hydrofracturing' for 'hydrofacturing'.

(Page 4, clause 6.4, line 1) — Delete '(F. A. L.)'.

(Page 4, clause 6.4.2.3, line 2) — Substitute '6' for '5'.

(Page 4, clause 7.1, lines 2 and 3) — Delete 'that is' and insert 'It should be ensured that' after 'provided'.

(Page 4, clause 7.1, line 4) — Substitute 'vegetation' for 'vegitation'.

(Page 5, clause 8.1, line 1) — Substitute 'of' for 'or'.

(Page 5, clause 8.4, line 3) — Substitute 'obtained' for 'obtanied'.

(Page 5, clause 9.2.1.1, line 4) — Substitute ' θ ' for ' ϕ '.

[Page 6, Fig. 2(a)] — Substitute ' ψ_p ' for ' ψ_b '.

(CED 48)