

AMENDMENT NO. 5 FEBRUARY 2023
TO
IS 14664 : 2010 AUTOMOTIVE VEHICLES — PERFORMANCE REQUIREMENTS
AND TESTING PROCEDURE FOR BRAKING SYSTEM OF TWO AND THREE
WHEELED MOTOR VEHICLES
(First Revision)

(Page 4, Clause 4.1.12) — Substitute the following for the existing clause:

‘4.1.12 Vehicles that are equipped with a split service brake system shall be fitted with a red warning lamp, which shall be activated:

- a) when there is a hydraulic failure on the application of a force of ≤ 90 N on the control; or
- b) without actuation of the brake control, when the brake fluid level in the master cylinder reservoir falls below the greater of:
 - 1) that which is specified by the manufacturer; and
 - 2) that which is less than or equal to half of the fluid reservoir capacity.

A red warning lamp fitted for conditions in a) or b) above shall be identified by tell-tale symbol as per B.01 or B.13 of Annex B of ISO 2575 : 2021.

To permit function checking, the warning lamp shall be illuminated by the activation of the ignition switch and shall be extinguished when the check has been completed. This condition is satisfied if the warning lamp switches off after few second. The warning lamp shall remain ‘ON’, while a failure condition exists whenever the ignition switch is in the ‘ON’ position.’

(TED 04)

Publication Unit, BIS, New Delhi, India