

**AMENDMENT NO. 1 MAY 2003
TO
IS 3521 : 1999 INDUSTRIAL SAFETY BELTS AND
HARNESSES — SPECIFICATION**

(Third Revision)

(Page 1, clause 2) — Substitute 'IS 3203 : 1982 Methods of testing local thickness of electroplated coating (*first revision*)' for 'IS 4171 : 1983 Copper rods and bars for general engineering purposes (*first revision*)'.

(Page 1, clauses 3.3 and 3.4) — Delete and renumber the subsequent clauses.

(Page 3, clause 5.2.5, line 9) — Substitute 'plating or powder' for 'plating, powder'.

(Page 3, clause 5.2.5, line 12) — Substitute 'IS 3203' for 'IS 4171'.

(Page 8, clause B-2, Title) — Substitute the following for the existing:

'B-2 TESTS FOR CLASS D, CLASS E AND CLASS L'

(Page 8, clause B-2.1, line 1) — Substitute 'belts or harnesses' for 'belts harnesses'.

(Page 8, Table 2) — Substitute the existing table with the following:

Table 2 Free Fall Distance
(Clauses B-2.1 and D-4)

Sl No.	Class	Distance in m, Max
(1)	(2)	(3)
i)	D	1.8
ii)	E	0.6
iii)	L	0.6

(Page 9, clause B-3, Title) — Substitute 'CLASS P' for 'TYPE 4 LINEMAN POLES SAFETY BELT'.

Amend No. 1 to IS 3521 : 1999

(*Page 9, clause B-3.1*) — Substitute the following for the existing:

'B-3.1 Attach the safety belt or harness to the dummy as it would be worn by the worker. Secure the work positioning attachment element with a properly affixed rigid anchorage. Raise the dummy in an upright position until the axis of the work positioning attachment round the dummy and anchorage point are horizontal. Hold the dummy in poision by a quick release device. After the release when the dummy has come to rest examine for any slippage, damage or other deterioration.'