

Aeration Blower B-201 Maintenance Procedure

Normal vibration limit: 5.0 mm/s RMS. Check inlet filter differential pressure.

After filter service, verify even gasket seating and secure guard hardware.

Investigate tonal vibration with rising inlet differential pressure before VSD changes.

Maintain discharge air temperature below 115 C and record restart readings.