SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Cupboard turn-button latch

Family: latch

BEST EFFORT

Max error: 4.32 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.948, Hausdorff 2.28 mm, mean 0.35 mm
side: IoU 0.969, Hausdorff 0.71 mm, mean 0.07 mm
Part tests: 12/14 passed
- top: refined in the photo frame by +0.29 deg, (+0.01, -0.07) mm on the mat
- side: refined in the photo frame by -0.08 deg, (-0.00, +0.01) mm on the mat
- top view (photo frame): IoU 0.948 (not gated), mean contour distance 0.35 mm (needs <= 0.15 mm), Hausd

Key dimensions

Length: 47.12 mm ± 0.28 [measured]
Width: 17.11 mm ± 0.27 [measured]
Thickness: 5.00 mm ± 0.30 [user stated]
hole_1 Ø: 10.43 mm ± 0.01 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Y: -Y side on the bed

Repair passport

SGDK5X

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/SGDK5X

Or type the id on the PartSmith site at /p/<id>. No new photos needed.