SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

L-bracket replacement

Family: bracket

BEST EFFORT

Max error: 0.43 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.987, Hausdorff 0.43 mm, mean 0.09 mm
side: IoU 0.983, Hausdorff 0.30 mm, mean 0.04 mm
Part tests: 16/17 passed
- top: refined in the photo frame by +0.17 deg, (-0.15, -0.26) mm on the mat
- side: refined in the photo frame by +0.02 deg, (+1.07, +0.39) mm on the mat
- top view (photo frame): IoU 0.987 (needs >= 0.97), Hausdorff 0.43 mm (needs <= 0.5 mm)

Key dimensions

Length: 46.37 mm ± 0.09 [measured]
Width: 30.53 mm ± 0.09 [measured]
Thickness: 2.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.59 mm ± 0.05 [measured]
hole_2 Ø: 3.60 mm ± 0.04 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

2878N6

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/2878N6

Or type the id on the PartSmith site at /p/<id>. No new photos needed.