SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Hinge leaf

Family: hinge

BEST EFFORT

Max error: 3.68 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.920, Hausdorff 3.43 mm, mean 0.57 mm
side: IoU 0.748, Hausdorff 3.68 mm, mean 0.84 mm
Part tests: 23/24 passed
- top: refined in the photo frame by +0.09 deg, (-0.03, -0.09) mm on the mat
- side: refined in the photo frame by +0.14 deg, (+0.01, +0.11) mm on the mat
- top view (photo frame): IoU 0.920 (needs >= 0.97), Hausdorff 3.43 mm (needs <= 0.5 mm) (worst at x=27.6,

Key dimensions

Length: 58.54 mm ± 0.13 [measured]
Width: 29.67 mm ± 0.12 [measured]
Thickness: 2.50 mm ± 0.30 [user stated]
hole_1 Ø: 4.23 mm ± 0.01 [measured]
hole_2 Ø: 4.25 mm ± 0.01 [measured]
hole_3 Ø: 4.27 mm ± 0.02 [measured]
hole_4 Ø: 4.23 mm ± 0.02 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: +X: +X end on the bed

Repair passport

HVK89T

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/HVK89T

Or type the id on the PartSmith site at /p/<id>. No new photos needed.