

Incident Report: Pump P-204 Gasket Swap Failure

Incident ID: INC-2025-894. Date: 2025-06-22. Plant Area: Unit 3 Distillation.

Description: Pump P-204 experienced minor fluid blowout from casing during restart.

Root Cause Analysis (RCA): The blowout occurred due to operator error and procedural violation. The torque sequence for the gasket casing bolts was not followed properly.

Corrective Actions: Gasket replaced, bolts retorqued using standard star-pattern torque sequence.